



report date: 2024-03-28

General information

Make	MINI
Model	COOPER D
Colour	Black
Year of manufacture	2010
Top speed	121 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	112 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Diesel
Consumption city	62.8 mpg
Consumption extra urban	76.4 mpg
Consumption combined	70.6 mpg
CO2 emission	105 g/km
CO2 label	B







Internet history

Entry 2


Date	2022-01-24
Pictures	32
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2022-01-22
Pictures	32
Listing price	View report



source: autotrader.co.uk



MOT history

MOT expiry date	2025-01-30
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	27
Total items failed	6

MOT #17 2024-01-31 10:24

MOT test number 975624627916

Result ✓ Passed

Next expiry date 2025-01-30

Advice Offside Rear Inner Brake pad(s) wearing thin Look to be right on, or possibly below limit, can't tell 100% difficult to see, NEEDS Investigating (1.1.13 (a) (ii))

MOT #16 2024-01-29 15:47

MOT test number 252814727819

Result ✗ Failed

DANGEROUS Offside Front Inner Tyre has ply or cords exposed (5.2.3 (d) (ii))

MAJOR Rear Registration plate inscription illegible Excessively Deteriorated (0.1 (b))

Advice Offside Rear Inner Brake pad(s) wearing thin Look to be right on, or possibly below limit, can't tell 100% difficult to see, NEEDS Investigating (1.1.13 (a) (ii))

MAJOR Rear Registration plate does not conform to the specified requirements Excessively Deteriorated (0.1 (d))

MOT #15 2023-01-30 15:26

MOT test number 691599287547

Result ✓ Passed

Advice Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Rear number plate starting to delemenate

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

**MOT #14** 2023-01-23 12:40**MOT test number** 317511682183**Result** ✗ Failed**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**Advice** Rear number plate starting to delemenate**DANGEROUS** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (ii))**MOT #13** 2022-01-26 08:32**MOT test number** 809406495485**Result** ✓ Passed**MOT #12** 2021-05-15 09:16**MOT test number** 399926184755**Result** ✓ Passed**MOT #11** 2020-05-20 12:47**MOT test number** 229357955067**Result** ✓ Passed**Advice** Nearside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))**MOT #10** 2019-04-08 07:43**MOT test number** 956274673100**Result** ✓ Passed

**MOT #9** 2019-04-02 11:35**MOT test number** 102940683942**Result** ✗ Failed**DANGEROUS** Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #8** 2018-04-03 09:15**MOT test number** 270759411981**Result** ✓ Passed**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Advice** Offside Rear Tyre worn close to the legal limit and slightly out of shape (4.1.E.1)**MOT #7** 2018-03-29 14:28**MOT test number** 962610808268**Result** ✗ Failed**Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)**Fail** Nearside Front Tyre has a bulge, caused by separation or partial failure of its structure (4.1.D.1b)**Advice** Offside Rear Tyre worn close to the legal limit and slightly out of shape (4.1.E.1)**MOT #6** 2017-01-25 13:05**MOT test number** 616343232611**Result** ✓ Passed

**MOT #5** 2017-01-25 10:06**MOT test number** 138506184208**Result** ✗ Failed**Fail** Nearside Windscreen wiper does not clear the windscreen effectively (8.2.2)**Pass with rectification** Windscreen washer provides insufficient washer liquid (8.2.3)**Fail** Tyre pressure monitoring system warning lamp indicates a fault (4.1.D.4)**Fail** Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)**MOT #4** 2016-01-12 13:14**MOT test number** 971429000125**Result** ✓ Passed**Advice** Tyre pressure light on**Advice** Signs of wear to both front tyres on edges**MOT #3** 2015-02-06 15:03**MOT test number** 675987235039**Result** ✓ Passed**MOT #2** 2014-12-24 11:47**MOT test number** 447668854437**Result** ✓ Passed**Notice** Damage wheel rims.**Notice** Stone chips front windscreen.



MOT #1 2013-12-05 11:32

MOT test number 147849433391

Result ✓ Passed

- Notice** Front wipers are starting to smear + blades are starting to split
- Advice** Nearside Front Road wheel with a slightly distorted bead rim (4.2.A.1a)
- Notice** Engine oil level is low
- Advice** Nearside Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)



Tax & MOT check

<div><div>✓</div><div>Taxed</div><div>Tax due: 1 January 2025</div></div>		<div><div>✓</div><div>MOT</div><div>Expires: 30 January 2025</div></div>	
Tax status			Valid until 1 January
Days left			247
MOT expiry date			30 January 2025
Full MOT history			See MOT history

Tax calculation

Vehicle class	49
Band	B
Single payment (12 months)	£ 20,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 21,00,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2019-09-29
Current registration	
Plate since	2019-09-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2010-12-30
Last registration	2024-01-31
Complete history	See info



Registration #1	2010-12-30	14 mi
Registration #2	2013-12-05	21.264 mi
Registration #3	2014-12-24	25.944 mi
Registration #4	2015-02-06	25.967 mi
Registration #5	2016-01-12	34.863 mi
Registration #6	2017-01-25	52.211 mi
Registration #7	2017-01-25	52.211 mi
Registration #8	2018-03-29	61.204 mi
Registration #9	2018-04-03	61.241 mi
Registration #10	2019-04-02	66.675 mi
Registration #11	2019-05-20	71.277 mi
Registration #12	2019-05-20	71.277 mi
Registration #13	2019-05-20	71.277 mi
Registration #14	2019-05-20	71.277 mi
Registration #15	2019-05-20	71.277 mi
Registration #16	2019-05-20	71.277 mi
Registration #17	2019-05-20	71.277 mi
Registration #18	2019-05-20	71.277 mi
Registration #19	2019-05-20	71.277 mi
Registration #20	2019-05-20	71.277 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1414 mm
Length	3723 mm
Wheel base	2467 mm
Kerb weight	1200 kg
Max. allowed weight	1630 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Direct Injection
Number of doors	2
Number of seats	4

Number of axles	2
Engine number	71407541