



Mercedes-Benz




report date: 2024-03-29

General information

Make	MERCEDES
Model	E E320 CDI SPORT
Colour	Silver
Year of manufacture	2009
Top speed	155 mph
0 - 60 mph	6.8 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	221 BHP
Max. torque	510 Nm at 2.800 rpm
Engine capacity	2.987 cc
Cylinders	6
Fuel type	Diesel
Consumption city	26.7 mpg
Consumption extra urban	47.1 mpg
Consumption combined	37.2 mpg
CO2 emission	202 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-01-21
Pictures	19
Listing price	<a href="#">View report</a>



source: yesauto.com



MOT history

MOT expiry date	2024-12-13
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	33
Total items failed	7

MOT #14	2023-11-16 17:24
---------	------------------

MOT test number	837218909595
-----------------	--------------

Result	✓ Passed
--------	----------

Next expiry date	2024-12-13
------------------	------------

- Advice** Offside centre exhaust mounting broken exhaust still supported ok
- Advice** Offside Brake pipe corroded, covered in grease or other material Front to rear at back of vehicle (1.1.11 (c))
- Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Advice** Nearside Brake pipe corroded, covered in grease or other material Front to rear at back of vehicle (1.1.11 (c))
- Advice** Rear tyres wearing low on inner edges
- Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))

**MOT #13**

2023-11-15 17:44

**MOT test number**

366691489440

**Result****✗ Failed**

- Fail** Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Nearside Brake pipe corroded, covered in grease or other material Front to rear at back of vehicle (1.1.11 (c))
- Advice** Nearside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Fail** Offside Front Upper Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Rear tyres wearing low on inner edges
- Fail** Nearside Rear Coil spring fractured or broken (5.3.1 (b) (i))
- Advice** Offside Brake pipe corroded, covered in grease or other material Front to rear at back of vehicle (1.1.11 (c))
- Advice** Offside Rear Brake hose slightly deteriorated (1.1.12 (b) (ii))
- Fail** Nearside Front Lower Suspension arm ball joint excessively worn Back joint (5.3.4 (a) (i))
- Advice** Offside centre exhaust mounting broken exhaust still supported ok

**MOT #12**

2022-11-30 16:07

**MOT test number**

758847777817

**Result****✓ Passed**

- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside centre exhaust mounting broken but exhaust still supported ok
- Advice** Offside Rear Coil spring corroded (5.3.1 (b) (i))
- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside front upper suspension ball joint boot slightly deteriorated
- Advice** Nearside Rear Coil spring corroded (5.3.1 (b) (i))

**MOT #11**

2021-12-03 17:49

**MOT test number**

239115213373

**Result**

✓ Passed

**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**MOT #10**

2021-12-03 14:14

**MOT test number**

841091034538

**Result**

✗ Failed

**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Offside Rear Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Offside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Rear Tyre has ply or cords exposed (5.2.3 (d) (ii))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Fail** Nearside Rear Outer Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Front Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))**MOT #9**

2020-12-14 16:37

**MOT test number**

654510933930

**Result**

✓ Passed

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge worn on edge and close to limit (5.2.3 (e))**Advice** Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge also badly cracked (5.2.3 (e))**Advice** Nearside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c))**Advice** Offside Front Wheel bearing has slight play (5.1.3 (a) (i))

**MOT #8** 2019-03-27 13:56**MOT test number** 525268461764**Result** ✓ Passed**MOT #7** 2018-03-14 11:56**MOT test number** 640670986295**Result** ✓ Passed**MOT #6** 2017-05-15 14:01**MOT test number** 516374990583**Result** ✓ Passed**MOT #5** 2016-05-10 11:05**MOT test number** 696426951370**Result** ✓ Passed**MOT #4** 2015-05-15 13:41**MOT test number** 899585535102**Result** ✓ Passed**MOT #3** 2014-05-06 11:09**MOT test number** 588096024136**Result** ✓ Passed**Notice** Play in steering rack inner joint(s)**MOT #2** 2013-04-25 14:23**MOT test number** 459445713170**Result** ✓ Passed**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)



MOT #1	2012-05-19 12:35
MOT test number	697780442195
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
  
Tax due:  
1 July 2024

✓  
**MOT**  
  
Expires:  
13 December 2024

Tax status	Valid until 1 July
Days left	62
MOT expiry date	13 December 2024
Full MOT history	<a href="#">See MOT history</a>

Tax calculation

Vehicle class	49
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-





Damage history


Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 *****
Plate since	2024-03-29
Current registration	 *****
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.


Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-01-30
Last registration	2023-11-16
Complete history	<a href="#">See info</a>



Registration #1	2009-01-30	18 mi
Registration #2	2012-05-19	50.437 mi
Registration #3	2013-04-25	65.246 mi
Registration #4	2014-05-06	82.494 mi
Registration #5	2015-05-15	100.139 mi
Registration #6	2016-05-10	115.462 mi
Registration #7	2017-05-15	128.838 mi
Registration #8	2018-03-14	140.049 mi
Registration #9	2019-05-20	151.257 mi
Registration #10	2020-05-20	162.465 mi
Registration #11	2021-05-20	173.673 mi
Registration #12	2022-05-20	184.881 mi
Registration #13	2023-05-20	196.089 mi
Registration #14	2024-05-20	207.297 mi
Registration #15	2025-05-20	218.505 mi
Registration #16	2026-05-20	229.713 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1990 mm
Height	1450 mm
Length	4818 mm
Wheel base	2833 mm
Kerb weight	1740 kg

Additional information

Fuel tank capacity	80 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	64292040655687