



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	GETZ GSI
Colour	Black
Year of manufacture	2008
Top speed	104 mph
Gearbox	4 speed automatic

Engine & fuel consumption

Power	96 BHP
Max. torque	126 Nm at 3.200 rpm
Engine capacity	1.399 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.0 mpg
Consumption extra urban	53.3 mpg
Consumption combined	42.2 mpg
CO2 emission	159 g/km
CO2 label	G







Internet history

Entry 3

Date 2023-12-13

Pictures 8



source: g3remarketing.co.uk

Entry 2

Date 2021-09-12

Pictures 25

Listing price [View report](#)



source: cargurus.co.uk

Entry 1

Date 2021-09-11

Pictures 25

Listing price [View report](#)



source: autotrader.co.uk



## MOT history

MOT expiry date	2024-06-20
MOT pass rate	68 %
MOT passed	13
Failed MOT tests	6
Total advice items	25
Total items failed	20

MOT #19	2023-06-21 10:24
MOT test number	198006380641
Result	✓ Passed
Next expiry date	2024-06-20
Advice	Offside Front Inner plastic cover missing

MOT #18	2023-05-31 16:00
MOT test number	427195007988
Result	✗ Failed
Fail	Nearside Front Headlamp aim too high (4.1.2 (a))
Fail	Offside Rear Parking (secondary brake) on a single line braking system has inadequate effort at a wheel (1.3.1 (a) (i))
Fail	Offside Front Headlamp aim too high (4.1.2 (a))
Fail	Nearside Rear Parking (secondary brake) on a single line braking system has inadequate effort at a wheel (1.3.1 (a) (i))
Fail	Offside Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))
Fail	Offside Front Headlamp insecure (4.1.1 (c))
Fail	Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))

MOT #17	2022-05-16 16:27
MOT test number	661028742523
Result	✓ Passed

**MOT #16** 2022-05-16 16:27**MOT test number** 288227648410**Result** ✗ Failed**Pass with rectification** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #15** 2021-05-15 11:30**MOT test number** 148876056830**Result** ✓ Passed**MOT #14** 2020-07-13 12:49**MOT test number** 824956802390**Result** ✓ Passed**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**MOT #13** 2020-07-11 11:37**MOT test number** 969341625137**Result** ✗ Failed**Advice** Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii))**Advice** Offside Front Lower Suspension arm ball joint has slight play (5.3.4 (a) (i))**Advice** Nearside Front Outer Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Rear fog lamp tell-tale not working (4.9.1 (a) (ii))**Fail** Nearside Front Inner Brake pad(s) worn down to wear indicator (1.1.13 (a) (i))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Fail** Offside Rear fog lamp not working (4.5.1 (a) (ii))

**MOT #12**

2019-03-28 13:31

**MOT test number**

342494886486

**Result**

✓ Passed

- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Offside Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Nearside Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**MOT #11**

2019-03-27 12:32

**MOT test number**

809987313194

**Result**

✗ Failed

- Fail** Offside Front Upper Macpherson strut mounting damaged and seriously weakened (5.3.3 (b) (i))
- Fail** Rear fog lamp tell-tale not working (4.9.1 (a) (ii))
- Fail** Nearside Front Upper Macpherson strut pin or bush excessively worn top mount (5.3.4 (a) (i))
- Advice** Nearside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Offside Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Central Rear fog lamp not working (4.5.1 (a) (ii))
- Fail** Offside Front Upper Macpherson strut pin or bush excessively worn top mount (5.3.4 (a) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
- Advice** Nearside Rear Sub-frame pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))
- Fail** Nearside Front Lower Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**MOT #10** 2018-04-16 15:05**MOT test number** 494467490687**Result** ✓ Passed**Advice** Child Seat fitted not allowing full inspection of adult belt**MOT #9** 2018-04-10 14:40**MOT test number** 990222720195**Result** ✗ Failed**Advice** Child Seat fitted not allowing full inspection of adult belt**Fail** Offside Stop lamp not working (1.2.1b)**Fail** Nearside Front wheel bearing rough when rotated (2.5.A.2)**MOT #8** 2017-04-14 11:52**MOT test number** 693409964561**Result** ✓ Passed**Advice** Nearside Front Wiper blade starting to split**Advice** Offside Rear Child Seat fitted not allowing full inspection of adult belt**MOT #7** 2016-04-19 11:11**MOT test number** 178648511496**Result** ✓ Passed**MOT #6** 2015-06-22 09:09**MOT test number** 698073675151**Result** ✓ Passed**MOT #5** 2014-06-04 09:46**MOT test number** 298065354442**Result** ✓ Passed

**MOT #4** 2013-06-11 09:58**MOT test number** 959922663195**Result** ✓ Passed

**Advice** Nearside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**Advice** Offside Front Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

**MOT #3** 2012-06-14 14:32**MOT test number** 697926362125**Result** ✓ Passed

**Advice** Nearside Inner Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

**MOT #2** 2012-06-14 14:32**MOT test number** 225096562168**Result** ✗ Failed

**Pass with rectification** Offside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

**Advice** Nearside Inner Front Road wheel with a slightly distorted bead rim (4.2.A.1a)

**MOT #1** 2011-06-01 15:22**MOT test number** 809822751185**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 July 2024

✓  
**MOT**  
**Expires:**  
20 June 2024

<b>Tax status</b>	Valid until 1 July
<b>Days left</b>	62
<b>MOT expiry date</b>	20 June 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	G
<b>Single payment (12 months)</b>	£ 240,00,-
<b>Single six month payment</b>	£ 132,00,-
<b>Total payable by 12 monthly instalments</b>	£ 252,00,-





Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	EN08DKE
Plate since	2019-03-29
Current registration	EN08DKE
Plate since	2019-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2008-06-25
Last registration	2023-06-21
Complete history	<a href="#">See info</a>



Registration #1	2008-06-25	13 mi
Registration #2	2011-06-01	9.443 mi
Registration #3	2012-06-14	12.075 mi
Registration #4	2013-06-11	14.870 mi
Registration #5	2014-06-04	17.472 mi
Registration #6	2015-06-22	25.941 mi
Registration #7	2016-04-19	27.946 mi
Registration #8	2017-04-14	31.753 mi
Registration #9	2018-04-10	36.918 mi
Registration #10	2018-04-16	36.983 mi
Registration #11	2019-03-27	41.672 mi
Registration #12	2019-03-27	41.672 mi
Registration #13	2019-03-27	41.672 mi
Registration #14	2019-03-27	41.672 mi
Registration #15	2019-03-27	41.672 mi
Registration #16	2019-03-27	41.672 mi
Registration #17	2019-03-27	41.672 mi
Registration #18	2019-03-27	41.672 mi
Registration #19	2019-03-27	41.672 mi
Registration #20	2019-03-27	41.672 mi
Registration #21	2019-03-27	41.672 mi

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1665 mm
Height	1490 mm
Length	3825 mm
Wheel base	2455 mm
Kerb weight	1055 kg
Max. allowed weight	1540 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	G4EE8974622