





report date: 2022-08-09

General information

Make	MASERATI
Model	GRAN TURISMO V8 AUTO V8
Colour	Grey
Year of manufacture	2008
Top speed	177 mph
Gearbox	6 speed automatic

Engine & fuel consumption

Power	400 BHP
Max. torque	460 Nm at 4.750 rpm
Engine capacity	4.244 cc
Cylinders	8
Fuel type	Petrol
Consumption city	13.1 mpg
Consumption extra urban	28.2 mpg
Consumption combined	19.2 mpg
CO2 emission	330 g/km
CO2 label	М



CarCheck.co.uk page 1/12



Internet history

Entry 2


Date 2022-01-11

Pictures 7

Listing price <u>View report</u>











source: autotrader.co.uk


Entry 1

Date	2021-06-13
Pictures	7

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



B 4	\sim $-$			
10.71	α	- h	sto	rv
101	() I		510	II V
	•			. ,

MOT expiry date	2024-02-19
MOT pass rate	93 %
MOT passed	13
Failed MOT tests	1
Total advice items	18
Total items failed	0

MOT #14	2023-02-20 11:25
MOT test number	859224018397
Result	✓ Passed
Next expiry date	2024-02-19

MOT #13	2022-02-03 13:44
MOT test number	661487500863
Result	✓ Passed

MOT #12	2020-12-18 15:15
MOT test number	897031658070
Result	✓ Passed

MOT #11		2019-12-17 13:37
MOT test	number	724336909043
Result		✓ Passed
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front and rear brake discs worn	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Front and rear inner brake pads worn difficult to see clearly	
Advice	Coil spring corroded all 4 (5.3.1 (b) (i))	

CarCheck.co.uk page 3/12



✓ Passed

MOT #10 2019-12-13 09:37

MOT test number 319252951861

Result X Failed

DANGEROUS Offside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front and rear brake discs worn

Advice Coil spring corroded all 4 (5.3.1 (b) (i))

DANGEROUS Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front and rear inner brake pads worn difficult to see clearly

MOT #9 2018-12-11 14:19

MOT test number 900161228535

Result
✓ Passed

Advice Front brake pads worn

Result

Advice Coil spring corroded all 4 (5.3.1 (b) (i))

MOT #8 2017-12-19 11:20

MOT test number 542536510331

Result ✓ Passed

MOT #7 2017-05-31 09:39

MOT test number 840291043520

Result
✓ Passed

MOT #6 2016-06-17 10:53

MOT test number 269986862059

CarCheck.co.uk page 4/12



MOT test number

Result

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Notice Offside front wiper blade splitting at the ends but serviceable

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #4	2014-04-30 10:17
MOT test number	477300524125
Result	✓ Passed
MOT #3	2013-05-25 12:59
MOT test number	835165243180
Result	✓ Passed
Notice Offside rear tyre cut in outer side wall bead	

MOT #2	2012-05-29 17:04
MOT test number	677160152177
Result	✓ Passed
MOT #1	2011-06-06 11:51
MOT test number	236137251442
Result	✓ Passed

CarCheck.co.uk page 5/12





Tax & MOT check



Expired: 19 February 2024 X MOT

Tax expired: 1 January 2023

Tax status

Days left

MOT expiry date

Full MOT history

Expired at 1 January 2023

481 days too late
19 February 2024

See MOT history

Tax calculation

Vehicle class	48
Band	M
Single payment (12 months)	£ 695,00,-
Single six month payment	£ 382,25,-
Total payable by 12 monthly instalments	£ 729,75,-

CarCheck.co.uk page 6/12




Damage history

Check the damage history for this MASERATI. See if, where and when this MASERATI had damage and the car repair costs. We also check if this MASERATI was scrapped. Download the premium report here for the results.

Damage 1

Date	
Category	
Туре	
Damage 2	
Date	



Extra MASERATI salvage check



Category

Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this MASERATI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



More info >

Owner history

For how long did the current and previous owner(s) have this MASERATI? How many own MASERATI have? Check it in the premium report and see all owner registrations. Downlo here.	

	More info >
Plate changes	
See in this check if this MASERATI had different number plates.	
Number of plates	,
Current registration	NK SIN
Plate since	
Current registration	AIR AIR
Plate since	

CarCheck.co.uk page 9/12



Finance check

Check if this MASERATI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MASERATI has been settled.

If not, and you buy this MASERATI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MASERATI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info

More info >

CarCheck.co.uk page 10/12



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-07-04
Last registration	2023-02-20
Complete history	See info



Registration #1	2008-07-04	17 mi
Registration #2	2011-06-06	15.575 mi
Registration #3	2012-05-29	17.733 mi
Registration #4	2013-05-25	20.173 mi
Registration #5	2014-04-30	21.516 mi
Registration #6	2015-06-16	28.666 mi
Registration #7	2016-06-17	32.460 mi
Registration #8	2017-05-31	34.991 mi
Registration #9	2017-12-19	36.241 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		91.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		0.00 44
Registration #17		D.777 es

More info >

CarCheck.co.uk page 11/12



			_		
- 11	manc	Innc	λ.	$M \cap M$	aht
וט	mens	כווטו	CX.	$vv \subset v$	ullu

Width	1915 mm
Height	1353 mm
Length	4881 mm
Wheel base	2942 mm
Kerb weight	1880 kg

Additional information

Fuel tank capacity	86 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	135500

CarCheck.co.uk page 12/12