



report date: 2024-03-29

General information

Make	FORD
Model	FOCUS ST-3
Colour	Black
Year of manufacture	2009
Top speed	150 mph
0 - 60 mph	6.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	223 BHP
Max. torque	320 Nm at 4.000 rpm
Engine capacity	2.521 cc
Cylinders	5
Fuel type	Petrol
Consumption city	20.5 mpg
Consumption extra urban	41.5 mpg
Consumption combined	30.4 mpg
CO2 emission	224 g/km
CO2 label	K





Internet history

Entry 1

Date	2021-06-04
Pictures	7
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-26
MOT pass rate	71 %
MOT passed	12
Failed MOT tests	5
Total advice items	22
Total items failed	15

MOT #172023-07-13 15:52

MOT test number897528960512

Result✓ Passed

Next expiry date2024-07-26

Advice Front Service brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bushes both sides (5.3.4 (a) (i))

Advice Rear subframe and all suspension arms corroded

Advice Nearside Front Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))

Advice Rear Anti-roll bar linkage ball joint has slight play both rear drop links (5.3.4 (a) (i))

**MOT #16**

2023-07-11 11:33

MOT test number

184341728792

Result

✗ Failed

- Advice** Nearside Front Inner Tyre worn close to legal limit/worn on edge edge (5.2.3 (e))
- Advice** Rear Anti-roll bar linkage ball joint has slight play both rear drop links (5.3.4 (a) (i))
- Advice** Offside Front headlamp leveling device slightly loose
- Fail** Offside Rear Upper Shock absorbers likely to become detached (5.3.2 (a) (ii))
- Fail** Front Headlamp aim too high both fronts too high (4.1.2 (a))
- Fail** Offside Outer Integral body structure corroded to the extent that the rigidity of the assembly is significantly reduced sill holed (6.1.1 (c) (i))
- Advice** Rear subframe and all suspension arms corroded
- Advice** Rear Suspension arm pin or bush worn but not resulting in excessive movement trailing arm bushes both sides (5.3.4 (a) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Fail** Rear Headlamp levelling device inoperative disconnected from arm (4.1.5 (a))
- Advice** Front Service brake imbalance requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))

MOT #15

2022-07-15 13:12

MOT test number

717306823788

Result

✓ Passed

- Advice** Rear Anti-roll bar linkage ball joint has slight play both rear drop links (5.3.4 (a) (i))
- Advice** Rear subframe and suspension arms suffering from corrosion

MOT #14

2021-07-27 09:43

MOT test number

716286798479

Result

✓ Passed



MOT #13	2020-07-25 07:47
MOT test number	328138251922
Result	✓ Passed
Advice	Rear Exhaust has a minor leak of exhaust gases backbox (6.1.2 (a))
Advice	Offside Front Play in steering rack inner joint(s)

MOT #12	2020-07-22 10:29
MOT test number	491244228464
Result	✗ Failed
Fail	Offside Front Suspension arm pin or bush excessively worn rear bush on arm (5.3.4 (a) (i))
Advice	Offside Front Play in steering rack inner joint(s)
Fail	Offside Front Position lamp not working sidelight flashing (4.2.1 (a) (ii))
Fail	Nearside Front Suspension arm pin or bush excessively worn rear bush on arm (5.3.4 (a) (i))
Minor	Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
Advice	Rear Exhaust has a minor leak of exhaust gases backbox (6.1.2 (a))

MOT #11	2019-07-19 11:15
MOT test number	823996539189
Result	✓ Passed
Advice	Offside Tyre worn close to legal limit/worn on edge and nearside rear tyres 2mm (225/40/18) (5.2.3 (e))
Advice	Child Seat fitted not allowing full inspection of adult belt

MOT #10	2018-07-24 13:54
MOT test number	102582532262
Result	✓ Passed

**MOT #9** 2018-07-24 09:00**MOT test number** 570641131840**Result** ✗ Failed**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #8** 2017-10-11 09:09**MOT test number** 856969033252**Result** ✓ Passed**MOT #7** 2017-10-11 09:09**MOT test number** 873402373504**Result** ✗ Failed**Pass with rectification** Front Front position lamp(s) not working both sidelights inop. (1.1.A.3b)**MOT #6** 2016-10-07 09:41**MOT test number** 169143244301**Result** ✓ Passed**MOT #5** 2016-10-07 09:41**MOT test number** 994233069616**Result** ✗ Failed**Pass with rectification** Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Pass with rectification** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)**Pass with rectification** Nearside Rear Registration plate lamp not working (1.1.C.1d)**Pass with rectification** Offside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)**Pass with rectification** Front Windscreen washer provides insufficient washer liquid (8.2.3)**Pass with rectification** Offside Rear Direction indicator incorrect colour (1.4.A.2f)



MOT #4	2015-10-01 14:58
MOT test number	676621437064
Result	✓ Passed
MOT #3	2014-10-09 10:48
MOT test number	286962484278
Result	✓ Passed
MOT #2	2013-10-10 13:24
MOT test number	717673583298
Result	✓ Passed
MOT #1	2012-10-11 15:43
MOT test number	549505582272
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 March 2025

✓
MOT
Expires:
26 July 2024

Tax status	Valid until 1 March
Days left	305
MOT expiry date	26 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	EA59ASV
Plate since	2019-03-29
Current registration	EA59ASV
Plate since	2019-03-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-10-16
Last registration	2023-07-13
Complete history	See info



Registration #1	2009-10-16	8 mi
Registration #2	2012-10-11	21.433 mi
Registration #3	2013-10-10	26.884 mi
Registration #4	2014-10-09	32.279 mi
Registration #5	2015-10-01	37.959 mi
Registration #6	2016-10-07	44.182 mi
Registration #7	2016-10-07	44.182 mi
Registration #8	2017-10-11	49.094 mi
Registration #9	2017-10-11	49.094 mi
Registration #10	2018-07-24	50.626 mi
Registration #11	2019-05-29	51.377 mi
Registration #12	2019-05-29	51.377 mi
Registration #13	2019-05-29	51.377 mi
Registration #14	2019-05-29	51.377 mi
Registration #15	2019-05-29	51.377 mi
Registration #16	2019-05-29	51.377 mi
Registration #17	2019-05-29	51.377 mi
Registration #18	2019-05-29	51.377 mi
Registration #19	2019-05-29	51.377 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1839 mm
Height	1497 mm
Length	4357 mm
Wheel base	2640 mm
Kerb weight	1392 kg
Max. allowed weight	1860 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	9A35999