



report date: 2024-03-29

General information

| | |
|---------------------|----------------|
| Make | VOLKSWAGEN |
| Model | FOX URBAN FOX |
| Colour | Grey |
| Year of manufacture | - |
| Top speed | 92 mph |
| 0 - 60 mph | 17.5 seconds |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| | |
|-------------------------|---------------------|
| Power | 55 BHP |
| Max. torque | 108 Nm at 3.000 rpm |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 36.2 mpg |
| Consumption extra urban | 55.4 mpg |
| Consumption combined | 46.3 mpg |



LABEL UNKNOWN

**MOT history**

| | |
|-------------------------|--|
| MOT #13 | 2020-11-05 17:11 |
| MOT test number | 112287611764 |
| Result | ✓ Passed |
| Next expiry date | 2021-11-04 |
| Advice | Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii)) |
| Advice | Power steering pipes corroded |
| Advice | Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e)) |
| Advice | Offside Front Play in steering rack inner joint(s) |
| Advice | Rear exhaust box corroded |

| | |
|------------------------|--|
| MOT #12 | 2020-11-04 10:33 |
| MOT test number | 123845277364 |
| Result | ✗ Failed |
| Advice | Offside Front Play in steering rack inner joint(s) |
| Fail | Offside Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii)) |
| Fail | Front Windscreen wiper does not clear the windscreen effectively both (3.4 (b) (ii)) |
| Advice | Power steering pipes corroded |
| Advice | Front Tyre worn close to legal limit/worn on edge both (5.2.3 (e)) |
| Fail | Exhaust emissions likely to be affected by an exhaust leak (8.2.1.1 (b)) |
| Fail | Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b)) |
| Fail | Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii)) |
| Fail | Emissions not tested (8.2.1.2 (d)) |
| Advice | Rear exhaust box corroded |
| Advice | Rear Tyre slightly damaged/cracking or perishing both (5.2.3 (d) (ii)) |
| Fail | Rear fog lamp does not emit a steady red light (4.5.4 (a)) |

**MOT #11** 2019-09-17 14:07**MOT test number** 619650662340**Result** ✓ Passed**Advice** Rear exhaust back box corroded**MOT #10** 2019-09-17 12:22**MOT test number** 741859091392**Result** ✗ Failed**Fail** Offside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**Advice** Rear exhaust back box corroded**Fail** Nearside Front Anti-roll bar ball joint dust cover no longer prevents the ingress of dirt (5.3.4 (b) (ii))**MOT #9** 2018-08-29 13:51**MOT test number** 632854368180**Result** ✓ Passed**MOT #8** 2018-08-29 13:51**MOT test number** 393661816218**Result** ✗ Failed**Pass with rectification** Headlamp aim too low Both (4.1.2 (a))**MOT #7** 2017-09-08 13:57**MOT test number** 126706103671**Result** ✓ Passed**Advice** Undertrays fitted**Advice** Oil leak

**MOT #6**

2017-09-06 09:06

MOT test number

740446723180

Result

✗ Failed

Fail Nearside Front Shock absorber has a serious fluid leak (2.7.3)**Fail** Front Exhaust has a major leak of exhaust gases Flexi pipe (7.1.2)**Advice** Undertrays fitted**Fail** Offside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)**Advice** Oil leak**MOT #5**

2016-08-26 09:03

MOT test number

435085340134

Result

✓ Passed

Advice Oil leak**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**MOT #4**

2015-08-25 09:05

MOT test number

796104240003

Result

✓ Passed

MOT #3

2014-09-02 13:30

MOT test number

659975344280

Result

✓ Passed

Notice Nearside rear tyre cracking**Notice** Nail in offside rear tyre**Notice** Offside rear tyre cracking



| | |
|-----------------|------------------|
| MOT #2 | 2013-08-30 09:21 |
| MOT test number | 288232343201 |
| Result | ✓ Passed |
| MOT #1 | 2012-09-04 11:38 |
| MOT test number | 395888942299 |
| Result | ✓ Passed |



Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

| | |
|----------|--|
| Date | |
| Category | |
| Type | |

Damage 2

| | |
|----------|--|
| Date | |
| Category | |
| Type | |



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

| | |
|-----------------------------|----------|
| Trade retail value | £ 19,999 |
| Auction value | £ 19,999 |
| Average private trade value | £ 19,999 |

More info >



Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many owners did this VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

| | |
|-------|--------------|
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |
| Owner | Registration |

More info >

Plate changes

See in this check if this VOLKSWAGEN had different number plates.

| | |
|----------------------|--|
| Number of plates | 1 |
| Current registration |  SK59YJT |
| Plate since | 2024-03-29 |
| Current registration |  SK59YJT |
| Plate since | 2024-03-29 |

More info >



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLKSWAGEN is financed.

| | | |
|-------------------|----------|----------|
| Finance company | REDACTED | REDACTED |
| Date of agreement | REDACTED | REDACTED |
| Agreement type | REDACTED | REDACTED |
| Agreement term | REDACTED | REDACTED |
| Agreement number | REDACTED | REDACTED |
| Contact info | REDACTED | REDACTED |

More info >



Mileage check

| | |
|----------------------------|--------------------------|
| Odometer | In miles |
| Mileage registrations | 14 |
| First mileage registration | 2009-09-03 |
| Last registration | 2020-11-05 |
| Complete history | See info |



| | | |
|------------------|------------|-----------|
| Registration #1 | 2009-09-03 | 10 mi |
| Registration #2 | 2012-09-04 | 20.113 mi |
| Registration #3 | 2013-08-30 | 26.309 mi |
| Registration #4 | 2014-09-02 | 32.357 mi |
| Registration #5 | 2015-08-25 | 39.617 mi |
| Registration #6 | 2016-08-26 | 45.328 mi |
| Registration #7 | 2017-09-06 | 50.606 mi |
| Registration #8 | 2018-09-06 | 55.884 mi |
| Registration #9 | 2019-09-06 | 61.162 mi |
| Registration #10 | 2020-09-06 | 66.440 mi |
| Registration #11 | 2021-09-06 | 71.718 mi |
| Registration #12 | 2022-09-06 | 76.996 mi |
| Registration #13 | 2023-09-06 | 82.274 mi |
| Registration #14 | 2024-09-06 | 87.552 mi |

More info >



Car features

The VOLKSWAGEN factory car options list is only available in the premium report.

| | |
|-------|------------------|
| S0225 | Air conditioning |
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| S0567 | |
| S0569 | |

View the complete VOLKSWAGEN factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

| | |
|---------------------|---------|
| Width | 1660 mm |
| Height | 1544 mm |
| Length | 3828 mm |
| Wheel base | 2465 mm |
| Kerb weight | 1069 kg |
| Max. allowed weight | 1480 kg |

Additional information

| | |
|--------------------|-----------------------|
| Fuel tank capacity | 50 l |
| Fuel delivery | Multi-Point Injection |
| Number of doors | 3 |

| | |
|-----------------|------------|
| Number of seats | 4 |
| Number of axles | 2 |
| Engine number | CHF 004629 |