



report date: 2024-03-28

General information

Make	FORD
Model	MONDEO TITANIUM X 145
Colour	Blue
Year of manufacture	-
Top speed	130 mph
0 - 60 mph	9.6 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	144 BHP
Max. torque	190 Nm at 4.500 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	25.2 mpg
Consumption extra urban	47.1 mpg
Consumption combined	35.8 mpg



LABEL UNKNOWN

**MOT history**

<b>MOT #16</b>	2020-12-31 14:50
<b>MOT test number</b>	238985152140
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2021-12-30
<b>Advice</b>	Sub-frame pin or bush worn but not resulting in excessive movement all rear (5.3.4 (a) (i))
<b>Advice</b>	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
<b>Advice</b>	Brake pipe corroded, covered in grease or other material both main runs rear (1.1.11 (c))
<b>Advice</b>	Tyre worn close to legal limit/worn on edge both front (5.2.3 (e))

<b>MOT #15</b>	2019-06-28 12:07
<b>MOT test number</b>	950619713564
<b>Result</b>	✓ Passed
<b>Advice</b>	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
<b>Advice</b>	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

<b>MOT #14</b>	2019-06-28 10:14
<b>MOT test number</b>	657722278257
<b>Result</b>	✗ Failed
<b>Fail</b>	Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
<b>Advice</b>	Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
<b>Advice</b>	Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #13**

2018-06-29 14:23

**MOT test number**

833563677231

**Result**

✓ Passed

- Advice** Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Advice** Front exhaust pipe from front pipe adrift but not insecure
- Minor** Nearside Front Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #12**

2017-06-27 16:31

**MOT test number**

420502940398

**Result**

✓ Passed

- Advice** Nearside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**MOT #11**

2017-06-27 16:31

**MOT test number**

985706250466

**Result**

✗ Failed

- Pass with rectification** Offside Rear Direction indicator incorrect colour (1.4.A.2f)
- Advice** Nearside Front Outer Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)
- Pass with rectification** Nearside Rear Direction indicator incorrect colour (1.4.A.2f)
- Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**MOT #10**

2016-06-27 09:04

**MOT test number**

528196068151

**Result**

✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Nearside Rear Rear position lamp(s) has light sources not illuminating, but not more than 50% (1.1.A.3b)
- Advice** Offside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Quite alot of handbrake travel
- Advice** Offside Rear Direction indicator slightly discoloured (1.4.A.2f)
- Advice** Nearside Front constant velocity joint gaiter deteriorated, but preventing the ingress of dirt (2.5.C.1a)

**MOT #9**

2015-05-18 15:56

**MOT test number**

465838635110

**Result**

✓ Passed

**MOT #8**

2015-05-18 14:18

**MOT test number**

947658535116

**Result**

✗ Failed

- Fail** Offside Front Track rod end ball joint has excessive play (2.2.B.1f)
- Fail** Brake pedal anti-slip provision incomplete (3.3.A.1b)
- Fail** Offside Rear wheel bearing has excessive play (2.6.2)

**MOT #7**

2014-05-14 09:16

**MOT test number**

525724034134

**Result**

✓ Passed

- Advice** Parking brake lever has little reserve travel (3.1.6b)

**MOT #6** 2013-05-08 16:29**MOT test number** 835858023147**Result** ✓ Passed**Advice** Brake pipe slightly corroded (3.6.B.2c)**Notice** Slight cut on o/s/f inner tyre wall**MOT #5** 2013-05-08 15:26**MOT test number** 717588123141**Result** ✗ Failed**Fail** Braking system leaking (3.6.A.1)**Notice** Hand brake travel high**Advice** Brake pipe slightly corroded (3.6.B.2c)**Notice** Slight cut on o/s/f inner tyre wall**MOT #4** 2012-05-09 13:28**MOT test number** 607210132185**Result** ✓ Passed**MOT #3** 2012-05-09 08:38**MOT test number** 207190632192**Result** ✗ Failed**Fail** Nearside rear parking brake recording little or no effort (3.7.B.6a)**Fail** Parking brake: efficiency below requirements (3.7.B.7)



MOT #2 2011-06-04 09:46

MOT test number 148775451174

Result ✓ Passed

- Advice** Rear Brake pad(s) wearing thin (3.5.1g)
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Rear Exhaust has part of the system slightly deteriorated (7.1.1a)
- Advice** Front Brake pad(s) wearing thin (3.5.1g)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)
- Advice** Centre Exhaust has part of the system slightly deteriorated (7.1.1a)

MOT #1 2010-02-25 13:54

MOT test number 233596050054

Result ✓ Passed

- Advice** Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28
Current registration	<b>XXXXXX</b>
Plate since	2024-03-28

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-03-14
Last registration	2020-12-31
Complete history	<a href="#">See info</a>



Registration #1	2007-03-14	6 mi
Registration #2	2010-02-25	33.908 mi
Registration #3	2011-06-04	43.278 mi
Registration #4	2012-05-09	55.724 mi
Registration #5	2012-05-09	55.725 mi
Registration #6	2013-05-08	69.860 mi
Registration #7	2013-05-08	69.860 mi
Registration #8	2014-05-14	82.812 mi
Registration #9	2015-05-18	95.972 mi
Registration #10	2016-05-20	111.277 mi
Registration #11	2016-05-20	111.277 mi
Registration #12	2016-05-20	111.277 mi
Registration #13	2016-05-20	111.277 mi
Registration #14	2016-05-20	111.277 mi
Registration #15	2016-05-20	111.277 mi
Registration #16	2016-05-20	111.277 mi
Registration #17	2016-05-20	111.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2078 mm
Height	1451 mm
Length	4778 mm
Wheel base	2850 mm
Kerb weight	1491 kg
Max. allowed weight	2090 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2

Engine number

7J08915