





report date: 2024-03-29

General information

Make	MERCEDES
Model	C CLK200K SPORT
Colour	Black
Year of manufacture	2008
Top speed	147 mph
0 - 60 mph	9.1 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	181 BHP
Max. torque	250 Nm at 2.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	22.4 mpg
Consumption extra urban	43.5 mpg
Consumption combined	32.5 mpg
CO2 emission	207 g/km
CO2 label	K



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2022-02-18

Pictures 10

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



	_				
MC)	h	いてた	or	V
1,10	<i>,</i> ,		J	$\mathbf{o}_{\mathbf{i}}$	y.

MOT expiry date	2024-05-25
MOT pass rate	75 %
MOT passed	12
Failed MOT tests	4
Total advice items	12
Total items failed	5

MOT #16	2023-05-25 12:33
MOT test number	609584960559
Result	✓ Passed
Next expiry date	2024-05-25

MOT #15	2022-05-26 09:35
MOT test number	860557628726
Result	✓ Passed

MOT #14	2021-04-07 13:22
MOT test number	258102310431
Result	✓ Passed

MOT #13	2021-04-07 10:17
MOT test number	319292902238
Result	× Failed
Fail Offside Front Inner Suspension arm hall joint excessively worn (5.3.4 (a) (i))	

MOT #12	2020-04-03 10:43
MOT test number	767813645504
Result	✓ Passed

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #11 2020-04-03 08:53

MOT test number 102572235371

Result

× Failed

Fail Nearside Rear Lower Anti-roll bar linkage pin or bush excessively worn Drop link (5.3.4 (a) (i))

Fail Offside Rear Brake pipe excessively corroded (1.1.11 (c))

MOT #10 2019-04-05 15:52

MOT test number 196495948874

Result ✓ Passed

MOT #9 2019-04-05 10:56

MOT test number 852126134378

Result X Failed

Fail Offside Front Upper Anti-roll bar linkage ball joint dust cover no longer prevents the ingress of dirt Drop link dust cover. (5.3.4 (b) (ii))

MOT #8 2018-03-31 09:59

MOT test number 165484059541

Result ✓ Passed

MOT #7 2017-04-03 11:36

MOT test number 525759461819

Result ✓ Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #6		2016-03-09 10:43
MOT test	number	283460535686
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit centre of 1.8mm (4.1.E.1)	
Advice	Offside Front Tyre worn close to the legal limit outer edge of (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit centre of 1.9mm (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit outer edge of (4.1.E.1)	

MOT #5		2015-04-02 11:37
MOT test	number	827312095007
Result		✓ Passed
MOT #4		2014-04-04 10:45
MOT test	number	559074694007
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Brake pipe slightly corroded (3.6.B.2c)	

MOT #3	2013-04-08 14:56
MOT test number	459128593079
Result	✓ Passed

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT #2

MOT test number

Result

Notice Both o/s and n/s front brake discs slightly worn

MOT #1

MOT test number

Failed

Notice Both o/s and n/s front brake discs slightly worn

Pass with rectification

Offside Headlamp aim aimed so that it dazzles other road users (1.8.A.1a)

CarCheck.co.uk page 6/13



Tax & MOT check



Tax status	Valid until 1 February
Days left	277
MOT expiry date	25 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
venicle class	70
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history


Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date	
Category	
Туре	

Damage 2

Damage 2	
Date	
Category	



Extra MERCEDES salvage check



Type

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



Owner history

Owner history	
For how long did the current and previous owner(s) have this MERCEDES? How many ow MERCEDES have? Check it in the premium report and see all owner registrations. Downlo <u>here</u> .	

	More info >
Plate changes	
See in this check if this MERCEDES had different number plates.	
Number of plates	,
Current registration	NIP VIK
Plate since	
Current registration	NIK NIK
Plate since	
	More info >

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MERCEDES is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
0.1.116	

Contact info

More info >

CarCheck.co.uk page 11/13



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2008-09-12
Last registration	2023-05-25
Complete history	See info



Registration #1	2008-09-12	18 mi
Registration #2	2011-12-30	37.083 mi
Registration #3	2013-04-08	46.135 mi
Registration #4	2014-04-04	53.894 mi
Registration #5	2015-04-02	62.540 mi
Registration #6	2016-03-09	71.673 mi
Registration #7	2017-04-03	81.693 mi
Registration #8	2018-03-31	89.266 mi
Registration #9	2019-04-05	94.617 mi
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		91,700 esi
Registration #16		

More info >

CarCheck.co.uk page 12/13



Dimensions & weight

Width	1991 mm
Height	1415 mm
Length	4652 mm
Wheel base	2715 mm
Kerb weight	1540 kg

Additional information

Fuel tank capacity	62 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4
Number of axles	2
Engine number	27195531026547

CarCheck.co.uk page 13/13