



RENAULT




report date: 2024-03-28

General information

Make	RENAULT
Model	MEGANE FIDJI 16V SCENIC
Colour	Silver
Year of manufacture	2003
Top speed	108 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	95 BHP
Max. torque	127 Nm at 3.750 rpm
Engine capacity	1.390 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.1 mpg
Consumption extra urban	49.6 mpg
Consumption combined	39.8 mpg
CO2 emission	173 g/km
CO2 label	H





MOT history

MOT expiry date	2021-03-25
MOT pass rate	67 %
MOT passed	14
Failed MOT tests	7
Total advice items	45
Total items failed	12

MOT #212020-03-19 16:46

MOT test number757968278366

Result✓ Passed

Next expiry date2021-03-25

- Advice

Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Oil leak, but not excessive (8.4.1 (a) (i))
- Advice

Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- Advice

Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice

Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice

Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))

**MOT #20**

2020-03-19 15:14

MOT test number

122123745687

Result**✗ Failed**

- Advice** Nearside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Headlamp has a product on the lens but not seriously reducing light output (4.1.4 (b))
- Advice** Offside Front Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))
- MAJOR** Exhaust system insecure center clamp loose (6.1.2 (a))

MOT #19

2019-03-26 13:40

MOT test number

462126140521

Result**✓ Passed**

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #18

2019-03-26 10:30

MOT test number

487119102360

Result**✗ Failed**

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- MAJOR** Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #17**

2017-08-22 10:29

MOT test number

208978964058

Result

✓ Passed

Advice Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Front suspension noise

Advice Nearside Rear Nail in tyre

Advice Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Nearside Headlamp deteriorated but light output not reduced (1.7.5a)

MOT #16

2017-08-18 09:31

MOT test number

551921372290

Result

✗ Failed

Fail Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Advice Nearside Rear Nail in tyre

Advice Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Fail Offside Outer Front constant velocity joint gaiter insecure to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Advice Nearside Headlamp deteriorated but light output not reduced (1.7.5a)

Advice Front suspension noise

Advice Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

MOT #15

2016-09-01 09:32

MOT test number

247386229803

Result

✓ Passed

**MOT #14** 2015-05-11 17:28**MOT test number** 785871435189**Result** ✓ Passed**Notice** Under-trays fitted obscuring some underside components**Notice** Items removed from driver's view prior to test**Notice** Engine covers fitted obscuring some components in the engine bay**MOT #13** 2015-05-11 16:18**MOT test number** 208271435181**Result** ✗ Failed**Fail** Nearside Front Lower Suspension arm has excessive play in a ball joint (2.4.G.2)**Notice** Engine covers fitted obscuring some components in the engine bay**Notice** Under-trays fitted obscuring some underside components**Fail** Power steering pump leaking from a failed component (2.3.3b)**Notice** Items removed from driver's view prior to test**MOT #12** 2014-05-10 09:18**MOT test number** 138760334128**Result** ✓ Passed**Advice** Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)**Notice** Rear offside tyre worn on outer edge.

**MOT #11** 2014-05-10 09:18**MOT test number** 258310734171**Result** ✗ Failed

Pass with rectification Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

Advice Nearside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

Notice Rear offside tyre worn on outer edge.

MOT #10 2013-05-15 09:30**MOT test number** 266335533107**Result** ✓ Passed**MOT #9** 2012-05-29 17:04**MOT test number** 609620552179**Result** ✓ Passed

Advice Power steering pump has slight seepage from a component (2.3.3b)

MOT #8 2012-05-29 11:26**MOT test number** 156560752162**Result** ✗ Failed

Fail Offside front brake juddering severely (3.7.A.2b)

Fail Offside Registration plate lamp not working (1.1.C.1d)

Fail Nearside front brake juddering severely (3.7.A.2b)

Advice Power steering pump has slight seepage from a component (2.3.3b)

Fail Centre Stop lamp not working (1.2.1b)

MOT #7 2011-06-09 15:50**MOT test number** 216160661478**Result** ✓ Passed

**MOT #6** 2011-06-09 12:04**MOT test number** 177300261122**Result** ✗ Failed**Fail** Offside Front Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**MOT #5** 2010-06-18 10:23**MOT test number** 871319360123**Result** ✓ Passed**MOT #4** 2009-06-12 10:06**MOT test number** 273893769123**Result** ✓ Passed**MOT #3** 2008-06-03 11:48**MOT test number** 240315558427**Result** ✓ Passed**Notice** Offside rear tyre perished**Advice** Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #2** 2007-06-11 09:53**MOT test number** 202202767158**Result** ✓ Passed**MOT #1** 2006-06-14 08:11**MOT test number** 311315766120**Result** ✓ Passed



Tax & MOT check

✕
Untaxed

Tax expired:
21 December 2020

✕
MOT

Expired:
25 March 2021

Tax status	Expired at 21 December 2020
Days left	1225 days too late
MOT expiry date	25 March 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	H
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	21
First mileage registration	2003-06-30
Last registration	2020-03-19
Complete history	See info



Registration #1	2003-06-30	15 mi
Registration #2	2006-06-14	20.065 mi
Registration #3	2007-06-11	24.120 mi
Registration #4	2008-06-03	28.003 mi
Registration #5	2009-06-12	33.182 mi
Registration #6	2010-06-18	36.546 mi
Registration #7	2011-06-09	40.062 mi
Registration #8	2011-06-09	40.068 mi
Registration #9	2012-05-29	44.017 mi
Registration #10	2012-05-29	44.017 mi
Registration #11	2013-05-15	47.769 mi
Registration #12	2014-05-29	51.521 mi
Registration #13	2015-05-29	55.273 mi
Registration #14	2016-05-29	59.025 mi
Registration #15	2017-05-29	62.777 mi
Registration #16	2018-05-29	66.529 mi
Registration #17	2019-05-29	70.281 mi
Registration #18	2020-03-19	74.033 mi
Registration #19	2020-03-19	77.785 mi
Registration #20	2020-03-19	81.537 mi
Registration #21	2020-03-19	85.289 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	2007 mm
Height	1600 mm
Length	4140 mm
Wheel base	2580 mm
Kerb weight	1235 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	D343405