





report date: 2024-03-28

### General information

Make	PEUGEOT
Model	307 RAPIER
Colour	Blue
Year of manufacture	2003
Top speed	113 mph
0 - 60 mph	11.4 seconds
Gearbox	5 speed Manual

### Engine & fuel consumption

Power	107 BHP
Max. torque	147 Nm at 4.000 rpm
Engine capacity	1.587 cc
Cylinders	4
Fuel type	Petrol
Consumption city	28.5 mpg
Consumption extra urban	44.8 mpg
Consumption combined	36.7 mpg
CO2 emission	178 g/km
CO2 label	I



CarCheck.co.uk page 1/16



# Internet history

### Entry 1

Date 2021-07-14

Pictures 12

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/16



MOT history

MOT expiry date	2025-02-22
MOT pass rate	68 %
MOT passed	15
Failed MOT tests	7
Total advice items	61
Total items failed	8

MOT #22	2024-02-23 16:15
MOT test number	531479204212
Result	✓ Passed
Next expiry date	2025-02-22
Advice Rear Brakes imbalanced requirements only just met. It would appear requires adjustment or repair. (1.2.1 (b) (i))	r that the braking system

MOT #21		2024-02-20 16:03
MOT test	number	399228182471
Result		<b>★</b> Failed
MAJOR	Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
MAJOR	Horn not working (7.7 (a))	
MAJOR	Offside Front Direction indicator incorrect colour (4.4.3 (a))	
MAJOR	Nearside Front Headlamp aim projected beam image is obviously incorrect (4	4.1.2 (c))
MAJOR	Nearside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))	
Advice Rear Brakes imbalanced requirements only just met. It would appear that the braking system requires adjustment or repair. (1.2.1 (b) (i))		e braking system
MAJOR	Nearside Front Direction indicator not working (4.4.1 (a) (ii))	
Minor	Central Rear Stop lamp(s) with a multiple light source up to 1/2 not functioning	g (4.3.1 (a) (i))
MAJOR	Battery insecure and likely to cause a short circuit (4.13 (a) (ii))	
MAJOR	Offside Front Headlamp aim unable to be tested not working (4.1.2 (b))	

CarCheck.co.uk page 3/16



MOT #20 2023-02-21 13:44

MOT test number 150502215047

**Result** ✓ Passed

Advice

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #19 2022-02-22 18:25

**MOT test number** 599492475226

**MOT #18** 2022-02-17 18:50

MOT test number 463668396306

Result X Failed

MAJOR Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MAJOR Battery insecure and likely to fall from carrier (4.13 (a) (ii))

**MAJOR** Offside Rear Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength SILL (5.3.6 (a) (i))

**MAJOR** Offside Rear Outer Seat belt anchorage prescribed area strength or continuity significantly reduced SILL (7.1.1 (a) (i))

MAJOR Offside Side repeater incorrect colour (4.4.3 (a))

**MAJOR** Nearside Rear Outer Suspension component mounting prescribed area excessively corroded significantly reducing structural strength SILL (5.3.6 (a) (i))

**MAJOR** Nearside Rear Outer Seat belt anchorage prescribed area strength or continuity significantly reduced SILL (7.1.1 (a) (i))

**MOT #17** 2021-02-18 15:15

**MOT test number** 338833240679

CarCheck.co.uk page 4/16



**MOT #16** 2021-02-04 17:01

MOT test number 568540145844

**Result** X Failed

MAJOR Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))

**MAJOR** Horn not working (7.7 (a) (ii))

**Advice** Front tyres wearing on edges , n/s/r tyre getting low

**MAJOR** Emissions not tested (8.2.1.2 (d))

**MOT #15** 2016-09-22 15:55

MOT test number 893035131742

**Result** 
✓ Passed

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #14** 2016-09-21 09:08

MOT test number 113298459587

Result × Failed

**Fail** Nearside Headlamp aim beam image obviously incorrect (1.8.A.1b)

**Fail** Offside Rear Registration plate lamp not working (1.1.C.1d)

Fail Nearside Rear Registration plate lamp not working (1.1.C.1d)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #13 2015-06-09 09:00

**MOT test number** 178620765161

CarCheck.co.uk page 5/16



MOT #12		2014-06-10 09:54
MOT test	number	657961664181
Result		✓ Passed
Notice	Rear silencer corroded	
Advice	Front Brake pad(s) wearing thin (3.5.1g)	
Notice	O/s/r tyre misshapen	
Notice	N/s/r tyre slightly misshapen	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	Rear silencer baffles noisy	
Advice	Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)	
Notice	O/s/r tyre perishing	

MOT #11		2013-06-10 10:31
MOT test	number	757561563124
Result		✓ Passed
Notice	Rear (3rd) row of seats not fitted for test	
Advice	Front Exhaust has a minor leak of exhaust gases (7.1.2)	
Notice	Passenger seat(s) missing at time of test	

CarCheck.co.uk page 6/16



Result

Result

BN53UBJ report date: 2024-03-28

✓ Passed

× Failed

**MOT #10** 2012-06-07 16:24

**MOT test number** 318809852110

Advice Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Centre Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)

**Notice** Passenger seat(s) missing at time of test

**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)

**Notice** Rear(3rd) row of seats not fitted for test

**MOT #9** 2012-06-07 14:31

**MOT test number** 389199052172

**Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Notice** Passenger seat(s) missing at time of test

Advice Centre Stop lamp has light sources not illuminating, but not more than 50% (1.2.1b)

Fail Horn not working (1.6.2a)

**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)

**Notice** Rear(3rd) row of seats not fitted for test

MOT #8 2011-06-16 12:31

**MOT test number** 846797561108

**Result** ✓ Passed

**Notice** Part of centre brake light not working

**Notice** Rear(3rd)row of seats not fitted at time of test


**Notice** Offside rear tyre tread worn uneven

CarCheck.co.uk page 7/16



BN53UBJ

report date: 2024-03-28



MOT #6	2010-06-09	09:30
MOT test number	36002036	60185
Result	<b>✓</b> P	assed
MOT #5	2009-05-28	16:37
MOT test number	46080864	49197
Result	<b>✓</b> P	assed
Advice Offside Front Tyre	worn close to the legal limit (4.1.E.1)	
Advice Nearside Front Tyr	re worn close to the legal limit (4.1.E.1)	

MOT #4	2009-05-28 12:56	
MOT test number	174078149164	
Result	<b>X</b> Failed	
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)		
Fail Horn not working (1.6.2a)		
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)		

CarCheck.co.uk page 8/16



MOT #3 2008-06-09 11:17 **MOT test number** 572431368142 ✓ Passed Result MOT #2 2007-06-14 17:19 **MOT test number** 780185467141 Result Passed **Notice** Nearside sill panel damaged Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1) Notice High level brake light has one bulb not working

MOT #1		2006-09-05 13:44
MOT test	number	310838946464
Result		✓ Passed
Notice	Rear w/blade split	
Notice	Child seat fitted not allowing full inspection of adult belt	

CarCheck.co.uk page 9/16





Tax & MOT check



Tax status	Valid until 1 August
Days left	95
MOT expiry date	22 February 2025
Full MOT history	See MOT history

### Tax calculation

Vehicle class	48
Band	1
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-


CarCheck.co.uk page 10/16



#### Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



#### Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 11/16



#### Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 12/16



### Owner history

For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	
**************************************	
***************************************	
********	
***************************************	
	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	,
Current registration	NIE NIE NIE
Plate since	
Current registration	NK SIK
Plate since	
	More info >

CarCheck.co.uk page 13/16



### Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

**Contact info** 


More info >

CarCheck.co.uk page 14/16



# Mileage check

Odometer	In miles
Mileage registrations	24
First mileage registration	2003-09-04
Last registration	2024-02-23
Complete history	See info



Registration #1	2003-09-04	28 mi
Registration #2	2006-09-05	25.447 mi
Registration #3	2007-06-14	29.015 mi
Registration #4	2008-06-09	35.545 mi
Registration #5	2009-05-28	39.971 mi
Registration #6	2009-05-28	39.971 mi
Registration #7	2010-06-09	45.392 mi
Registration #8	2011-06-15	51.229 mi
Registration #9	2011-06-16	51.229 mi
Registration #10	2012-06-07	57.083 mi
Registration #11	2012-06-07	57.083 mi
Registration #12	2013-06-10	61.405 mi
Registration #12 Registration #13	2013-06-10	61.405 mi
Registration #13		
Registration #13 Registration #14		
Registration #13 Registration #14 Registration #15		
Registration #13 Registration #14 Registration #15 Registration #16		
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17		
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18		
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19		
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20		
Registration #13 Registration #14 Registration #15 Registration #16 Registration #17 Registration #18 Registration #19 Registration #20 Registration #21		

More info >



### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1757 mm
Height	1544 mm
Length	4419 mm
Wheel base	2708 mm
Kerb weight	1269 kg

# Additional information

<u> </u>	
Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number Carcheck.co.uk	FX3K1620981 page 16/16