



Mercedes-Benz



report date: 2024-03-28

General information

Make	MERCEDES
Model	SLK SLK 200 KOMPRESSOR
Colour	Red
Year of manufacture	2009
Top speed	155 mph
Gearbox	7 speed automatic

Engine & fuel consumption

Power	184 BHP
Max. torque	250 Nm at 2.800 rpm
Engine capacity	1.796 cc
Cylinders	4
Fuel type	Petrol
Consumption city	23.9 mpg
Consumption extra urban	45.6 mpg
Consumption combined	34.5 mpg
CO2 emission	196 g/km
CO2 label	J





Internet history

Entry 1

Date	2021-08-07
Pictures	29
Listing price	View report



source: cargurus.co.uk

**MOT history**

MOT expiry date	2024-09-01
MOT pass rate	87 %
MOT passed	13
Failed MOT tests	2
Total advice items	15
Total items failed	6

MOT #15	2023-08-21 08:46
MOT test number	899741888679
Result	✓ Passed
Next expiry date	2024-09-01

MOT #14	2022-08-15 10:11
MOT test number	823411905287
Result	✓ Passed
Advice	Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

MOT #13	2021-09-02 09:33
MOT test number	658403886501
Result	✓ Passed

MOT #12	2020-10-22 11:39
MOT test number	634530196003
Result	✓ Passed
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened x2 inner faces slightly scored (1.1.14 (a) (ii))
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #11**

2019-09-30 12:30

MOT test number

506332767108

Result

✓ Passed

Advice

Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice

Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #10

2019-09-30 08:16

MOT test number

908469679918

Result

✗ Failed

Fail

Offside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice

Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Fail

Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))

Advice

Nearside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))

MOT #9

2018-10-04 10:17

MOT test number

118693133472

Result

✓ Passed

Advice

UNDERSIDE RUSTY

Advice

Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice

INNER BRAKE DISC FACES RUSTY

**MOT #8** 2018-09-29 10:51**MOT test number** 581713663455**Result** ✗ Failed

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords
PERISHED AND WORN VERY LOW (5.2.3 (d) (i))

Advice UNDERSIDE RUSTY

Fail Offside Front Suspension arm ball joint excessively worn REAR MOST ARM (5.3.4 (a) (i))

Fail Offside Rear Brake pipe excessively corroded (1.1.11 (c))

Advice INNER BRAKE DISC FACES RUSTY

Advice Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Fail Nearside Rear Brake pipe excessively corroded (1.1.11 (c))

MOT #7 2017-08-22 06:15**MOT test number** 993974040081**Result** ✓ Passed**MOT #6** 2016-08-22 15:20**MOT test number** 440380218402**Result** ✓ Passed**MOT #5** 2015-09-04 10:03**MOT test number** 815809163098**Result** ✓ Passed**MOT #4** 2014-09-06 14:22**MOT test number** 167409944260**Result** ✓ Passed



MOT #3	2014-02-10 13:49
MOT test number	307331744059
Result	✓ Passed

MOT #2	2013-02-18 13:55
MOT test number	196909343448
Result	✓ Passed
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

MOT #1	2012-02-15 13:54
MOT test number	857716242046
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 September 2024

✓
MOT
Expires:
1 September 2024

Tax status	Valid until 1 September
Days left	124
MOT expiry date	1 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 YX58JYF
Plate since	2019-06-29
Current registration	 YX58JYF
Plate since	2019-06-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2009-02-19
Last registration	2023-08-21
Complete history	See info



Registration #1	2009-02-19	6 mi
Registration #2	2012-02-15	8.323 mi
Registration #3	2013-02-18	11.332 mi
Registration #4	2014-02-10	15.487 mi
Registration #5	2014-09-06	17.564 mi
Registration #6	2015-09-04	21.570 mi
Registration #7	2016-08-22	25.583 mi
Registration #8	2017-08-22	30.206 mi
Registration #9	2018-09-29	35.078 mi
Registration #10	2019-09-29	39.377 mi
Registration #11	2020-09-29	43.377 mi
Registration #12	2021-09-29	47.377 mi
Registration #13	2022-09-29	51.377 mi
Registration #14	2023-09-29	55.377 mi
Registration #15	2024-09-29	59.377 mi
Registration #16	2025-09-29	63.377 mi
Registration #17	2026-09-29	67.377 mi

More info >



Dimensions & weight

Width	2012 mm
Height	1296 mm
Length	4103 mm
Wheel base	2430 mm
Kerb weight	1415 kg
Max. allowed weight	1705 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	2
Number of axles	2
Engine number	27195431253706