





General information

Make	RENAULT
Model	WIND GT LINE VVT
Colour	Blue
Year of manufacture	2011
Top speed	125 mph
0 - 100 km/h	9.2 seconds
0 - 60 mph	9.2 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	98 kW / 133 HP / 133 BHP
Max. torque	160 Nm at 4.400 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.0 mpg
Consumption extra urban	49.6 mpg
Consumption combined	40.9 mpg
CO2 emission	159 g/km
CO2 label	G







Internet history

Entry 1

Date Pictures 2021-08-17

12

Listing price

View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-08-24
MOT pass rate	73 %
MOT passed	11
Failed MOT tests	4
Total advice items	24
Total items failed	9

MOT #15		2023-08-22 08:12
MOT test	number	599307559895
Result		✓ Passed
Next expi	ry date	2024-08-24
Advice	Nearside Front Brake pipe corroded, covered in grease or other material (1	.1.11 (c))
Advice	Front Brake disc worn, pitted or scored, but not seriously weakened inner fa	ace (1.1.14 (a) (ii))
Advice	Front Service brake fluctuating, but not excessively (1.2.1 (e))	
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1	.11 (c))
Advice	Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #14		2022-08-25 14:41
MOT test	number	354254971976
Result		✓ Passed
Advice	Offside Front Brake pipe corroded, covered in grease or other material (1.1.1	L (c))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously weakened	(1.1.14 (a) (ii))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1	.1.14 (a) (ii))
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1	1.14 (a) (ii))





MOT #13		2022-08-22 11:13
MOT test	number	580052489043
Result		× Failed
Advice	Offside Front Brake disc worn, pitted or scored, but not seriously weak	ened (1.1.14 (a) (ii))
Advice	Nearside Front Brake disc worn, pitted or scored, but not seriously wea	kened (1.1.14 (a) (ii))
Fail N	earside Front Lower Suspension component ball joint excessively worn (5	5.3.4 (a) (i))
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weake	ened (1.1.14 (a) (ii))
Advice	Offside Front Brake pipe corroded, covered in grease or other material	(1.1.11 (c))

MOT #12	2021-08-24 07:10
MOT test number	411638111420
Result	✓ Passed

MOT #11	2020-11-30 10:01
MOT test number	704155614809
Result	✓ Passed
Advice Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #10		2020-11-30 10:01
MOT test number		241834850292
Result		🗙 Failed
Pass with rectification	Nearside Headlamp aim too high (4.1.2 (a))	
Advice Nearside Front T	yre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

МОТ #9	2019-11-13 10:26
MOT test number	787650590663
Result	Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	



SD61SUV
report date: 2024-03-28

МОТ #8	2019-11-09 11:21
MOT test number	152437653921
Result	🗙 Failed
Fail Offside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Fail Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))	
Fail Parking brake efficiency below requirements (1.4.2 (a) (i))	

MOT #7	2019-05-29 09:02
MOT test	number 561715994753
Result	✓ Passed
Advice	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Advice	Service light on

MOT #6 2019-	05-22 12:50
MOT test number 31	9910705764
Result	🗙 Failed
Fail Nearside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	
Fail Horn not working (7.7 (a) (ii))	
Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
Fail Offside Front Track rod end ball joint has excessive play (2.1.3 (b) (i))	
Fail Offside Rear Coil spring fractured or broken (5.3.1 (b) (i))	
Advice Service light on	



SD61SUV report date: 2024-03-28

MOT #5	2018-05-03 10:59
MOT test number	532930003128
Result	✓ Passed
Advice Nearside Front Track rod end ball joint has slight play (2.2.B.1f)	
Advice Offside Front Track rod end ball joint has slight play (2.2.B.1f)	
МОТ #4	2017-05-04 15:57
MOT test number	421177521491
Result	✓ Passed
MOT #3	2016-11-02 10:24
MOT test number	125923325352
Result	🗸 Passed
MOT #2	2015-10-28 10:41
MOT test number	288818767878
Result	🗸 Passed
MOT #1	2014-10-28 10:29
MOT test number	117011604337
Result	✓ Passed
Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)	



Tax & MOT check

Tax due: 1 August 2024	√ axed	Expires: 24 August 2024	✓ МОТ
Tax status			Valid until 1 August
Days left			95
MOT expiry date			24 August 2024
Full MOT history			See MOT history
Tax calculation			

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-





Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	FERM
Category	 A PLANE
Туре	
Damage 2	AMPLE
Damage 2	E Stand
Date	*
Category	 ante.
Туре	

Extra RENAULT salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4.11.111
Auction value	4 10.000
Average private trade value	4 11 711





Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	



SD61SUV report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2011-10-31
Last registration	2023-08-22
Complete history	<u>See info</u>



Registration #1	2011-10-31	8 mi
Registration #2	2014-10-28	16.514 mi
Registration #3	2015-10-28	23.869 mi
Registration #4	2016-11-02	31.334 mi
Registration #5	2017-05-04	33.838 mi
Registration #6	2018-05-03	41.914 mi
Registration #7	2019-05-22	46.309 mi
Registration #8	2019-05-29	46.316 mi
Registration #9	2019-11-09	48.344 mi
Registration #10		11.777 esi
Registration #11		11.777 mi
Registration #12		11.777 esi
Registration #13		11.777 mi
Registration #14		11.777 esi
Registration #15		11.777 mi
Registration #16		11.777 est
Registration #17		11.777 mi





Car features

S0225	Air conditioning
\$0295	
50482	
50501	
60566	
60567	
60569	

Safety ratings

NCAP rating

Video

see crash video



Dimensions & weight	
Width	1913 mm
Height	1381 mm
Length	3833 mm
Wheel base	2368 mm
Kerb weight	1131 kg
Max. allowed weight	1383 kg
Additional information	
Fuel tank capacity	40
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats CarCheck.co.uk	2 page 13/13

Number of axles	2
Engine number	D011593