





report date: 2024-03-29

### General information

| Make                | VAUXHALL |
|---------------------|----------|
| Model               | INSIGNIA |
| Colour              | Grey     |
| Year of manufacture | 2019     |
| Gearbox             | -        |

# Engine & fuel consumption

| Engine capacity | 1.956 сс |
|-----------------|----------|
| Fuel type       | Diesel   |
| CO2 emission    | 147 g/km |
| CO2 label       | F        |



CarCheck.co.uk page 1/9



report date: 2024-03-29

### Internet history

#### Entry 1

Date 2022-03-04

Pictures 34

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/9



report date: 2024-03-29

| N/I | $\alpha$ |    | TC: | - | r\/ |
|-----|----------|----|-----|---|-----|
| 101 | •        |    | 115 |   | ıv  |
|     | •        | Γh |     |   | . , |

| MOT expiry date    | 2025-03-03 |
|--------------------|------------|
| MOT pass rate      | 100 %      |
| MOT passed         | 3          |
| Failed MOT tests   | 0          |
| Total advice items | 4          |
| Total items failed | 0          |

| MOT #3           | 2024-03-01 14:24 |
|------------------|------------------|
| MOT test number  | 920833523144     |
| Result           | ✓ Passed         |
| Next expiry date | 2025-03-03       |

| MOT #2      |  | 2023-03-01 13:00         |
|-------------|--|--------------------------|
| MOT test    | number   | 618835637500             |
| Result      |  | ✓ Passed                 |
| Advice (i)) | Nearside Front Tyre has a cut but not deep enough to reach the ply or co | rds Side wall (5.2.3 (d) |
| Advice      | Front Brake pad(s) wearing thin (1.1.13 (a) (ii))                        |                          |

| MOT #1   | 2022-02-28 21:55   |
|----------|--|
| MOT test | number 407000241530  |
| Result   | ✓ Passed   |
| Advice   | Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii)) |
| Advice   | Front Brake disc worn, pitted or scored, but not seriously weakened Both (1.1.14 (a) (ii))     |

CarCheck.co.uk page 3/9



report date: 2024-03-29

### Tax & MOT check



| Tax status       | Valid until 1 April |
|------------------|---------------------|
| Days left        | 337                 |
| MOT expiry date  | 3 March 2025        |
| Full MOT history | See MOT history     |

### Tax calculation

| -  |            |
|--|------------|
| Vehicle class  | 49         |
| Band   | Н          |
| First licence fee (12 months)                        | £ 255,00,- |
| First licence fee diesel non RDE2 tested (12 months) | £ 645,00,- |
| Standard rate (12 months)                            | £ 180,00,- |
| Standard rate (6 months)                             | £ 99,00,-  |
| Premium rate (12 months)                             | £ 570,00,- |
| Premium rate (6 months)                              | £ 313,50,- |

CarCheck.co.uk page 4/9



report date: 2024-03-29

#### Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report <u>here</u> for the results.

Damage 1

Date

Category

**Type** 

Damage 2

Date

**Category** 

**Type** 



#### Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 5/9



report date: 2024-03-29

More info >

### Owner history

| owner mistery   |             |
|---|-------------|
| For how long did the current and previous owner(s) have this VAUXHALL? How many own VAUXHALL have? Check it in the premium report and see all owner registrations. Downlo here. |             |
| 99999999  |             |
|   |             |
| ***************************************   |             |
|   |             |
|   |             |
|   |             |
| **************************************  |             |
|   | More info > |
| Plate changes  See in this check if this VAUXHALL had different number plates.  |             |
| Number of plates  |             |
| Current registration  | UK SIE      |
| Plate since   |             |
| Current registration  | NK NK       |
| Plate since   |             |

CarCheck.co.uk page 6/9



report date: 2024-03-29

#### Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VAUXHALL is financed.

| Finance company   |  |
|-------------------|--|
| Date of agreement |  |
| Agreement type    |  |
| Agreement term    |  |
| Agreement number  |  |
|                   |  |

**Contact info** 

More info >

CarCheck.co.uk page 7/9



report date: 2024-03-29

Mileage check

| Odometer                   | In miles   |
|----------------------------|------------|
| Mileage registrations      | 5          |
| First mileage registration | 2019-03-04 |
| Last registration          | 2024-03-01 |
| Complete history           | See info   |



| Registration #1 | 2019-03-04 | 22 mi     |
|-----------------|------------|-----------|
| Registration #2 | 2022-02-28 | 35.147 mi |
| Registration #3 |            | 11.177 es |
| Registration #4 |            | 71.777 es |
| Registration #5 |            | 11.777 es |

More info >

CarCheck.co.uk page 8/9



report date: 2024-03-29

# Safety ratings

| NCAP rating    | ****            |
|----------------|-----------------|
| Adult          | 93%             |
| Children       | 85%             |
| Pedestrian     | 78%             |
| Safety systems | 69%             |
| Overall rating | 84%             |
| Video          | see crash video |



## Additional information

| Engine number | D20DTH OPT-17F83385 |
|---------------|---------------------|
|---------------|---------------------|

CarCheck.co.uk page 9/9