





report date: 2024-03-29

General information

Make	RENAULT
Model	MEGANE RENAULTSPORT TROPHY S/S
Colour	Black
Year of manufacture	2015
Top speed	158 mph
0 - 60 mph	6.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	271 BHP
Max. torque	360 Nm at 3.000 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption city	28.8 mpg
Consumption extra urban	45.6 mpg
Consumption combined	37.7 mpg
CO2 emission	174 g/km
CO2 label	Н



CarCheck.co.uk page 1/11



Internet history

Entry 4

Date 2023-01-12

Pictures 43

Listing price <u>View report</u>










source: cargurus.co.uk


Entry 3

Date	2023-01-10
------	------------

Pictures 20

Listing price <u>View report</u>









source: autotrader.co.uk

Entry 2

Date 2021-12-02

Pictures 5

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Pictures 17

Listing price <u>View report</u>









source: autotrader.co.uk



MOT history

MOT expiry date	2025-03-10
MOT pass rate	75 %
MOT passed	6
Failed MOT tests	2
Total advice items	7
Total items failed	2

MOT #8	2024-02-28 10:16
MOT test number	214551050221
Result	✓ Passed
Next expiry date	2025-03-10

MOT #7	2023-03-11 09:44
MOT test number	913029968489
Result	✓ Passed
Advice Offside Rear Wheel bearing has slight play (5.1.3 (a) (i))	

MOT #6	2023-02-16 08:45
MOT test number	981936530004
Result	X Failed
Pass with rectification (4.1.2 (c))	Nearside Front Headlamp aim projected beam image is obviously incorrect
Advice Offside Rear Wh	eel bearing has slight play (5.1.3 (a) (i))
Pass with rectification	Nearside Front Headlamp aim too low (4.1.2 (a))
MAJOR Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))	

MOT #5	2022-02-15 16:07
MOT test number	427122438704
Result	✓ Passed

CarCheck.co.uk page 3/11



LP15KUR

report date: 2024-03-29

MOT #4		2022-01-18 13:22
MOT test	number	209132051959
Result		× Failed
MAJOR	Nearside Headlamp not working on main beam (4.1.1 (a) (ii))	
MAJOR Exhaust carbon monoxide content at idle exceeds manufacturer's specified limits (8.2.1.2 (b))		
MAJOR Nearside Headlamp aim projected beam image is obviously incorrect (4.1.2 (c))		
MAJOR Exhaust carbon monoxide content after 2nd fast idle exceeds manufacturer's specified limits		
(8.2.1.2 (a		

(8.2.1.2 (a))	
MOT #3	2020-12-29 13:16
MOT test number	381136331359
Result	✓ Passed
MOT #2	2019-05-24 08:05
MOT test number	632014661526
Result	✓ Passed
MOT #1	2018-05-25 13:43
MOT test number	577173653930
Result	✓ Passed

CarCheck.co.uk page 4/11



Tax & MOT check

Tax expired: 1 April 2024





Tax status	Expired at 1 April 2024
Days left	29 days too late
MOT expiry date	10 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
Single payment (12 months)	£ 290,00,-
Single six month payment	£ 159,50,-
Total payable by 12 monthly instalments	£ 304,50,-

CarCheck.co.uk page 5/11



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owne have? Check it in the premium report and see all owner registrations. Download the full respectively.		AULT

	More info	>
Plate changes		
See in this check if this RENAULT had different number plates.		
Number of plates		,
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 8/11



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



LP15KUR

report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2015-05-26
Last registration	2024-02-28
Complete history	See info



Registration #1	2015-05-26	24 mi
Registration #2	2018-05-25	23.079 mi
Registration #3	2019-05-24	29.904 mi
Registration #4	2020-12-29	44.166 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7	2022-01-18	49.760 mi
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		0.074
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es

More info >

CarCheck.co.uk page 10/11



Car features

S0225	Air conditioning
S0295	
S0482	
50501	
50566	
50567	
S0569	

Safety ratings

NCAP rating	****
Adult	83%
Children	78%
Pedestrian	60%
Safety systems	56%
Overall rating	72%
Video	see crash video



Dimensions & weight

Width	1848 mm
Height	1435 mm
Length	4299 mm
Wheel base	2636 mm
Kerb weight	1376 kg
Max. allowed weight	1809 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles 2

Engine number C028959