





report date: 2024-03-28

General information

Make	JAGUAR
Model	F-TYPE V6 S
Colour	Silver
Year of manufacture	2014
Top speed	171 mph
Gearbox	8 speed automatic

Engine & fuel consumption

Power	380 BHP
Max. torque	460 Nm at 3.500 rpm
Engine capacity	2.995 cc
Cylinders	6
Fuel type	Petrol
Consumption city	22.1 mpg
Consumption extra urban	40.4 mpg
Consumption combined	31.0 mpg
CO2 emission	213 g/km
CO2 label	K



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-01-31


Pictures 10

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2024-10-23
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	9
Total items failed	3

MOT #9	2023-10-24 12:23
MOT test number	439653467223
Result	✓ Passed
Next expiry date	2024-10-23

MOT #8	2022-05-04 14:24
MOT test number	718367308177
Result	✓ Passed

MOT #7		2021-04-09 15:02
MOT test	number	887136678619
Result		✓ Passed
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

CarCheck.co.uk page 3/12



MOT #6 2020-03-06 10:08

MOT test number 439175979543

Result \rightarrow Passed

Advice Offside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Nearside Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #5 2019-03-08 11:15

MOT test number 277127032421

Result \rightarrow Passed

MOT #4 2019-03-06 15:45

MOT test number 910501094340

Result X Failed

Fail Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Minor Nearside Windscreen wiper blade defective Small split (3.4 (b) (i))

Fail Horn not working (7.7 (a) (ii))

MOT #3 2018-03-14 16:05

MOT test number 946373851714

Result ✓ Passed

MOT #2 2018-03-13 11:27

MOT test number 832690382023

Result X Failed

Fail Nearside Front Inner Tyre has ply or cords exposed damaged (4.1.D.1b)

Advice Offside Front tyre worn inner

CarCheck.co.uk page 4/12



MOT #1 2017-03-15 11:14

MOT test number 534819967943

Result ✓ Passed

Advice

Both rear tyres 3+mm n,s,r sidewall damaged

CarCheck.co.uk page 5/12



Tax & MOT check



Tax status	Valid until 1 November
Days left	185
MOT expiry date	23 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history

*		
For how long did the current and previous owner(s) have this JAGUAR? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.		AR

	More info	>
Plate changes See in this check if this JAGUAR had different number plates.		
Number of plates		,
Current registration	UK	
Plate since		
Current registration	UK NE	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12





report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-05-02
Last registration	2023-10-24
Complete history	See info



Registration #1	2014-05-02	11 mi
Registration #2	2017-03-15	35.283 mi
Registration #3	2018-03-13	42.168 mi
Registration #4	2018-03-14	42.303 mi
Registration #5	2019-03-06	48.135 mi
Registration #6	2019-03-08	48.140 mi
Registration #7		11.777 es
Registration #8		11.777 es
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		71.777 mg

More info >

CarCheck.co.uk page 11/12



— •	_	
Dumanci	One A.	Walaht
Dimensi	צו כווט	welull

Width	1923 mm
Height	1309 mm
Length	4470 mm
Wheel base	2622 mm
Kerb weight	1594 kg
Max. allowed weight	2050 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	2
Number of axles	2
Engine number	14032910303306PS

CarCheck.co.uk page 12/12