



RENAULT

MAIOYRF

report date: 2024-03-29

General information

Make	RENAULT
Model	MEGANE DYNAMIQUE VVT
Colour	Grey
Year of manufacture	2010
Top speed	118 mph
0 - 60 mph	10.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	110 BHP
Max. torque	151 Nm at 4.250 rpm
Engine capacity	1.598 cc
Cylinders	4
Fuel type	Petrol
Consumption city	29.1 mpg
Consumption extra urban	50.4 mpg
Consumption combined	39.8 mpg
CO2 emission	162 g/km
CO2 label	G





Internet history

Entry 1

Date	2021-06-18
Pictures	11
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2023-11-25
MOT pass rate	79 %
MOT passed	11
Failed MOT tests	3
Total advice items	24
Total items failed	7

MOT #14	2022-11-26 15:27
MOT test number	633168853814
Result	✓ Passed
Next expiry date	2023-11-25

MOT #13	2021-10-30 14:14
MOT test number	969543669825
Result	✓ Passed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Front Nail in tyre
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #12	2021-10-30 14:14
MOT test number	102309638277
Result	✗ Failed
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))
Advice	Nearside Front Nail in tyre
Pass with rectification	Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11**

2020-11-26 16:20

MOT test number

259813027858

Result

✓ Passed

- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Rear Shock absorbers has slight external damage to the casing Both corroded (5.3.2 (b))

MOT #10

2020-11-26 11:53

MOT test number

375015739750

Result

✗ Failed

- Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Offside Front Position lamp not working (4.2.1 (a) (ii))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Oil leak, but not excessive (8.4.1 (a) (i))
- Advice** Rear Shock absorbers has slight external damage to the casing Both corroded (5.3.2 (b))
- Fail** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))
- Fail** Front Headlamp aim too high both (4.1.2 (a))
- Fail** Front Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt Both (6.1.7 (g) (ii))



MOT #9	2019-11-11 10:03
---------------	------------------

MOT test number	350833799883
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #8	2018-11-10 10:37
---------------	------------------

MOT test number	642248969266
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #7	2017-11-13 14:45
---------------	------------------

MOT test number	452569415285
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #6	2016-11-03 14:24
---------------	------------------

MOT test number	290126843830
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #5	2015-11-06 08:56
---------------	------------------

MOT test number	653562337572
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #4	2014-11-11 16:03
---------------	------------------

MOT test number	525045414396
------------------------	--------------

Result	✓ Passed
---------------	----------

MOT #3	2013-11-26 09:51
---------------	------------------

MOT test number	386270533346
------------------------	--------------

Result	✓ Passed
---------------	----------

Advice	Offside Front Front wheel bearing has slight play (2.5.A.3c)
---------------	--

Advice	Front Brake pad(s) wearing thin (3.5.1g)
---------------	--



MOT #2	2013-11-26 09:51
MOT test number	899190633330
Result	✗ Failed
Pass with rectification	Offside Headlamp aim too low (1.8)
Advice	Offside Front Front wheel bearing has slight play (2.5.A.3c)
Pass with rectification	Nearside Headlamp aim too low (1.8)
Advice	Front Brake pad(s) wearing thin (3.5.1g)

MOT #1	2013-03-26 11:25
MOT test number	149205083046
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 10,000
Auction value	£ 10,000
Average private trade value	£ 10,000

More info >



Owner history

For how long did the current and previous owner(s) have this RENAULT? How many owners did this RENAULT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this RENAULT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this RENAULT is financed.

Finance company	RENAULT	2024
Date of agreement	RENAULT	2024
Agreement type	RENAULT	2024
Agreement term	RENAULT	2024
Agreement number	RENAULT	2024
Contact info	RENAULT	2024

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2010-03-31
Last registration	2022-11-26
Complete history	See info



Registration #1	2010-03-31	16 mi
Registration #2	2013-03-26	31.093 mi
Registration #3	2013-11-26	40.287 mi
Registration #4	2014-11-11	47.979 mi
Registration #5	2015-11-06	52.845 mi
Registration #6	2016-11-03	57.226 mi
Registration #7	2017-11-13	61.557 mi
Registration #8	2018-11-10	67.681 mi
Registration #9	2019-11-10	73.805 mi
Registration #10	2020-11-10	79.929 mi
Registration #11	2021-11-10	86.053 mi
Registration #12	2022-11-10	92.177 mi
Registration #13	2023-11-10	98.301 mi
Registration #14	2024-11-10	104.425 mi
Registration #15	2025-11-10	110.549 mi

More info >



Car features

The RENAULT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete RENAULT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	2037 mm
Height	1423 mm
Length	4299 mm
Wheel base	2640 mm
Kerb weight	1205 kg
Max. allowed weight	1728 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	5

Engine number	D051208
---------------	---------