



report date: 2024-03-29

General information

Make	NISSAN
Model	CABSTAR 34.10 SWB P/U
Colour	White
Year of manufacture	2004
Gearbox	5 speed Manual

Engine & fuel consumption

Power	156 BHP
Max. torque	323 Nm at 2.000 rpm
Engine capacity	2.953 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-11-06
Pictures	11
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-09-19
MOT pass rate	94 %
MOT passed	17
Failed MOT tests	1
Total advice items	37
Total items failed	0

MOT #182023-09-20 14:42

MOT test number517076443708

Result✓ Passed

Next expiry date2024-09-19

- Advice

Oil leak, but not excessive Slight oil leak around sump (8.4.1 (a) (i))
- Advice

Nearside Front Tyre worn close to legal limit/worn on edge Worn on outer edge (5.2.3 (e))
- Advice

Front Exhaust has a minor leak of exhaust gases Down pipe cracked (6.1.2 (a))
- Advice

Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor

Electrical wiring insecure Negative terminal loose on battery (4.11 (a) (i))
- Advice

Offside Rear Tyre worn close to legal limit/worn on edge 3mm tread (5.2.3 (e))

**MOT #17**

2023-09-11 15:23

MOT test number

991787835319

Result**✗ Failed**

- Advice** Front Exhaust has a minor leak of exhaust gases Down pipe cracked (6.1.2 (a))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge Worn on outer edge (5.2.3 (e))
- Advice** Offside Front Brake pipe corroded, covered in grease or other material (1.1.11 (c))
- Minor** Electrical wiring insecure Negative terminal loose on battery (4.11 (a) (i))
- MAJOR** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Service brake efficiency below requirements (1.2.2 (a) (i))
- MAJOR** Nearside Rear Position lamp adversely affected by the operation of another lamp All lights (4.2.3 (c))
- MAJOR** Nearside Front Brake pipe excessively corroded x3 pipes In chassis to joining block (1.1.11 (c))
- Advice** Oil leak, but not excessive Slight oil leak around sump (8.4.1 (a) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge 3mm tread (5.2.3 (e))
- MAJOR** Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))
- MAJOR** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Rear Brakes imbalanced across an axle Axle 2 (1.2.1 (b) (i))
- MAJOR** Offside Rear Position lamp adversely affected by the operation of another lamp All lights (4.2.3 (c))

**MOT #16** 2022-07-20 11:26**MOT test number** 275544724525**Result** ✓ Passed

Advice Nearside Rear Position lamp slightly affected by the operation of another lamp Slight Interaction on rear lights (4.2.3 (c))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Front Brake pipe corroded, covered in grease or other material x3 pipes slightly corroded in n/s front chassis to joining block (1.1.11 (c))

Minor Nearside Windscreen wiper blade defective (3.4 (b) (i))

Advice Offside Rear Position lamp slightly affected by the operation of another lamp Slight interaction on rear lights (4.2.3 (c))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Front Exhaust has a minor leak of exhaust gases Downpipe cracked (6.1.2 (a))

Minor Offside Windscreen wiper blade defective (3.4 (b) (i))

MOT #15 2021-06-18 07:33**MOT test number** 846412094882**Result** ✓ Passed**MOT #14** 2020-06-19 15:39**MOT test number** 882680871246**Result** ✓ Passed**MOT #13** 2019-06-06 11:00**MOT test number** 438184915814**Result** ✓ Passed

Advice Brake pipe corroded, covered in grease or other material all pipes greased (1.1.11 (c))

MOT #12 2018-05-25 13:03**MOT test number** 806348050921**Result** ✓ Passed

**MOT #11** 2017-06-12 11:35**MOT test number** 609412823485**Result** ✓ Passed**MOT #10** 2016-06-06 15:41**MOT test number** 332085912553**Result** ✓ Passed**MOT #9** 2015-06-08 09:27**MOT test number** 985189955102**Result** ✓ Passed**Advice** Brake pipe slightly corroded (3.6.B.2c)**MOT #8** 2014-05-28 09:51**MOT test number** 275078444197**Result** ✓ Passed**MOT #7** 2013-05-31 14:58**MOT test number** 525451253125**Result** ✓ Passed**MOT #6** 2012-05-25 14:24**MOT test number** 599856642185**Result** ✓ Passed**MOT #5** 2011-05-27 15:43**MOT test number** 208767641195**Result** ✓ Passed**Advice** Windscreen has damage to an area less than a 40mm circle outside zone 'A' (8.3.1d)

**MOT #4** 2010-06-21 15:30**MOT test number** 480252470112**Result** ✓ Passed**MOT #3** 2009-06-22 11:08**MOT test number** 502403179128**Result** ✓ Passed

- Notice** Centre exhaust clamp heavily corroded.
- Notice** Condition of offside rear shock absorber bottom bush borderline.
- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)
- Notice** Nearside front wiper blade borderline condition.
- Notice** Crak in nearside rear light unit.

MOT #2 2008-06-20 09:56**MOT test number** 210892678456**Result** ✓ Passed**MOT #1** 2007-06-22 11:06**MOT test number** 180363077108**Result** ✓ Passed

- Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
19 September 2024

Tax status		Valid until 1 January
Days left		247
MOT expiry date		19 September 2024
Full MOT history		See MOT history



Damage history

Check the damage history for this NISSAN. See if, where and when this NISSAN had damage and the car repair costs. We also check if this NISSAN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra NISSAN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this NISSAN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this NISSAN? How many owners did this NISSAN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this NISSAN had different number plates.

Number of plates	1
Current registration	FT04EXW
Plate since	2019-03-29
Current registration	FT04EXW
Plate since	2019-03-29

More info >



Finance check

Check if this NISSAN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this NISSAN has been settled.

If not, and you buy this NISSAN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this NISSAN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2004-06-22
Last registration	2023-09-20
Complete history	See info



Registration #1	2004-06-22	9 mi
Registration #2	2007-06-22	33.796 mi
Registration #3	2008-06-20	44.271 mi
Registration #4	2009-06-22	55.833 mi
Registration #5	2010-06-21	65.850 mi
Registration #6	2011-05-27	74.840 mi
Registration #7	2012-05-25	83.450 mi
Registration #8	2013-05-31	98.376 mi
Registration #9	2014-05-28	113.370 mi
Registration #10	2015-06-08	125.074 mi
Registration #11	2016-06-08	136.788 mi
Registration #12	2017-06-08	148.502 mi
Registration #13	2018-06-08	160.216 mi
Registration #14	2019-06-08	171.930 mi
Registration #15	2020-06-08	183.644 mi
Registration #16	2021-06-08	195.358 mi
Registration #17	2022-06-08	207.072 mi
Registration #18	2023-06-08	218.786 mi
Registration #19	2024-06-08	230.500 mi
Registration #20	2025-06-08	242.214 mi

More info >



Car features

The NISSAN factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete NISSAN factory list for this vehicle [here](#).

More info >

Dimensions & weight

Width	1800 mm
Max. allowed weight	3400 kg

Additional information

Number of seats	3
Number of axles	2
Engine number	075371