





report date: 2024-03-28

General information

Make	VOLKSWAGEN
Model	EOS TSI
Colour	Black
Year of manufacture	2008
Top speed	122 mph
0 - 60 mph	10.9 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	122 BHP
Max. torque	200 Nm at 1.500 rpm
Engine capacity	1.390 сс
Cylinders	4
Fuel type	Petrol
Consumption city	32.5 mpg
Consumption extra urban	50.4 mpg
Consumption combined	42.2 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2022-02-24

Pictures 68

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/12



MOT history

MOT expiry date	2023-08-26
MOT pass rate	86 %
MOT passed	12
Failed MOT tests	2
Total advice items	16
Total items failed	3

MOT #14	2022-08-08 08:24
MOT test number	304297761571
Result	✓ Passed
Next expiry date	2023-08-26

MOT #13	2021-08-27 10:55
MOT test number	932354510569
Result	✓ Passed
Advice Offside Front Lower Suspension arm pin or bush worn but not resulting in exces (5.3.4 (a) (i))	ssive movement
Advice Front Brake disc worn, but not excessively (1.1.14 (a) (i))	
Advice Offside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))	
Advice Nearside Front Lower Suspension arm pin or bush worn but not resulting in exc (5.3.4 (a) (i))	cessive movement
Advice Nearside Front Tyre worn close to legal limit/worn on edge 3mm (5.2.3 (e))	

MOT #12	2020-10-13 09:23
MOT test number	365725317423
Result	✓ Passed

CarCheck.co.uk page 3/12



MOT #11 2020-10-13 09:23

MOT test number 486952008660

Result X Failed

Pass with rectification

Front Windscreen washer provides insufficient washer liquid (3.5 (a))

MOT #10 2019-09-11 07:47

MOT test number 929833159467

MOT #9 2018-10-20 09:19

MOT test number 515165915817

Result \rightarrow Passed

Advice

Child Seat fitted not allowing full inspection of adult belt

MOT #8 2017-11-29 15:20

MOT test number 812903531239

MOT #7 2017-11-29 13:35

MOT test number 799346860934

Result ★ Failed

Fail Nearside Front Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Fail Offside Rear Tyre has ply or cords exposed (4.1.D.1b)

MOT #6 2016-10-14 07:46

MOT test number 680728341939

Result

Passed

Advice Offside Rear Tyre worn close to the legal limit bald inside edge (4.1.E.1)

CarCheck.co.uk page 4/12



RJ08WVR

report date: 2024-03-28

MOT #5	2015-10-06 07:55
MOT test number	851974166720
Result	✓ Passed
MOT #4	2014-09-22 08:46
MOT test number	539855164202
Result	✓ Passed
Notice Engine covers fitted obscuring some components in the engine bay	
Notice Under-trays fitted obscuring some underside components	

MOT #3		2013-07-04 16:00
MOT test	number	865535683162
Result		✓ Passed
Notice	Engine covers fitted obscuring some components in the engine bay	
Advice	Rear Brake pad(s) wearing thin (3.5.1g)	
Notice	Under-trays fitted obscuring some underside components	

MOT #2		2012-07-12 09:17
MOT test	number	177604392111
Result		✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)	
Advice	Offside Rear Tyre worn close to the legal limit (4.1.E.1)	
Advice	Nearside Rear Tyre worn close to the legal limit (4.1.E.1)	
Notice	Under-trays fitted obscuring some underside components	

MOT #1	2011-07-05 09:15
MOT test number	789956481180
Result	✓ Passed

CarCheck.co.uk page 5/12



Tax & MOT check



MOT
Expired:
26 August 2023

Tax expired: 3 November 2022

Tax status Expired at 3 November 2022

Days left 544 days too late

MOT expiry date 26 August 2023

Full MOT history See MOT history

Tax calculation

Vehicle class	48
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



Damage history


Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date
Category
Type
Damage 2
Date

Category

Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	NIE
Plate since	
Current registration	AIR AIR
Plate since	
	More info >

CarCheck.co.uk page 9/12



Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 10/12



Mileage check

Registration #16

Odometer	In miles
Mileage registrations	16
First mileage registration	2008-05-09
Last registration	2022-08-08
Complete history	See info



Registration #1	2008-05-09	15 mi
Registration #2	2011-07-05	18.014 mi
Registration #3	2012-07-12	25.003 mi
Registration #4	2013-07-04	31.191 mi
Registration #5	2014-09-22	38.174 mi
Registration #6	2015-10-06	43.973 mi
Registration #7	2016-10-14	48.953 mi
Registration #8	2017-11-29	54.336 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		D.777 es

7075.75.75

More info >

77. 777 mg

CarCheck.co.uk page 11/12



Car features

50225	Air conditionir
50295	
60482	
60501	
60566	
0567	
60569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1791 mm
Height	1437 mm
Length	4407 mm
Wheel base	2578 mm
Max. allowed weight	1930 kg

Additional information

-	
Fuel tank capacity	55 I
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of seats	4

CarCheck.co.uk page 12/12

Number of axles	2
Engine number	CAX 016127