



report date: 2024-03-28

General information

Make	CITROEN
Model	NEMO 610 LX HDI
Colour	Grey
Year of manufacture	2009
Top speed	94 mph
0 - 60 mph	16.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	70 BHP
Max. torque	160 Nm at 1.750 rpm
Engine capacity	1.399 cc
Cylinders	4
Fuel type	Diesel
Consumption city	49.6 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-07-28
Pictures	0
Listing price	View report

source: cargurus.co.uk



MOT history

MOT expiry date	2023-07-15
MOT pass rate	91 %
MOT passed	10
Failed MOT tests	1
Total advice items	20
Total items failed	1

MOT #11 2022-07-16 11:42

MOT test number 999652680257

Result ✓ Passed

Next expiry date 2023-07-15

- Advice** Offside Front and o\s\r tyres wearing and getting low to nearing 2mm,
- Advice** Offside Front Headlamp has a product on the light source but not seriously reducing light output lens opered (4.1.4 (b))
- Advice** Rear Coil spring corroded both sides rear (5.3.1 (b) (i))
- Advice** Rear Direction indicator slightly discoloured both sides rear (4.4.3 (a))
- Advice** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced rear sub frame area (6.1.1 (c) (i))

MOT #10 2022-07-12 16:01

MOT test number 141367086152

Result ✗ Failed

- Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))
- Advice** Rear Coil spring corroded both sides rear (5.3.1 (b) (i))
- Advice** Offside Front Headlamp has a product on the light source but not seriously reducing light output lens opered (4.1.4 (b))
- Advice** Offside Front and o\s\r tyres wearing and getting low to nearing 2mm,
- Advice** Rear Vehicle structure is corroded but structural rigidity is not significantly reduced rear sub frame area (6.1.1 (c) (i))
- Advice** Rear Direction indicator slightly discoloured both sides rear (4.4.3 (a))

**MOT #9** 2020-02-04 10:03**MOT test number** 434145215519**Result** ✓ Passed**Advice** Nearside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Offside Rear tyre perrishing**Advice** Front both tyres wearing on edges**Advice** All rear suspension parts corroded**MOT #8** 2019-01-31 14:51**MOT test number** 638944986610**Result** ✓ Passed**MOT #7** 2018-01-29 12:39**MOT test number** 903470523508**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre**MOT #6** 2017-02-10 15:34**MOT test number** 780519967471**Result** ✓ Passed**Advice** Nearside Rear Nail in tyre**MOT #5** 2016-02-02 16:43**MOT test number** 963857703778**Result** ✓ Passed

**MOT #4** 2015-02-05 15:17**MOT test number** 666796335090**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)**MOT #3** 2014-02-07 12:56**MOT test number** 928598734025**Result** ✓ Passed**Notice** No peak detected**MOT #2** 2013-02-08 09:53**MOT test number** 176509233457**Result** ✓ Passed**MOT #1** 2012-02-08 15:42**MOT test number** 749429032088**Result** ✓ Passed



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	
Plate since	2019-01-01
Current registration	
Plate since	2019-01-01

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXX	XXXX
Date of agreement	XXXXXXXX	XXXX
Agreement type	XXXXXXXX	XXXX
Agreement term	XXXXXXXX	XXXX
Agreement number	XXXXXXXX	XXXX
Contact info	XXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2009-02-10
Last registration	2022-07-16
Complete history	See info



Registration #1	2009-02-10	9 mi
Registration #2	2012-02-08	12.347 mi
Registration #3	2013-02-08	13.874 mi
Registration #4	2014-02-07	16.706 mi
Registration #5	2015-02-05	20.562 mi
Registration #6	2016-02-02	24.826 mi
Registration #7	2017-02-10	29.487 mi
Registration #8	2018-02-09	34.148 mi
Registration #9	2019-02-07	38.809 mi
Registration #10	2020-02-05	43.470 mi
Registration #11	2021-02-03	48.131 mi
Registration #12	2022-02-01	52.792 mi
Registration #13	2022-07-16	57.453 mi

More info >



Dimensions & weight

Width	2019 mm
Height	1721 mm
Length	3864 mm
Kerb weight	1090 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	2
Engine number	FD982502161