



Mercedes-Benz




report date: 2024-03-29

General information

Make	MERCEDES
Model	ML ML 280 CDI EDITION S
Colour	Silver
Year of manufacture	2007
Top speed	127 mph
0 - 60 mph	9.8 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	188 BHP
Max. torque	440 Nm at 2.800 rpm
Engine capacity	2.987 cc
Cylinders	6
Fuel type	Diesel
Consumption city	21.9 mpg
Consumption extra urban	35.3 mpg
Consumption combined	28.8 mpg
CO2 emission	254 g/km
CO2 label	L






Internet history

Entry 2




Date	2021-07-12
Pictures	15
Listing price	View report



source: [autotrader.co.uk](#)

Entry 1

Date	2021-05-25
Pictures	14
Listing price	View report



source: [autotrader.co.uk](#)



MOT history

MOT expiry date	2024-06-29
MOT pass rate	72 %
MOT passed	13
Failed MOT tests	5
Total advice items	30
Total items failed	14

MOT #18 2023-06-30 14:34

MOT test number 356869033700

Result ✓ Passed

Next expiry date 2024-06-29

- Minor** Nearside Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))
- Advice** Offside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))
- Advice** Offside Front Power steering component has slight seepage from a component Rack gaiter area (2.1.5 (a))

MOT #17 2022-06-14 09:34

MOT test number 428377664067

Result ✓ Passed

- Advice** Power steering component has slight seepage from a component (2.1.5 (a))
- Advice** Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))
- Minor** Nearside Side repeater lens defective which has no effect on emitted light (4.4.1 (b) (i))
- Advice** Brake pedal wearing smooth (1.1.2 (c))
- Minor** Offside Steering rack gaiter damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))
- Advice** Offside Front Road wheel slightly distorted (5.2.2 (c) (i))
- Minor** Offside Headlamp reflector slightly defective (4.1.1 (b) (i))
- Advice** Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

**MOT #16** 2021-05-18 12:25**MOT test number** 988567381238**Result** ✓ Passed**MOT #15** 2021-05-15 10:53**MOT test number** 141818328828**Result** ✗ Failed**Fail** Front Brake hose excessively deteriorated both (1.1.12 (b) (ii))**Advice** Front Shock absorbers has a reduced damping effect (5.3.2 (d))**Fail** Offside Registration plate lamp inoperative in the case of a single lamp or all lamps (4.7.1 (b) (ii))**Fail** Rear Coil spring fractured or broken both (5.3.1 (b) (i))**Advice** Oil leak, but not excessive (8.4.1 (a) (i))**MOT #14** 2020-06-09 17:40**MOT test number** 567180232071**Result** ✓ Passed**Advice** N/s/f tyre 2mm tread + worn/bold edges - recommend replace**Advice** Struggled to pass emissions test**Advice** Nail in n/s/r tyre**MOT #13** 2019-06-13 11:53**MOT test number** 113986739191**Result** ✓ Passed**Advice** Slight edge fray to n/s/f seat belt**Advice** N/s/f tyre worn outer edge + some small splits in tyre outer side wall rim**Advice** Front brake hoses deteriorating - recommend replace**Advice** Some wear to brake pedal rubber

**MOT #12**

2019-06-13 11:37

MOT test number

675346177132

Result**✗ Failed****Fail** Nearside Rear Direction indicator not working (4.4.1 (a) (ii))**Advice** Slight edge fray to n/s/f seat belt**Advice** N/s/f tyre worn outer edge + some small splits in tyre outer side wall rim**Fail** Nearside Rear Position lamp not working (4.2.1 (a))**Advice** Front brake hoses deteriorating - recommend replace**Advice** Some wear to brake pedal rubber**Fail** Offside Front Position lamp not working (4.2.1 (a))**MOT #11**

2018-06-19 10:00

MOT test number

640794849076

Result**✓ Passed****MOT #10**

2018-06-12 10:35

MOT test number

383656051470

Result**✗ Failed****Fail** Exhaust emissions exceed level of metered smoke for a turbo charged engine (8.2.2.2 (b))**Fail** Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))**Minor** Offside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**MOT #9**

2017-06-13 08:27

MOT test number

354817348742

Result**✓ Passed****Advice** Rear Brake pad(s) wearing thin (3.5.1g)

**MOT #8** 2016-09-13 10:03**MOT test number** 848912739209**Result** ✓ Passed**MOT #7** 2015-09-12 16:17**MOT test number** 691906927834**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)**MOT #6** 2013-11-07 15:30**MOT test number** 206961613327**Result** ✓ Passed**MOT #5** 2013-11-07 11:29**MOT test number** 119471613395**Result** ✗ Failed**Fail** Headlamp not working on dipped beam (1.7.5a)**Notice** Oil leak**Fail** Offside Rear Direction indicators incorrect colour (1.4.A.2f)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**Fail** Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**Advice** Brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**MOT #4** 2012-09-10 12:25**MOT test number** 899424852207**Result** ✓ Passed



MOT #3	2012-09-10 12:25
MOT test number	395254252450
Result	✗ Failed
Pass with rectification	Rear fog lamp not working (1.3.2b)
Pass with rectification	Offside Rear position lamp(s) not working (1.1.A.3b)

MOT #2	2011-05-27 16:20
MOT test number	935937841173
Result	✓ Passed

MOT #1	2010-04-19 12:16
MOT test number	470169100110
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 August 2024

✓
MOT
Expires:
29 June 2024

Tax status	Valid until 1 August
Days left	93
MOT expiry date	29 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	L
Single payment (12 months)	£ 675,00,-
Single six month payment	£ 371,25,-
Total payable by 12 monthly instalments	£ 708,75,-




Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.


Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	1
Current registration	 XXXXXX
Plate since	2024-03-29
Current registration	 XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	20
First mileage registration	2007-05-03
Last registration	2023-06-30
Complete history	See info



Registration #1	2007-05-03	25 mi
Registration #2	2010-04-19	31.290 mi
Registration #3	2011-05-27	42.604 mi
Registration #4	2012-09-10	55.383 mi
Registration #5	2013-11-07	65.358 mi
Registration #6	2013-11-07	65.358 mi
Registration #7	2015-09-12	79.581 mi
Registration #8	2016-09-13	86.859 mi
Registration #9	2017-06-13	87.955 mi
Registration #10	2018-06-12	92.400 mi
Registration #11	2019-06-20	95.377 mi
Registration #12	2019-06-20	95.377 mi
Registration #13	2019-06-20	95.377 mi
Registration #14	2019-06-20	95.377 mi
Registration #15	2019-06-20	95.377 mi
Registration #16	2019-06-20	95.377 mi
Registration #17	2019-06-20	95.377 mi
Registration #18	2019-06-20	95.377 mi
Registration #19	2019-06-20	95.377 mi
Registration #20	2019-06-20	95.377 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1911 mm
Height	1884 mm
Length	4780 mm
Wheel base	2915 mm
Kerb weight	2185 kg

Additional information

Fuel tank capacity	95 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	64294040371305