





report date: 2024-03-29

General information

Make	VOLVO
Model	V60 D2 BUSINESS EDITION
Colour	Grey
Year of manufacture	2017
Top speed	121 mph
0 - 60 mph	10.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	118 BHP
Max. torque	280 Nm at 1.500 rpm
Engine capacity	1.969 cc
Cylinders	4
Fuel type	Diesel
Consumption city	67.3 mpg
Consumption extra urban	78.5 mpg
Consumption combined	74.3 mpg
CO2 emission	98 g/km
CO2 label	Α



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2021-08-14

Pictures 50

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

MOT expiry date	2024-09-06
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	15
Total items failed	0

MOT #6		2023-08-29 14:07
MOT test	number	264335052387
Result		✓ Passed
Next expi	y date	2024-09-06
Advice	Offside Rear Seat belt slightly damaged (7.1.2 (b) (i))	
Advice	Offside Front Tyre slightly damaged/cracking or perishing outer sidewall ((5.2.3 (d) (ii))
Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords outer sidewall (5.2.3 (d) (i))		
Advice	Nearside Front Tyre slightly damaged/cracking or perishing outer sidewal	I (5.2.3 (d) (ii))
Advice	Offside Rear Tyre slightly damaged/cracking or perishing outer sidewall (5.2.3 (d) (ii))

MOT #5		2022-08-19 12:25
MOT test	number	514967334383
Result		✓ Passed
Advice	Offside Rear Tyre slightly damaged/cracking or perishing outer sidewall (5	.2.3 (d) (ii))
Advice Offside Front Tyre has a cut but not deep enough to reach the ply or cords outer sidewall (5.2.3 (d) (i))		

MOT #4	2021-09-07 14:49
MOT test number	580917008237
Result	✓ Passed

CarCheck.co.uk page 3/11



YM66AZV report date: 2024-03-29

MOT #3 2021-01-05 10:07
MOT test number 166486916364

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt

Advice Offside Rear Seat belt slightly damaged (7.1.2 (b) (i))

MOT #2 2020-01-07 16:13

MOT test number 745152197445

Result
✓ Passed

MOT #1 2020-01-07 11:44

MOT test number 691337236958

Result X Failed

Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MAJOR Front Windscreen washer provides insufficient washer liquid (3.5 (a))

DANGEROUS Offside Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))

Advice TPMS on

Advice Nearside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check





Expires: 6 September 2024

Tax status	Valid until 1 September
Days left	125
MOT expiry date	6 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	Α
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



YM66AZV report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full	

THE STATE OF THE S	

	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	
Current registration	NK NK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-01-11
Last registration	2023-08-29
Complete history	See info



Registration #1	2017-01-11	16 mi
Registration #2	2020-01-07	31.835 mi
Registration #3	2020-01-07	31.835 mi
Registration #4	2021-01-05	36.378 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	94%
Children	82%
Pedestrian	64%
Safety systems	100%
Overall rating	86%
Video	see crash video



Dimensions & weight

Width	2097 mm
Height	1484 mm
Length	4635 mm
Wheel base	2776 mm
Kerb weight	1617 kg
Max. allowed weight	2170 kg

Additional information

Fuel tank capacity	67	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5 page	11/11

Number of axles2Engine number1925912