





report date: 2024-03-28

General information

| Make | TOYOTA |
|---------------------|----------------|
| Model | IQ VVT-I IQ |
| Colour | Silver |
| Year of manufacture | 2010 |
| Top speed | 93 mph |
| Gearbox | 5 speed Manual |

Engine & fuel consumption

| Power | 67 BHP |
|-------------------------|--------------------|
| Max. torque | 91 Nm at 4.800 rpm |
| Engine capacity | 998 сс |
| Cylinders | 3 |
| Fuel type | Petrol |
| Consumption city | 57.7 mpg |
| Consumption extra urban | 72.4 mpg |
| Consumption combined | 65.7 mpg |
| CO2 emission | 99 g/km |
| CO2 label | A |



CarCheck.co.uk page 1/12



Internet history

Entry 1

Date 2021-10-02

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/12



MOT history

| MOT expiry date | 2024-10-18 |
|--------------------|------------|
| MOT pass rate | 85 % |
| MOT passed | 11 |
| Failed MOT tests | 2 |
| Total advice items | 5 |
| Total items failed | 3 |

| MOT #13 | 2023-10-19 15:40 |
|--|-----------------------------------|
| MOT test number | 593415419995 |
| Result | ✓ Passed |
| Next expiry date | 2024-10-18 |
| Advice Front Headlamp has a product on the lens but not seriously reduci | ing light output Both (4.1.4 (b)) |

| MOT #12 | | 2022-09-29 12:56 |
|--|--|------------------|
| MOT test | number | 714111999123 |
| Result | | ✓ Passed |
| Advice Offside Brake pipe corroded, covered in grease or other material front to rear (1.1.11 (c)) | | |
| Advice | Advice Brake pad(s) wearing thin Front & Rear (1.1.13 (a) (ii)) | |
| Advice | Tyre worn close to legal limit/worn on edge Both front (5.2.3 (e)) | |

| MOT #11 | 2021-10-15 14:34 |
|-----------------|------------------|
| MOT test number | 613396104667 |
| Result | ✓ Passed |

CarCheck.co.uk page 3/12



MOT #10

MOT test number

Result

Pass with rectification

Nearside Rear Service brake excessively binding (1.2.1 (f))

Pass with rectification

Offside Rear Service brake excessively binding (1.2.1 (f))

MOT #9

MOT test number

631633568289

Result

Advice (c))

Offside Brake pipe corroded, covered in grease or other material front to rear pipe at rear (1.1.11

| MOT #8 | 2019-08-14 09:57 |
|-----------------|------------------|
| MOT test number | 704331172040 |
| Result | ✓ Passed |

| MOT #7 | 2018-08-07 10:59 |
|-----------------|------------------|
| MOT test number | 605937032726 |
| Result | ✓ Passed |

| MOT #6 | 2017-08-08 09:36 |
|-----------------|------------------|
| MOT test number | 542966085931 |
| Result | ✓ Passed |

| MOT #5 | 2016-08-09 11:49 |
|-----------------|------------------|
| MOT test number | 189207294961 |
| Result | ✓ Passed |

CarCheck.co.uk page 4/12



MOT #4 2016-08-09 11:49
MOT test number 565752545042

Result X Failed

Pass with rectification

Windscreen wiper does not clear the windscreen effectively both blades (8.2.2)

MOT #3 2015-08-13 11:40 MOT test number 975552290404

Result

Passed

MOT #2 2014-08-21 11:09

MOT test number 928853134218

Result ✓ Passed

MOT #1 2013-08-22 11:34

MOT test number 835724333277

CarCheck.co.uk page 5/12



Tax & MOT check



| Tax status | Valid until 1 November |
|------------------|------------------------|
| Days left | 187 |
| MOT expiry date | 18 October 2024 |
| Full MOT history | See MOT history |

Tax calculation

| Vehicle class | 48 |
|---|----------------|
| Band | A |
| Single payment (12 months) | £ 0,00,- |
| Single six month payment | Not applicable |
| Total payable by 12 monthly instalments | Not applicable |

CarCheck.co.uk page 6/12



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

| Damage 1 | |
|----------|--|
| Date | |
| Category | |
| Туре | |
| Damage 2 | |
| Date | |
| Category | |
| Type | |



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



VX10ZFZ

report date: 2024-03-28

| Owner history | |
|--|-------------|
| For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full it | |
| ********* | |
| | |
| *************************************** | |
| ********* | |
| *************************************** | |
| *************************************** | |
| | More info > |
| Plate changes | |
| See in this check if this TOYOTA had different number plates. | |
| Number of plates | |
| Current registration | NE NE |
| Plate since | |
| Current registration | NK NK |
| Plate since | |
| | More info > |

CarCheck.co.uk page 9/12



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

| Finance company | |
|-------------------|--|
| Date of agreement | |
| Agreement type | |
| Agreement term | |
| Agreement number | |
| Contact info | |

More info >

CarCheck.co.uk page 10/12



Mileage check

| Odometer | In miles |
|----------------------------|------------|
| Mileage registrations | 15 |
| First mileage registration | 2010-06-18 |
| Last registration | 2023-10-19 |
| Complete history | See info |



| Registration #1 | 2010-06-18 | 13 mi |
|------------------|------------|-----------|
| Registration #2 | 2013-08-22 | 18.515 mi |
| Registration #3 | 2014-08-21 | 21.148 mi |
| Registration #4 | 2015-08-13 | 23.430 mi |
| Registration #5 | 2016-08-09 | 26.050 mi |
| Registration #6 | 2016-08-09 | 26.050 mi |
| Registration #7 | 2017-08-08 | 28.433 mi |
| Registration #8 | 2018-08-07 | 31.296 mi |
| Registration #9 | | 11.777 es |
| Registration #10 | | 11.777 es |
| Registration #11 | | 11.777 es |
| Registration #12 | | 11.777 es |
| Registration #13 | | 11.777 es |
| Registration #14 | | 11.777 es |
| Registration #15 | | D.777 es |

More info >

CarCheck.co.uk page 11/12



Car features

| S0225 | Air conditioning |
|-------|------------------|
| S0295 | |
| S0482 | |
| S0501 | |
| S0566 | |
| 50567 | |
| S0569 | |

Safety ratings

| NCAP rating | **** |
|----------------|-----------------|
| Adult | 91% |
| Children | 71% |
| Pedestrian | 54% |
| Safety systems | 86% |
| Overall rating | 79% |
| Video | see crash video |



Dimensions & weight

| Width | 1680 mm |
|---------------------|---------|
| Height | 1500 mm |
| Length | 2985 mm |
| Wheel base | 2000 mm |
| Kerb weight | 845 kg |
| Max. allowed weight | 1215 kg |

Additional information

| Fuel tank capacity | 32 I |
|-----------------------------------|-----------------------|
| Fuel delivery | Multi-Point Injection |
| Number of doors | 3 |
| Number of seats CarCheck.co.uk | 4 page 12/12 |

Number of axles 2

Engine number 1KR1004227