



report date: 2024-03-29

General information

Make	FORD
Model	MONDEO TITANIUM X SPORT TDCI
Colour	Blue
Year of manufacture	-
Top speed	143 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	197 BHP
Max. torque	420 Nm at 1.750 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	36.2 mpg
Consumption extra urban	56.5 mpg
Consumption combined	47.1 mpg



LABEL UNKNOWN



Internet history

Entry 1

Date	2021-09-16
Pictures	10
Listing price	<a href="#">View report</a>



source: cargurus.co.uk

**MOT history**

<b>MOT #12</b>	2022-11-05 09:03
<b>MOT test number</b>	829330780396
<b>Result</b>	✓ Passed
<b>Next expiry date</b>	2023-11-07

<b>MOT #11</b>	2021-11-08 16:32
<b>MOT test number</b>	276575870087
<b>Result</b>	✓ Passed

<b>MOT #10</b>	2021-03-25 15:50
<b>MOT test number</b>	738504854237
<b>Result</b>	✓ Passed

<b>MOT #9</b>	2021-03-22 09:44
<b>MOT test number</b>	724547544354
<b>Result</b>	✗ Failed

- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))
- Fail** Front Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

<b>MOT #8</b>	2020-03-12 16:37
<b>MOT test number</b>	115052587989
<b>Result</b>	✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Inner faces (1.1.14 (a) (ii))
- Advice** Exhaust system and hangers corroded.
- Advice** Coil spring corroded All (5.3.1 (b) (i))

**MOT #7** 2020-03-12 10:16**MOT test number** 838042857180**Result** ✗ Failed

- Advice** Coil spring corroded All (5.3.1 (b) (i))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened Inner faces (1.1.14 (a) (ii))
- Advice** Exhaust system and hangers corroded.
- Fail** Offside Track rod end ball joint has excessive play (2.1.3 (b) (i))

**MOT #6** 2019-03-14 10:42**MOT test number** 612563409745**Result** ✓ Passed

- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Brake pipe corroded, covered in grease or other material Front to rear (1.1.11 (c))
- Advice** Coil spring corroded All (5.3.1 (b) (i))

**MOT #5** 2019-03-13 13:15**MOT test number** 242885411119**Result** ✗ Failed

- Fail** Nearside Rear Tyre has a lump, caused by separation or partial failure of its structure (5.2.3 (d) (ii))
- Advice** Brake pipe corroded, covered in grease or other material Front to rear (1.1.11 (c))
- Advice** Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
- Advice** Coil spring corroded All (5.3.1 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #4** 2018-03-21 07:51**MOT test number** 189338577979**Result** ✓ Passed

**MOT #3** 2017-10-06 14:44**MOT test number** 688215701482**Result** ✓ Passed**Advice** Tyres wearing on edges**MOT #2** 2016-10-15 07:40**MOT test number** 114459388427**Result** ✓ Passed**Advice** Nearside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement  
(2.4.G.2)**Advice** Offside Rear Trailing arm rubber bush deteriorated but not resulting in excessive movement  
(2.4.G.2)**MOT #1** 2015-10-17 07:21**MOT test number** 119406795613**Result** ✓ Passed



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >





Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-10-19
Last registration	2022-11-05
Complete history	<a href="#">See info</a>



Registration #1	2012-10-19	18 mi
Registration #2	2015-10-17	31.454 mi
Registration #3	2016-10-15	34.936 mi
Registration #4	2017-10-06	38.141 mi
Registration #5	2018-03-21	39.037 mi
Registration #6	2019-03-13	45.122 mi
Registration #7	2019-03-14	45.123 mi
Registration #8	2019-03-20	45.127 mi
Registration #9	2019-03-20	45.127 mi
Registration #10	2019-03-20	45.127 mi
Registration #11	2019-03-20	45.127 mi
Registration #12	2019-03-20	45.127 mi
Registration #13	2019-03-20	45.127 mi
Registration #14	2019-03-20	45.127 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating



Video

[see crash video](#)



Dimensions & weight

Width	2078 mm
Height	1500 mm
Length	4778 mm
Wheel base	2850 mm
Kerb weight	1740 kg
Max. allowed weight	2210 kg

Additional information

Fuel tank capacity	70 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

<b>Number of axles</b>	2
<b>Engine number</b>	CL62357