





General information

Make	MINI
Model	CLUBMAN COOPER
Colour	White
Year of manufacture	2017
Top speed	127 mph
0 - 60 mph	9.2 seconds
Gearbox	7 speed automatic

Engine & fuel consumption

Power	134 BHP
Max. torque	220 Nm at 4.200 rpm
Engine capacity	1.499 cc
Cylinders	3
Fuel type	Petrol
Consumption city	40.9 mpg
Consumption extra urban	56.5 mpg
Consumption combined	2.8 mpg
CO2 emission	121 g/km
CO2 label	D







Internet history

Entry 1

Date

Pictures

2021-09-25

10

Listing price

View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-10-20
MOT pass rate	83 %
MOT passed	5
Failed MOT tests	1
Total advice items	18
Total items failed	2

MOT #6		2023-10-03 12:56
MOT test	number	500894780973
Result		✓ Passed
Next expi	ry date	2024-10-20
Advice	Offside Rear Coil spring corroded (5.3.1 (b) (i))	
Advice (ii))	Offside Front Tyre slightly damaged/cracking or perishing Slight damage o	outer sidewall. (5.2.3 (d)
Advice	Nearside Rear Inner Road wheel slightly distorted (5.2.2 (c) (i))	

MOT #5	2022	2-10-21 13:51
MOT test	number 55	50232539031
Result		🗸 Passed
Advice	Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice (d) (i))	Nearside Front Tyre has a cut but not deep enough to reach the ply or cords Several c	uts. (5.2.3
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	





MOT #4	2022-10-21 13:51
MOT test number	288553142279
Result	🗙 Failed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Pass with rectification Offside Headlamp aim too high (4.1.2 (a))	
Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice Nearside Rear Child Seat fitted not allowing full inspection of adult belt	
Pass with rectification Nearside Headlamp aim too high (4.1.2 (a))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cord (d) (i))	ls Several cuts. (5.2.3
Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt	

MOT #3	2021-10-19 15:47
MOT test number	651296651463
Result	✓ Passed

MOT #2	2021-03-18 16:54
MOT test	number 981832988059
Result	✓ Passed
Minor	Front Windscreen damaged but not adversely affecting driver's view Chip in Zone 'A' (3.2 (a) (i))
Advice (d) (i))	Nearside Front Outer Tyre has a cut but not deep enough to reach the ply or cords Sidewall (5.2.3

MOT #1	2020-03-18 17:38
MOT test number	898417089925
Result	✓ Passed
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	



Tax & MOT check

✓ Taxed Tax due: 1 October 2024	MOT Expires: 20 October 2024
Tax status	Valid until 1 October
Days left	156
MOT expiry date	20 October 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-





Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

-
AMP
- A

Extra MINI salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 10.200





Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

And a second sec	

	More info >
Plate changes	
See in this check if this MINI had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	
	More info >





Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2017-03-14
Last registration	2023-10-03
Complete history	See info



Registration #1	2017-03-14	14 mi
Registration #2	2020-03-18	24.093 mi
Registration #3	2021-03-18	28.209 mi
Registration #4		11.777 esi
Registration #5		11.777 mi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #8		11.117 est





Car features

S0225	Air conditioning
\$0295	
50482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	90%
Children	68%
Pedestrian	68%
Safety systems	67%
Overall rating	77%
Video	see crash video



Dimensions & weight	
Width	1800 mm
Height	1441 mm
Length	4253 mm
Wheel base	2670 mm
Kerb weight	1395 kg
Max. allowed weight	1890 kg
Additional information	
Fuel tank capacity	48
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/11

Number of axles	2
Engine number	F683H501