





General information

Make	MAZDA
Model	3 SE NAV
Colour	Blue
Year of manufacture	2018
Top speed	129 mph
0 - 60 mph	9.5 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	143 BHP
Max. torque	210 Nm at 4.000 rpm
Engine capacity	1.998 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.8 mpg
Consumption extra urban	61.4 mpg
Consumption combined	51.4 mpg
CO2 emission	129 g/km
CO2 label	D








Internet history

Entry 2		
Date	2021-08-11	
Pictures	31	
Listing price	View report	



source: heycar.co.uk

Entry 1	
Date	2021-07-08
Pictures	12
Listing price	View report



source: cargurus.co.uk









MOT history

MOT expiry date	2024-08-26
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	16
Total items failed	0

MOT #5	2023-08-15 10:33
MOT test number	999090687786
Result	✓ Passed
Next expiry date	2024-08-26
Advice Rear pads geting lowv	

MOT #4		2022-08-18 08:57
MOT test	number	945664309516
Result		✓ Passed
Advice	Nearside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	
Advice	Front Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))	

MOT #3	2021-08-27 14:43
MOT test number	422762737127
Result	✓ Passed



	HK67XOS report date: 2024-03-29	
MOT #2	2021-08-26 11:39	
MOT test number	150154246499	
Result	🗙 Failed	
Advice Nearside Rear Nail in tyre		
MAJOR Nearside Front Headlamp aim too low (4.1.2 (a))		
DANGEROUS Nearside Front Inner Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))		
Minor Nearside Rear Tyre obviously under inflated (5.2.3 (I))		
Advice Offside Rear Nail in tyre		
MAJOR Offside Front Headlamp aim too low (4.1.2 (a))		

DANGEROUS Nearside Front Outer Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

Minor Offside Rear Tyre obviously under inflated (5.2.3 (I))

MOT #1		2020-11-03 13:17
MOT test	number	713817414916
Result		✓ Passed
Advice	Advice Nearside Front Tyre slightly damaged/cracking or perishing outer sidewall (5.2.3 (d) (ii))	
Advice Nearside Front Tyre has a cut but not deep enough to reach the ply or cords inner sidewall (5.2.3 (d) (i))		nner sidewall (5.2.3
Advice	Offside Front Tyre slightly damaged/cracking or perishing outer sidewall (5.2.3	3 (d) (ii))



Tax & MOT check

Tax due: 1 August 2024	✓ Taxed	Expires: 26 August 2024	✓ МОТ
Tax status			Valid until 1 August
Days left			95
MOT expiry date			26 August 2024
Full MOT history			See MOT history
Tax calculation			

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-





Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	4. ALANPE
Туре	
Damage 2	AMPL
Damage 2	E CUT-S
Date	14 N
Category	AMP
Туре	

Extra MAZDA salvage check

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.





Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	4 10.000
Auction value	4 10.000
Average private trade value	4 =





Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report <u>here</u>.

NUMBER OF TAXABLE PARTY	

	More info >
Plate changes	
See in this check if this MAZDA had different number plates.	
Number of plates	,
Carrent registration	
Plate since	
Carrent registration	
Plate since	





Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MAZDA is financed.


Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	





Mileage check

Odometer	In miles
Mileage registrations	8
First mileage registration	2018-01-16
Last registration	2023-08-15
Complete history	See info



Registration #1	2018-01-16	21 mi
Registration #2	2020-11-03	16.877 mi
Registration #3		11.777 mi
Registration #4		11.777 esi
Registration #5		11.777 mi
Registration #6		11.777 esi
Registration #7		11.777 mi
Registration #8		11.117 esi





Safety ratings

NCAP rating	****
Adult	92%
Children	77%
Pedestrian	66%
Safety systems	81%
Overall rating	83%
Video	<u>see crash video</u>



Dimensions & weight	
Width	1840 mm
Height	1450 mm
Length	4870 mm
Wheel base	2830 mm
Kerb weight	1300 kg
Max. allowed weight	1935 kg
Additional information	
Additional information Fuel tank capacity	62 l
	62 l Direct Injection
Fuel tank capacity	
Fuel tank capacity Fuel delivery	Direct Injection
Fuel tank capacity Fuel delivery Number of doors	Direct Injection 4