



HYUNDAI



report date: 2024-03-29

General information

Make	HYUNDAI
Model	IX35 CRDI PREMIUM
Colour	Black
Year of manufacture	2011
Top speed	108 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	114 BHP
Max. torque	260 Nm at 2.750 rpm
Engine capacity	1.685 cc
Cylinders	4
Fuel type	Diesel
Consumption city	44.8 mpg
Consumption extra urban	58.9 mpg
Consumption combined	48.7 mpg
CO2 emission	139 g/km
CO2 label	E





Internet history

Entry 1

Date	2021-01-31
Pictures	1
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2025-01-16
MOT pass rate	83 %
MOT passed	10
Failed MOT tests	2
Total advice items	10
Total items failed	9

MOT #12	2024-01-17 14:08
MOT test number	776234054611
Result	✓ Passed
Next expiry date	2025-01-16

MOT #11	2024-01-10 12:17
MOT test number	819771883080
Result	✗ Failed
Fail	Offside Rear Lower Suspension arm corroded and seriously weakened (5.3.3 (b) (i))
Fail	Fuel tank leaking (6.1.3 (b) (i))
Fail	Nearside Reversing lamp inoperative (4.6.1 (a))
Fail	Offside Rear Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))
Fail	Offside Front Suspension arm ball joint excessively worn (5.3.4 (a) (i))
Fail	Offside Front Anti-roll bar linkage ball joint excessively worn (5.3.4 (a) (i))

**MOT #10** 2022-11-26 15:38**MOT test number** 199845148434**Result** ✓ Passed**Advice** Offside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Minor** Nearside Front Outer Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))**Advice** Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**MOT #9** 2021-12-10 16:24**MOT test number** 976971063521**Result** ✓ Passed**MOT #8** 2020-11-04 17:05**MOT test number** 119166476575**Result** ✓ Passed**MOT #7** 2020-11-03 16:15**MOT test number** 504153028756**Result** ✗ Failed**Advice** Nearside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Offside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))**Fail** Offside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))**Advice** Offside Front Service brake fluctuating, but not excessively (1.2.1 (e))**Advice** Nearside Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Fail** Nearside Rear Brake disc significantly and obviously worn (1.1.14 (a) (i))



<b>MOT #6</b>	2019-09-07 09:04
<b>MOT test number</b>	196729004112
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Rear Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))

  

<b>MOT #5</b>	2018-09-08 11:38
<b>MOT test number</b>	553866272240
<b>Result</b>	✓ Passed
<b>Advice</b>	Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))
<b>Advice</b>	Nearside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

  

<b>MOT #4</b>	2017-09-14 12:33
<b>MOT test number</b>	570279164142
<b>Result</b>	✓ Passed

  

<b>MOT #3</b>	2016-09-10 07:46
<b>MOT test number</b>	700417219159
<b>Result</b>	✓ Passed

  

<b>MOT #2</b>	2015-09-05 07:59
<b>MOT test number</b>	902827596378
<b>Result</b>	✓ Passed

  

<b>MOT #1</b>	2014-09-16 14:19
<b>MOT test number</b>	356799154414
<b>Result</b>	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 March 2025

✓  
**MOT**  
**Expires:**  
16 January 2025

<b>Tax status</b>	Valid until 1 March
<b>Days left</b>	305
<b>MOT expiry date</b>	16 January 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	49
<b>Band</b>	E
<b>Single payment (12 months)</b>	£ 180,00,-
<b>Single six month payment</b>	£ 99,00,-
<b>Total payable by 12 monthly instalments</b>	£ 189,00,-



Damage history

Check the damage history for this HYUNDAI. See if, where and when this HYUNDAI had damage and the car repair costs. We also check if this HYUNDAI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HYUNDAI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HYUNDAI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this HYUNDAI? How many owners did this HYUNDAI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this HYUNDAI had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-29
Current registration	 
Plate since	2024-03-29

More info >



Finance check

Check if this HYUNDAI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HYUNDAI has been settled.

If not, and you buy this HYUNDAI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HYUNDAI is financed.

Finance company	XXXXXXXX XX
Date of agreement	XXXXXXXX XX
Agreement type	XXXXXXXX XX
Agreement term	XXXXXXXX XX
Agreement number	XXXXXXXX XX
Contact info	XXXXXXXX XX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2011-09-17
Last registration	2024-01-17
Complete history	<a href="#">See info</a>



Registration #1	2011-09-17	8 mi
Registration #2	2014-09-16	26.134 mi
Registration #3	2015-09-05	31.543 mi
Registration #4	2016-09-10	36.580 mi
Registration #5	2017-09-14	43.385 mi
Registration #6	2018-09-08	50.053 mi
Registration #7	2019-09-07	56.086 mi
Registration #8	2020-09-07	62.119 mi
Registration #9	2021-09-07	68.152 mi
Registration #10	2022-09-07	74.185 mi
Registration #11	2023-09-07	80.218 mi
Registration #12	2024-01-17	86.251 mi
Registration #13		
Registration #14		

More info >



Car features

The HYUNDAI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete HYUNDAI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	90%
Children	88%
Pedestrian	54%
Safety systems	71%
Overall rating	81%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1820 mm
Height	1670 mm
Length	4410 mm
Wheel base	2640 mm
Kerb weight	1537 kg
Max. allowed weight	1940 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	D4FDBZ048158