



report date: 2024-03-29

General information

Make	SUZUKI
Model	ALTO SZ
Colour	Red
Year of manufacture	2015
Top speed	96 mph
0 - 60 mph	13.5 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	67 BHP
Max. torque	90 Nm at 3.400 rpm
Engine capacity	996 cc
Cylinders	3
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	74.3 mpg
Consumption combined	64.2 mpg
CO2 emission	99 g/km
CO2 label	A








Internet history

Entry 2

Date	2021-02-01
Pictures	37
Listing price	View report



source: yesauto.com

Entry 1

Date	2021-01-21
Pictures	37
Listing price	View report



source: yesauto.com



MOT history

MOT expiry date	2025-01-25
MOT pass rate	100 %
MOT passed	7
Failed MOT tests	0
Total advice items	13
Total items failed	0

MOT #7	2024-01-19 11:03
MOT test number	812898888499
Result	✓ Passed
Next expiry date	2025-01-25

MOT #6	2023-01-20 15:25
MOT test number	666094594007
Result	✓ Passed

- Advice** Offside Front Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
- Advice** Offside Front Tyre slightly damaged/cracking or perishing starting to perish (5.2.3 (d) (ii))
- Advice** Front Suspension arm pin or bush worn but not resulting in excessive movement both lower arm bushes perishing (5.3.4 (a) (i))
- Minor** Offside Front Windscreen wiper blade defective still clearing screen (3.4 (b) (i))
- Advice** Offside Rear Tyre slightly damaged/cracking or perishing perished (5.2.3 (d) (ii))
- Advice** Both front inner cv joints weeping past clip slightly

**MOT #5** 2022-01-25 12:10**MOT test number** 996257577559**Result** ✓ Passed**Advice** Offside Front Tyre slightly damaged/cracking or perishing Slight damage to outer wall (5.2.3 (d) (ii))**Advice** Offside Front Lower Suspension arm rear bush starting to split**Advice** Offside Rear Tyre slightly damaged/cracking or perishing Badly cracking on outer edge (5.2.3 (d) (ii))**Advice** Offside Front Inner Slight leak of grease from boot clip**MOT #4** 2021-01-26 16:06**MOT test number** 641308801306**Result** ✓ Passed**MOT #3** 2020-03-12 15:40**MOT test number** 689164434119**Result** ✓ Passed**Advice** Nearside Rear Outer Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Advice** Offside Front Wheel bearing slightly noisy (5.1.3 (b) (i))**MOT #2** 2019-03-08 14:27**MOT test number** 558099961709**Result** ✓ Passed**MOT #1** 2018-03-13 11:48**MOT test number** 894115225519**Result** ✓ Passed**Advice** Both sides front tyres have aging cracks on outer shoulders



Tax & MOT check

✓
Taxed
Tax due:
1 February 2025

✓
MOT
Expires:
25 January 2025

Tax status	Valid until 1 February
Days left	278
MOT expiry date	25 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	A
Single payment (12 months)	£ 0,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	Not applicable



Damage history

Check the damage history for this SUZUKI. See if, where and when this SUZUKI had damage and the car repair costs. We also check if this SUZUKI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra SUZUKI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this SUZUKI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,200
Auction value	£ 15,200
Average private trade value	£ 15,200

More info >



Owner history

For how long did the current and previous owner(s) have this SUZUKI? How many owners did this SUZUKI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To
Owner	From	To

More info >

Plate changes

See in this check if this SUZUKI had different number plates.

Number of plates	1
Current registration	 
Plate since	2024-03-29
Current registration	 
Plate since	2024-03-29

More info >



Finance check

Check if this SUZUKI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this SUZUKI has been settled.

If not, and you buy this SUZUKI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this SUZUKI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	10
First mileage registration	2015-03-26
Last registration	2024-01-19
Complete history	See info



Registration #1	2015-03-26	24 mi
Registration #2	2018-03-13	6.734 mi
Registration #3	2019-03-08	9.341 mi
Registration #4	2020-03-12	11.983 mi
Registration #5	2020-03-26	15.277 mi
Registration #6	2020-03-26	15.277 mi
Registration #7	2020-03-26	15.277 mi
Registration #8	2020-03-26	15.277 mi
Registration #9	2020-03-26	15.277 mi
Registration #10	2020-03-26	15.277 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Adult	55%
Children	46%
Pedestrian	35%
Safety systems	29%
Overall rating	47%
Video	see crash video



Dimensions & weight

Width	1600 mm
Height	1470 mm
Length	3500 mm
Wheel base	2360 mm
Max. allowed weight	1250 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4
Number of axles	2
Engine number	K10BN 1757182