





report date: 2024-03-28

General information

Make	PEUGEOT
Model	HORIZON HDI TEPEE S
Colour	Bronze
Year of manufacture	2014
Top speed	103 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	92 BHP
Max. torque	230 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	46.3 mpg
Consumption extra urban	61.4 mpg
Consumption combined	54.3 mpg
CO2 emission	135 g/km
CO2 label	E



CarCheck.co.uk page 1/11



report date: 2024-03-28

Internet history

Entry 1

Date 2022-01-15

Pictures 11

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

B 4	\sim $-$		
10.71	$^{\prime}$	hic	tory
101	C I	1115	I OI V
	•		,

MOT expiry date	2025-04-22
MOT pass rate	89 %
MOT passed	8
Failed MOT tests	1
Total advice items	8
Total items failed	1

MOT #9	2024-04-23 08:46
MOT test number	355466602425
Result	✓ Passed
Next expiry date	2025-04-22

MOT #8		2023-05-22 13:52
MOT test number		290349477278
Result		✓ Passed
Advice Offside R	ear Coil spring corroded (5.3.1 (b) (i))	
Advice Nearside	Rear Coil spring corroded (5.3.1 (b) (i))	

MOT #7	2022-05-24 14:28
MOT test number	879252582675
Recult	/ Passed

MOT #6	2022-05-24 14:28

MOT test number 406525483902

Result X Failed

Pass with rectification Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #5 2021-05-28 11:41 837113994100 **MOT** test number Result ✓ Passed **MOT #4** 2020-08-17 10:50 **MOT** test number 379144635761 Result ✓ Passed **Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Nearside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Offside Front Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #3

MOT test number

786561066056

Result

Advice Rear Exhaust mounting defective (6.1.2 (a))

MOT test number

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

 MOT #1
 2017-10-12 13:14

 MOT test number
 854411497838

 Result
 ✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-28

Tax & MOT check

Tax expired: 10 April 2024





Expires: 22 April 2025

Tax status	Expired at 10 April 2024
Days left	20 days too late
MOT expiry date	22 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-

CarCheck.co.uk page 5/11



report date: 2024-03-28

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

Owner matery	
For how long did the current and previous owner(s) have this PEUGEOT? How many owner have? Check it in the premium report and see all owner registrations. Download the full is	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	NE NE
Plate since	
Current registration	IIK SIN
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2014-10-17
Last registration	2024-04-23
Complete history	See info



Registration #1	2014-10-17	17 mi
Registration #2	2017-10-12	16.225 mi
Registration #3	2018-10-12	19.455 mi
Registration #4	2019-09-09	21.363 mi
Registration #5	2020-08-17	22.785 mi
Registration #6	2021-05-28	23.588 mi
Registration #7		11.777 es
Registration #8		11.177 es
Registration #9		11.177 mi
Registration #10		11.777 es
Registration #11		9.777 sc

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-28

Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
S0567	
50569	

Safety ratings

NCAP rating	****
Adult	73%
Children	78%
Pedestrian	48%
Safety systems	86%
Overall rating	70%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1803 mm
Length	4380 mm
Wheel base	2728 mm
Kerb weight	1601 kg
Max. allowed weight	2040 kg

Additional information

Fuel tank capacity	60 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/1

Number of axles 2

Engine number JBEM0319986