



report date: 2024-03-28

General information

Make	VAUXHALL
Model	AGILA S
Colour	Blue
Year of manufacture	2012
Top speed	109 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	93 BHP
Max. torque	118 Nm at 4.800 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	46.3 mpg
Consumption extra urban	62.8 mpg
Consumption combined	55.4 mpg
CO2 emission	119 g/km
CO2 label	C





MOT history

MOT expiry date	2025-03-23
MOT pass rate	69 %
MOT passed	9
Failed MOT tests	4
Total advice items	16
Total items failed	9

MOT #13	2024-03-23 12:01
MOT test number	682600305068
Result	✓ Passed
Next expiry date	2025-03-23
Advice	Offside Front Drive shaft damaged but serviceable (6.1.7 (e))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Brake pipe corroded, covered in grease or other material all (1.1.11 (c))

MOT #12	2024-03-23 12:01
MOT test number	954853369969
Result	✗ Failed
Advice	Offside Front Drive shaft damaged but serviceable (6.1.7 (e))
Pass with rectification	Nearside Front Headlamp not working on main beam (4.1.1 (a) (ii))
Advice	Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))
Minor	Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i))
Advice	Brake pipe corroded, covered in grease or other material all (1.1.11 (c))

**MOT #11** 2023-03-18 11:31**MOT test number** 611223111020**Result** ✓ Passed**MOT #10** 2022-03-21 15:19**MOT test number** 511525453885**Result** ✓ Passed**Advice** Brake pipe corroded, covered in grease or other material nsf, osf and osr (1.1.11 (c))**MOT #9** 2022-03-18 11:15**MOT test number** 245225798910**Result** ✗ Failed**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Brake pipe corroded, covered in grease or other material nsf, osf and osr (1.1.11 (c))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Fail** Nearside Headlamp not working on main beam (4.1.1 (a) (ii))**MOT #8** 2021-03-24 13:58**MOT test number** 197663128630**Result** ✓ Passed

**MOT #7** 2021-01-12 14:00**MOT test number** 910292535345**Result** ✗ Failed**Fail** Offside Rear Brake pipe excessively corroded (1.1.11 (c))**Advice** Front Brake pad(s) wearing thin (1.1.13 (a) (ii))**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Offside Front Coil spring fractured or broken (5.3.1 (b) (i))**Advice** Nearside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**Fail** Nearside Front Coil spring fractured or broken (5.3.1 (b) (i))**MOT #6** 2019-07-29 11:01**MOT test number** 723822959650**Result** ✓ Passed**MOT #5** 2018-07-23 15:19**MOT test number** 737568751733**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge 3mm - wearing from outer edge (5.2.3 (e))**Advice** Nearside Rear Nail in tyre**MOT #4** 2017-04-05 13:46**MOT test number** 940242382703**Result** ✓ Passed**MOT #3** 2016-01-19 13:14**MOT test number** 724758699456**Result** ✓ Passed



MOT #2	2016-01-19 13:14
MOT test number	799025195889
Result	✗ Failed
Pass with rectification	Offside Front Windscreen washer provides insufficient washer liquid (8.2.3)
Pass with rectification	Nearside Front Windscreen washer provides insufficient washer liquid (8.2.3)

MOT #1	2015-01-15 12:27
MOT test number	706365615070
Result	✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 November 2024

✓  
**MOT**  
**Expires:**  
23 March 2025

<b>Tax status</b>	Valid until 1 November
<b>Days left</b>	186
<b>MOT expiry date</b>	23 March 2025
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	C
<b>Single payment (12 months)</b>	£ 35,00,-
<b>Single six month payment</b>	Not applicable
<b>Total payable by 12 monthly instalments</b>	£ 36,75,-



Damage history

Check the damage history for this VAUXHALL. See if, where and when this VAUXHALL had damage and the car repair costs. We also check if this VAUXHALL was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	



Damage 2

Date	
Category	
Type	



Extra VAUXHALL salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VAUXHALL in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this VAUXHALL? How many owners did this VAUXHALL have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this VAUXHALL had different number plates.

Number of plates	1
Current registration	 <b>NX61SWO</b>
Plate since	2019-06-29
Current registration	 <b>NX61SWO</b>
Plate since	2019-06-29

More info >



Finance check

Check if this VAUXHALL is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VAUXHALL has been settled.

If not, and you buy this VAUXHALL then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VAUXHALL is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	14
First mileage registration	2012-01-20
Last registration	2024-03-23
Complete history	<a href="#">See info</a>



Registration #1	2012-01-20	25 mi
Registration #2	2015-01-15	17.375 mi
Registration #3	2016-01-19	21.159 mi
Registration #4	2016-01-19	21.159 mi
Registration #5	2017-04-05	23.528 mi
Registration #6	2018-07-23	31.096 mi
Registration #7	2019-07-29	38.048 mi
Registration #8	2020-03-23	45.000 mi
Registration #9	2021-03-23	52.000 mi
Registration #10	2022-03-23	59.000 mi
Registration #11	2023-03-23	66.000 mi
Registration #12	2024-03-23	73.000 mi
Registration #13	2025-03-23	80.000 mi
Registration #14	2026-03-23	87.000 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1932 mm
Height	1590 mm
Length	3740 mm
Wheel base	2360 mm
Kerb weight	990 kg
Max. allowed weight	1485 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Number of axles	2
Engine number	1416399