



Mercedes-Benz




report date: 2024-03-29

General information

Make	MERCEDES
Model	SLK 230 KOMPRESSOR SPECIAL EDITION
Colour	Black
Year of manufacture	2004
Top speed	147 mph
0 - 60 mph	7.3 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	197 BHP
Max. torque	279 Nm at 2.500 rpm
Engine capacity	2.295 cc
Cylinders	4
Fuel type	Petrol
Consumption city	19.5 mpg
Consumption extra urban	39.8 mpg
Consumption combined	28.8 mpg
CO2 emission	226 g/km
CO2 label	L





Internet history

Entry 1

Date	2021-09-03
Pictures	10
Listing price	View report



source: [autotrader.co.uk](https://www.autotrader.co.uk)



MOT history

MOT expiry date	2024-07-09
MOT pass rate	71 %
MOT passed	17
Failed MOT tests	7
Total advice items	46
Total items failed	16

MOT #24	2023-07-10 14:34
MOT test number	401189592447
Result	✓ Passed
Next expiry date	2024-07-09
Advice	Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
Advice	Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))

**MOT #23**

2023-06-28 13:46

MOT test number

494120046059

Result**✗ Failed**

- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge right on limit 1.6 (5.2.3 (e))
- Fail** Nearside Front Position lamp not working (4.2.1 (a) (ii))
- Fail** Nearside Track rod end ball joint dust cover insecure so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))
- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Fail** Driver's seat fore and aft adjustment mechanism not functioning as intended. (6.2.5 (b) (i))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge right on limit 1.6 (5.2.3 (e))
- Advice** Nearside Front Wheel bearing has slight play (5.1.3 (a) (i))
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #22

2022-06-21 10:49

MOT test number

152380279049

Result**✓ Passed**

- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))
- Advice** Nearside trackrod end rubber perished
- Advice** Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #21** 2021-06-29 16:00**MOT test number** 584047967512**Result** ✓ Passed**Advice** Centre exhaust box slightly corroded**Minor** Nearside Front Track rod end ball joint dust cover damaged or deteriorated, but preventing the ingress of dirt (2.1.3 (g) (i))**MOT #20** 2020-10-26 16:14**MOT test number** 152756773153**Result** ✓ Passed**Advice** Items removed from driver's view prior to test**MOT #19** 2020-10-22 13:01**MOT test number** 413803916779**Result** ✗ Failed**Fail** Engine MIL inoperative or indicates a malfunction (8.2.1.2 (h))**Advice** Nearside Front jacking bung missing**Advice** Items removed from driver's view prior to test**Fail** Offside Track rod end ball joint dust cover excessively damaged or deteriorated so that it no longer prevents the ingress of dirt (2.1.3 (g) (ii))**MOT #18** 2019-10-28 16:33**MOT test number** 288873118529**Result** ✓ Passed

**MOT #17** 2019-10-23 14:25**MOT test number** 590451117528**Result** ✗ Failed

- Fail** Electronic stability control warning lamp indicates a fault (7.12 (e))
- Fail** Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Anti-lock braking system warning lamp indicates an ABS fault (1.6 (b))
- Fail** Rear fog lamp not working (4.5.1 (a) (ii))
- Fail** Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MOT #16 2018-10-25 14:24**MOT test number** 881209504272**Result** ✓ Passed

- Advice** Wiper blades smearing
- Advice** Rear Prop shaft flexible coupling slightly deteriorated (6.1.7 (d) (i))

MOT #15 2018-10-25 11:20**MOT test number** 336274606751**Result** ✗ Failed

- Pass with rectification** Offside Rear Rear fog lamp not working (4.5.1 (a) (ii))
- Advice** Rear Prop shaft flexible coupling slightly deteriorated (6.1.7 (d) (i))
- Fail** Nearside Front Lower Suspension arm ball joint excessively worn (5.3.4 (a) (i))
- Advice** Wiper blades smearing

**MOT #14** 2017-10-25 12:10**MOT test number** 195908204879**Result** ✓ Passed**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Advice** Wiper blades smearing**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Rear exhaust section slightly deteriorated**MOT #13** 2017-10-24 10:32**MOT test number** 320231371778**Result** ✗ Failed**Advice** Wiper blades smearing**Advice** Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Advice** Nearside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Advice** Rear exhaust section slightly deteriorated**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)**Fail** Offside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)**MOT #12** 2016-10-20 09:33**MOT test number** 848439318286**Result** ✓ Passed**Advice** Rear Direction indicators has light sources not illuminating, but not more than 50% (1.4.A.2c)**Advice** Offside Headlamp damaged but light output not reduced (1.7.5a)**Advice** Front Direction indicators slightly discoloured (1.4.A.2f)**Advice** Nearside Headlamp deteriorated but light output not reduced (1.7.5a)

**MOT #11** 2015-10-29 13:38**MOT test number** 506064254631**Result** ✓ Passed**Advice** Offside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**MOT #10** 2015-10-29 09:25**MOT test number** 653124932940**Result** ✗ Failed**Fail** Nearside Stop lamp not working (1.2.1b)**Advice** Offside Rear Brake pad(s) wearing thin (3.5.1g)**Advice** Offside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)**Fail** Offside Stop lamp not working (1.2.1b)**Advice** Front Brake pad(s) wearing thin (3.5.1g)**MOT #9** 2014-10-07 12:46**MOT test number** 446080484242**Result** ✓ Passed**MOT #8** 2013-10-17 14:06**MOT test number** 957090093280**Result** ✓ Passed**Advice** Rear Brake pad(s) wearing thin (3.5.1g)**MOT #7** 2012-10-30 15:47**MOT test number** 698534302325**Result** ✓ Passed

**MOT #6** 2011-10-24 14:49**MOT test number** 827187191251**Result** ✓ Passed**MOT #5** 2010-10-19 10:47**MOT test number** 362362890403**Result** ✓ Passed**Advice** Offside Front Lower Ball joint has slight play (2.2.B.1f)**MOT #4** 2010-10-18 15:47**MOT test number** 690371290249**Result** ✗ Failed**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)**Fail** Offside Rear Tyre has ply or cords exposed (4.1.D.1b)**Advice** Offside Front Lower Ball joint has slight play (2.2.B.1f)**MOT #3** 2009-10-21 12:55**MOT test number** 562574299209**Result** ✓ Passed**MOT #2** 2008-10-20 11:33**MOT test number** 211484198200**Result** ✓ Passed**MOT #1** 2007-10-25 12:18**MOT test number** 733508297264**Result** ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
9 July 2024

Tax status	Valid until 1 April
Days left	336
MOT expiry date	9 July 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-



Damage history

Check the damage history for this MERCEDES. See if, where and when this MERCEDES had damage and the car repair costs. We also check if this MERCEDES was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MERCEDES salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MERCEDES in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this MERCEDES? How many owners did this MERCEDES have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this MERCEDES had different number plates.

Number of plates	7
Current registration	 
Plate since	2024-03-29
Current registration	 
Plate since	2024-03-29

More info >



Finance check

Check if this MERCEDES is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MERCEDES has been settled.

If not, and you buy this MERCEDES then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MERCEDES is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	26
First mileage registration	2004-03-04
Last registration	2023-07-10
Complete history	See info



Registration #1	2004-03-04	21 mi
Registration #2	2007-10-25	20.029 mi
Registration #3	2008-10-20	24.723 mi
Registration #4	2009-10-21	28.471 mi
Registration #5	2010-10-18	31.917 mi
Registration #6	2010-10-19	31.930 mi
Registration #7	2011-10-24	35.450 mi
Registration #8	2012-10-30	36.788 mi
Registration #9	2013-10-17	38.041 mi
Registration #10	2014-10-07	39.404 mi
Registration #11	2015-10-29	45.872 mi
Registration #12	2015-10-29	45.874 mi
Registration #13	2016-10-20	55.333 mi
Registration #14	2016-10-20	55.333 mi
Registration #15	2016-10-20	55.333 mi
Registration #16	2016-10-20	55.333 mi
Registration #17	2016-10-20	55.333 mi
Registration #18	2016-10-20	55.333 mi
Registration #19	2016-10-20	55.333 mi
Registration #20	2016-10-20	55.333 mi
Registration #21	2016-10-20	55.333 mi
Registration #22	2016-10-20	55.333 mi
Registration #23	2016-10-20	55.333 mi
Registration #24	2016-10-20	55.333 mi
Registration #25	2016-10-20	55.333 mi
Registration #26	2016-10-20	55.333 mi

More info >



Dimensions & weight

Width	1715 mm
Height	1281 mm
Length	4010 mm
Wheel base	2400 mm
Kerb weight	1385 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	2
Number of axles	2
Engine number	11198340087137