





report date: 2024-03-29

General information

Make	VOLKSWAGEN
Model	SCIROCCO GT TSI BLUEMOTION TECHNOLOGY
Colour	White
Year of manufacture	2016
Top speed	126 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	92 kW / 125 HP / 123 BHP
Max. torque	280 Nm at 1.400 rpm
Engine capacity	1.395 cc
Cylinders	4
Fuel type	Petrol
Consumption city	41.5 mpg
Consumption extra urban	62.8 mpg
Consumption combined	52.3 mpg
CO2 emission	125 g/km
CO2 label	D



CarCheck.co.uk page 1/13



report date: 2024-03-29

Internet history

Entry 1

Date 2021-11-23

Pictures 5

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/13



report date: 2024-03-29

MOT history

MOT expiry date	2025-04-23
MOT pass rate	64 %
MOT passed	7
Failed MOT tests	4
Total advice items	26
Total items failed	2

MOT #11		2024-04-24 15:23
MOT test	number	437338342645
Result		✓ Passed
Next expi	ry date	2025-04-23
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Nearside Front Lower Suspension arm ball joint has slight play outer (5.3.4 (a) (i))
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Undertrays fitted	

CarCheck.co.uk page 3/13



report date: 2024-03-29

MOT #10 2024-04-18 09:29

MOT test number 551348179443

Result X Failed

MAJOR Headlamp levelling device inoperative (4.1.5 (a))

DANGEROUS Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MAJOR Tyre pressure monitoring system malfunctioning or obviously inoperative (5.2.3 (h))

Advice Nearside Front Lower Suspension arm ball joint has slight play outer (5.3.4 (a) (i))

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Undertrays fitted

(e))

MOT #9 2023-02-16 16:05

MOT test number 896945365010

Result

Passed

MOT #8 2023-02-15 16:39

MOT test number 462291693886

Result ★ Failed

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MAJOR Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge on tread markers advise to change (5.2.3

Advice Offside Front Outer Brake pad(s) wearing thin (1.1.13 (a) (ii))

MAJOR Nearside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

MAJOR Nearside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

CarCheck.co.uk page 4/13



report date: 2024-03-29

MOT #7 2022-01-13 10:02

MOT test number 386426895508

MOT #6 2021-08-16 12:20

MOT test number 290190410534

Result
✓ Passed

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Nearside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

MOT #5 2020-08-17 08:29

MOT test number 284235202330

Result ✓ Passed

MOT #4 2020-08-14 10:55

MOT test number 287014393845

Result X Failed

DANGEROUS Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

MOT #3 2019-08-17 08:41

MOT test number 446714762652

Result ✓ Passed

MOT #2 2019-01-16 13:54

MOT test number 941141504423

Result

Passed

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

CarCheck.co.uk page 5/13



report date: 2024-03-29

MOT test number

418065234427

Result

Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification Offside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Pass with rectification Nearside Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))

CarCheck.co.uk page 6/13





report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	23 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	D
Single payment (12 months)	£ 150,00,-
Single six month payment	£ 82,50,-
Total payable by 12 monthly instalments	£ 157,50,-

CarCheck.co.uk page 7/13



report date: 2024-03-29

Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

Damage 1

Date

Category

Type

Damage 2

Date

Category

Type



Extra VOLKSWAGEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 8/13



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 9/13



report date: 2024-03-29

More info >

Owner history

For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	

THE REAL PROPERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY ADDRESS OF THE PERTY ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY AND ADDRESS OF THE PERTY	

	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	
Current registration	IK SIN
Plate since	
Current registration	IIK SIE
Plate since	

CarCheck.co.uk page 10/13



report date: 2024-03-29

Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 11/13



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2016-02-20
Last registration	2024-04-24
Complete history	See info



Registration #1	2016-02-20	6 mi
Registration #2	2019-01-16	6.047 mi
Registration #3	2019-01-16	6.047 mi
Registration #4	2019-08-17	6.144 mi
Registration #5	2020-08-14	14.380 mi
Registration #6	2020-08-17	14.445 mi
Registration #7	2021-08-16	24.310 mi
Registration #8		11.777 es
Registration #9		11.177 mi
Registration #10		11.777 es
Registration #11		9.777 es
Registration #12		11.777 es
Registration #13		10.317 au

More info >

CarCheck.co.uk page 12/13



WU65VUM
report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Adult	87%
Children	73%
Pedestrian	53%
Safety systems	71%
Overall rating	76%
Video	see crash video



Dimensions & weight

Width	1810 mm
Height	1404 mm
Length	4256 mm
Wheel base	2578 mm
Kerb weight	1318 kg
Max. allowed weight	1680 kg

Additional information

Fuel tank capacity	55 I
Fuel delivery	Direct Injection
Number of doors	3
CarChack caluk	nago 12/13

CarCheck.co.uk page 13/13

Number of seats	4
Number of axles	2
Engine number	CZCA619609