





report date: 2024-03-29

General information

Make	MINI
Model	MINI (R60) ONE D
Colour	Red
Year of manufacture	2011
Top speed	106 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	90 BHP
Max. torque	215 Nm at 1.750 rpm
Engine capacity	1.600 cc
Cylinders	4
Fuel type	Diesel
Consumption city	60.1 mpg
Consumption extra urban	67.3 mpg
Consumption combined	64.2 mpg
CO2 emission	115 g/km
CO2 label	С



CarCheck.co.uk page 1/12



report date: 2024-03-29

Internet history

Entry 4

Date 2023-01-18

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 3

Date 2022-07-05	
-----------------	--

Pictures 12

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 2

Date	2021-07-09

Pictures 1

Listing price <u>View report</u>



source: cargurus.co.uk

Entry 1

Date CarCheck.c	o.uk 2021-07-08	page 2/12
car criccic.c	Oluk	page 2/12

Pictures 1

Listing price <u>View report</u>



source: autotrader.co.uk



HN61LWG
report date: 2024-03-29

MOT history

MOT expiry date	2025-03-08
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	12
Total items failed	3

MOT #13		2024-02-26 17:25
MOT test	number	483611328725
Result		✓ Passed
Next expi	ry date	2025-03-08
Advice	Nearside Front Tyre worn close to legal limit/worn on edge outer edge (5.2.3 (e))	
Advice	Nearside Rear Tyre worn close to legal limit/worn on edge inner edge (5.2.3 (e))	

MOT #12	2023-03-09 16:44
MOT test number	119188158125
Result	✓ Passed
MOT #11	2022-06-30 15:33
MOT test number	383766055607
Result	✓ Passed

MOT #10	2022-06-29 14:05

MOT test number 624664278508

Result × Failed

Result X Failed

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Fail Nearside Rear Anti-roll bar pin or bush excessively worn (5.3.4 (a) (i))

CarCheck.co.uk page 3/12



report date: 2024-03-29

MOT test number

850521525346

Result

Advice Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice Offside Front tyre wearing on outside edge

MOT #8 2021-10-04 14:00 790490360046 **MOT** test number Result × Failed **Advice** Offside Rear Anti-roll bar pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i)) Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii)) **Advice** Offside Front tyre wearing on outside edge Fail Brake lever has insufficient reserve travel (1.1.2 (a)) **Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

MOT #7

MOT test number

423546670272

Result

Advice Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

 MOT #6
 2019-11-05 09:28

 MOT test number
 424580614453

 Result
 ✓ Passed

CarCheck.co.uk page 4/12



MOT #3

Result

Result

MOT test number

HN61LWG

report date: 2024-03-29

2016-11-07 12:27

912008848608

✓ Passed

✓ Passed

MOT #5	2018-11-14 09:59
MOT test number	176161273002
Result	✓ Passed
MOT #4	2017-11-27 12:27
MOT test number	777320305127
Result	✓ Passed
Advice FRONT AND REAR INNER BRAKE PADS WORN THIN	

MOT #2	2015-11-17 10:18
MOT test number	409168615978
Result	✓ Passed
MOT #1	2014-11-24 09:17
MOT test number	919018824374

CarCheck.co.uk page 5/12



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 March
Days left	306
MOT expiry date	8 March 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

$\hat{}$	
Owner	history
OWITCE	ilistoi y

· · · · · · · · · · · · · · · · · · ·		
For how long did the current and previous owner(s) have this MINI? How many owners did check it in the premium report and see all owner registrations. Download the full report		e?

	More info	>
Plate changes		
See in this check if this MINI had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	UK UK	
Plate since		
	More info	>

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this MINI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	18
First mileage registration	2011-12-16
Last registration	2024-02-26
Complete history	See info



Registration #1	2011-12-16	16 mi
Registration #2	2014-11-24	21.790 mi
Registration #3	2015-11-17	28.857 mi
Registration #4	2016-11-07	35.420 mi
Registration #5	2017-11-27	41.383 mi
Registration #6	2018-11-14	47.079 mi
Registration #7	2019-11-05	53.019 mi
Registration #8	2020-11-02	57.061 mi
Registration #9		11.777 es
Registration #10		11.117 es
Registration #11		11.177 mi
Registration #12		11.777 es
Registration #13		11.177 mi
Registration #14		11.117 es
Registration #15		11.177 mi
Registration #16		11.117 es
Registration #17		11.177 es
Registration #18		13.777 es

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
0567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1789 mm
Height	1561 mm
Length	4097 mm
Wheel base	2595 mm
Kerb weight	1310 kg
Max. allowed weight	1820 kg

Additional information

Fuel tank capacity	47	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles 2

Engine number 71537878