





report date: 2024-03-28

#### General information

Make	AUDI
Model	A3 TDI E SPORT
Colour	Blue
Year of manufacture	2009
Top speed	120 mph
Gearbox	5 speed Manual

## Engine & fuel consumption

Power	104 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 сс
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	С



CarCheck.co.uk page 1/12



MOT history	Μ	OT	h	is	to	rv
-------------	---	----	---	----	----	----

MOT expiry date	2024-10-03
MOT pass rate	80 %
MOT passed	12
Failed MOT tests	3
Total advice items	27
Total items failed	11

MOT #15		2023-10-04 17:31
MOT test	number	443167439319
Result		✓ Passed
Next expi	ry date	2024-10-03
Advice	Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice (a) (i))	Nearside Front Suspension arm pin or bush worn but not resulting in exc	cessive movement (5.3.4
Advice	Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #14		2022-09-26 13:13
MOT test	number	704021504883
Result		✓ Passed
Advice	Nearside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))		

MOT #13		2021-09-07 14:06
MOT test	number	533200150586
Result		✓ Passed
Advice	Front Brake pad(s) wearing thin both sides (1.1.13 (a) (ii))	
Advice	Front Brake disc worn, but not excessively both sides (1.1.14 (a) (i))	

CarCheck.co.uk page 2/12



**MOT #12** 2020-10-03 11:01

**MOT test number** 515556955239

**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**Advice** Nearside Rear Direction indicator slightly discoloured (4.4.3 (a))

Advice Offside Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

**Advice** Offside Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))

**MOT #11** 2019-11-25 10:39

MOT test number 745991540901

**Result** 
✓ Passed

Advice Rear Brake disc worn, but not excessively (1.1.14 (a) (i))

**Advice** Offside Rear Service brake binding but not excessively (1.2.1 (f))

**MOT #10** 2018-11-05 16:17

**MOT test number** 132950793805

MOT #9 2018-10-30 13:34

**MOT test number** 762631474781

**Result** X Failed

Fail Offside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))

**Fail** Offside Obligatory mirror missing (3.3 (a))

**Fail** Nearside Headlamp aim too low (4.1.2 (a))

Fail Nearside Rear Tyre has a tear, caused by separation or partial failure of its structure (5.2.3 (d) (ii))

**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

CarCheck.co.uk page 3/12



Result

LR59YJJ

✓ Passed

report date: 2024-03-28

MOT #8 2017-11-27 17:29

**MOT test number** 755252105967

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

**Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #7** 2017-11-27 12:19

MOT test number 688539685866

Result X Failed

**Advice** Nearside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

Advice Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Fail** Nearside Front Inner Brake pad(s) insecure (3.5.1g)

**Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**Fail** Nearside Front Anti-roll bar linkage ball joint dust cover excessively damaged so that it no longer prevents the ingress of dirt (2.4.G.2)

**Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Advice Offside Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

**Fail** Offside Front Headlamp aim beam image obviously incorrect (1.8.A.1b)

**Fail** Nearside Front Inner Brake pad(s) less than 1.5 mm thick (3.5.1g)

**Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 4/12



**MOT** test number

LR59YJJ report date: 2024-03-28

MOT #6 2016-11-16 09:33 946183362505

Result ✓ Passed

MOT #5 2015-11-14 18:02

**MOT** test number 423517145039

Result ✓ Passed

MOT #4 2014-11-28 09:57

679592034397 **MOT test number** 

Result ✓ Passed

MOT #3 2014-11-27 11:41

**MOT** test number 389771734366

Result × Failed

Fail Nearside Front Headlamp not working on dipped beam (1.7.5a)

Fail Offside Rear Tyre has ply or cords exposed (4.1.D.1b)

**MOT #2** 2013-10-31 10:47

386894903350 **MOT** test number

Result ✓ Passed

**Advice** Offside Rear Tyre worn close to the legal limit (4.1.E.1)

**MOT #1** 2012-09-18 10:47

705322662267 **MOT** test number

Result Passed

**Notice** Under-trays fitted obscuring some underside components

CarCheck.co.uk page 5/12



## Tax & MOT check



Tax status	Valid until 1 April
Days left	338
MOT expiry date	3 October 2024
Full MOT history	See MOT history

#### Tax calculation

Vehicle class	49
Band	С
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-

CarCheck.co.uk page 6/12



#### Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report <a href="here">here</a> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



#### Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



#### Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 8/12



Owner	biotom,
UWNEI	nisioiv

For how long did the current and previous owner(s) have this AUDI? How many owners defined the premium report and see all owner registrations. Download the full report	
THE STATE OF THE S	
************	
*********	
THE STREET STREET	
	More info >
Plate changes	
See in this check if this AUDI had different number plates.	
Number of plates	
Current registration	NIE. AIS UK
Plate since	
Current registration	NK NK
Plate since	
	More info >

CarCheck.co.uk page 9/12



#### Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this AUDI is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 10/12



## Mileage check

Odometer	In miles
Mileage registrations	16
First mileage registration	2009-09-30
Last registration	2023-10-04
Complete history	See info



Registration #1	2009-09-30	21 mi
Registration #2	2012-09-18	53.103 mi
Registration #3	2013-10-31	64.882 mi
Registration #4	2014-11-27	77.545 mi
Registration #5	2014-11-28	77.545 mi
Registration #6	2015-11-14	89.299 mi
Registration #7	2016-11-16	102.403 mi
Registration #8	2017-11-27	116.200 mi
Registration #9		11.777 es
Registration #10		11.777 es
Registration #11		11.777 es
Registration #12		11.777 es
Registration #13		11.777 es
Registration #14		
		11.777 44
Registration #15		11,777 es

More info >

CarCheck.co.uk page 11/12



## Car features

S0225	Air conditioning
S0295	
50482	
50501	
50566	
50567	
50569	

# Safety ratings

NCAP rating	****
Video	see crash video



# Dimensions & weight

Width	1765 mm
Height	1423 mm
Length	4292 mm
Wheel base	2578 mm
Kerb weight	1320 kg
Max. allowed weight	1880 kg

## Additional information

Fuel tank capacity	55 l	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles 2

Engine number BLS B01113