



report date: 2024-03-29

General information

Make	VOLVO
Model	S60 D2 R-DESIGN
Colour	Gold
Year of manufacture	2011
Top speed	121 mph
0 - 60 mph	10.7 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	113 BHP
Max. torque	270 Nm at 1.750 rpm
Engine capacity	1.560 cc
Cylinders	4
Fuel type	Diesel
Consumption city	54.3 mpg
Consumption extra urban	74.3 mpg
Consumption combined	65.7 mpg
CO2 emission	114 g/km
CO2 label	C






Internet history

Entry 1

Date	2021-10-28
Pictures	25
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2024-12-28
MOT pass rate	78 %
MOT passed	7
Failed MOT tests	2
Total advice items	9
Total items failed	3

MOT #9	2023-12-28 12:48
MOT test number	401488190023
Result	✓ Passed
Next expiry date	2024-12-28

MOT #8	2022-12-14 17:37
MOT test number	510947310804
Result	✓ Passed
Advice	Fuel pipes cable tied to heat shield
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Outer edge (5.2.3 (e))

MOT #7	2022-12-14 13:13
MOT test number	154604357915
Result	✗ Failed
Fail	Nearside Front Seat belt buckle not functioning as intended Does not release under tension (7.1.2 (d))
Advice	Nearside Front Tyre worn close to legal limit/worn on edge Outer edge (5.2.3 (e))
Fail	Driver's view of the road through the swept area of the windscreen significantly affected by an obstruction Phone holder and pad stuck to screen (3.1 (a) (ii))

**MOT #6** 2021-12-16 09:43**MOT test number** 366224715806**Result** ✓ Passed**Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #5** 2020-12-29 16:25**MOT test number** 868324058783**Result** ✓ Passed**Advice** Offside Front Track rod end ball joint has slight play Track rod end outer slight play (2.1.3 (b) (i))**MOT #4** 2019-12-11 14:23**MOT test number** 171049595823**Result** ✓ Passed**Advice** Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**MOT #3** 2015-11-13 14:27**MOT test number** 712288244266**Result** ✓ Passed**MOT #2** 2015-11-11 13:22**MOT test number** 353230985422**Result** ✗ Failed**Advice** Nearside rear tyre wearing on outer edge**Fail** Nearside Front position lamp(s) not working (1.1.A.3b)



MOT #1	2014-10-01 09:28
MOT test number	827274374211
Result	✓ Passed
Advice	Offside Front Tyre worn close to the legal limit (4.1.E.1)
Advice	Nearside Front Tyre worn close to the legal limit (4.1.E.1)



Tax & MOT check

✓
Taxed
Tax due:
1 November 2024

✓
MOT
Expires:
28 December 2024

Tax status	Valid until 1 November
Days left	185
MOT expiry date	28 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,299
Auction value	£ 19,299
Average private trade value	£ 19,299

More info >



Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners did this VOLVO have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this VOLVO had different number plates.

Number of plates	1
Current registration	XXXXXX
Plate since	2024-03-29
Current registration	XXXXXX
Plate since	2024-03-29

More info >



Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this VOLVO is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	11
First mileage registration	2011-10-14
Last registration	2023-12-28
Complete history	See info



Registration #1	2011-10-14	8 mi
Registration #2	2014-10-01	38.133 mi
Registration #3	2015-11-11	55.141 mi
Registration #4	2015-11-13	55.145 mi
Registration #5	2019-12-11	98.596 mi
Registration #6	2020-12-29	103.875 mi
Registration #7	2023-12-28	103.875 mi
Registration #8	2023-12-28	103.875 mi
Registration #9	2023-12-28	103.875 mi
Registration #10	2023-12-28	103.875 mi
Registration #11	2023-12-28	103.875 mi

More info >



Car features

The VOLVO factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete VOLVO factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★★
Adult	91%
Children	78%
Pedestrian	26%
Safety systems	71%
Overall rating	73%
Video	see crash video



Dimensions & weight

Width	1782 mm
Height	1447 mm
Length	4266 mm
Wheel base	2640 mm
Kerb weight	1359 kg
Max. allowed weight	1780 kg

Additional information

Fuel tank capacity	52 l
Fuel delivery	Direct Injection
Number of doors	3
Number of seats	4

Number of axles	2
Engine number	1708102