





report date: 2024-03-29

General information

Make	VOLVO
Model	V40 T3 INSCRIPTION
Colour	Grey
Year of manufacture	2018
Top speed	130 mph
Gearbox	6 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	250 Nm at 1.300 rpm
Engine capacity	1.969 сс
Cylinders	4
Fuel type	Petrol
Consumption city	35.8 mpg
Consumption extra urban	60.1 mpg
Consumption combined	39.8 mpg
CO2 emission	139 g/km
CO2 label	E



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2022-07-29

Pictures 8

Listing price <u>View report</u>









source: autoonline.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history	Μ	OT	h	is	to	rv
-------------	---	----	---	----	----	----

MOT expiry date	2024-05-08
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	4
Total items failed	2

MOT #5	2023-05-03 11:39
MOT test number	247005239826
Result	✓ Passed
Next expiry date	2024-05-08

MOT #4	2022-05-09 11:01
MOT test number	475770072713
Result	✓ Passed

MOT #3	2022-05-06 08:28

MOT test number 837314715616

Result X Failed

Advice Offside Front Outer Tyre slightly damaged (5.2.3 (d) (ii))

Fail Offside Rear Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice Nearside Rear Outer Tyre slightly damaged (5.2.3 (d) (ii))

MOT #2 2021-07-16 10:06
MOT test number 660693693639

Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords also slight damage on outer side wall (5.2.3 (d) (i))

CarCheck.co.uk page 3/11



YX68GZT report date: 2024-03-29

MOT #1 2021-07-16 09:13

MOT test number 493162921025

Result



Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords also slight damage on outer side wall (5.2.3 (d) (i))

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i))

CarCheck.co.uk page 4/11



YX68GZT report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 January
Days left	246
MOT expiry date	8 May 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
First licence fee (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



YX68GZT report date: 2024-03-29

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



YX68GZT report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner	history
OWITE	iiiistoi y

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full is	

	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	,
Current registration	NE NE
Plate since	
Current registration	NK SIN
Plate since	
	More info >

CarCheck.co.uk page 8/11



YX68GZT report date: 2024-03-29

Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Control info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-09-12
Last registration	2023-05-03
Complete history	See info



Registration #1	2018-09-12	23 mi
Registration #2	2021-07-16	10.061 mi
Registration #3	2021-07-16	10.061 mi
Registration #4	2022-05-06	13.211 mi
Registration #5		11.777 es
Registration #6		71.777 66
Registration #7		11,777 mi

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

S0225	Air conditionin
S0295	
50482	
50501	
50566	
50567	
50569	

Safety ratings

NCAP rating	****
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	see crash video



Dimensions & weight

Width	1857 mm
Height	1439 mm
Length	4369 mm
Wheel base	2647 mm
Kerb weight	1393 kg
Max. allowed weight	1965 kg

Additional information

Fuel tank capacity	62 I
Fuel delivery	Direct Injection
Number of doors	5
Number of seats CarCheck.co.uk	5 page 11/1

Number of axles 2

Engine number 2726996