



report date: 2024-03-28

General information

Make	FIAT
Model	PANDA ACTIVE
Colour	Gold
Year of manufacture	2008
Top speed	93 mph
0 - 60 mph	15.0 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	54 BHP
Max. torque	87 Nm at 2.750 rpm
Engine capacity	1.108 cc
Cylinders	4
Fuel type	Petrol
Consumption city	39.2 mpg
Consumption extra urban	58.9 mpg
Consumption combined	49.6 mpg
CO2 emission	135 g/km
CO2 label	E





Internet history

Entry 2


Date	2024-03-18
Pictures	11
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2021-01-29
Pictures	10
Listing price	View report



source: autoonline.co.uk



MOT history

MOT expiry date	2025-04-10
MOT pass rate	74 %
MOT passed	14
Failed MOT tests	5
Total advice items	41
Total items failed	4

MOT #19	2024-04-11 13:25
MOT test number	939391875954
Result	✓ Passed
Next expiry date	2025-04-10

MOT #18	2023-07-17 11:51
MOT test number	790389575238
Result	✓ Passed
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear axel corroded

MOT #17	2023-07-17 11:35
MOT test number	744272165572
Result	✗ Failed
Advice	Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
Advice	Rear axel corroded
MAJOR	Offside Rear Direction indicator adversely affected by the operation of another lamp (4.4.3 (b))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
MAJOR	Nearside Headlamp aim too low (4.1.2 (a))

**MOT #16** 2022-07-13 15:21**MOT test number** 885199422642**Result** ✓ Passed**MOT #15** 2022-07-12 15:30**MOT test number** 152168140330**Result** ✗ Failed**DANGEROUS** Nearside Front Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**MAJOR** Nearside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))**DANGEROUS** Nearside Rear Tyre tread depth below requirements of 1.6mm (5.2.3 (e))**MAJOR** Nearside Rear Stop lamp(s) not working (4.3.1 (a) (ii))**MOT #14** 2021-04-29 12:30**MOT test number** 379948772518**Result** ✓ Passed**MOT #13** 2020-09-30 08:47**MOT test number** 629862893760**Result** ✓ Passed**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #12** 2019-09-27 14:56**MOT test number** 932368816084**Result** ✓ Passed**Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))

**MOT #11** 2018-11-07 10:50**MOT test number** 621711329581**Result** ✓ Passed**MOT #10** 2018-11-06 09:44**MOT test number** 353198013357**Result** ✗ Failed

- MAJOR** Nearside Front Position lamp not working (4.2.1 (a))
- MAJOR** Offside Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- MAJOR** Front Exhaust system insecure (6.1.2 (a))
- MAJOR** Nearside Front Anti-roll bar ball joint excessively worn (5.3.4 (a) (i))

MOT #9 2017-04-06 09:38**MOT test number** 369752575779**Result** ✓ Passed**MOT #8** 2016-04-25 14:15**MOT test number** 352972444921**Result** ✓ Passed**MOT #7** 2016-04-25 10:48**MOT test number** 793013435140**Result** ✗ Failed

- Fail** Nearside Front Suspension arm has excessive play in a pin/bush Rear Bush (2.4.G.2)
- Fail** Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2)
- Fail** Nearside Front Suspension arm has excessive play in a ball joint (2.4.G.2)

**MOT #6** 2015-03-02 10:12**MOT test number** 276191565088**Result** ✓ Passed

Advice Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Notice Nearside rear exhaust section outer skin corroded deteriorated but section has no exhaust leak

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #5 2014-02-13 10:27**MOT test number** 268834044034**Result** ✓ Passed

Advice Nearside Rear Tyre worn close to the legal limit (4.1.E.1)

Notice Nearside rear exhaust section outer skin deteriorated corroded but section has no exhaust leak

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #4 2013-02-25 17:41**MOT test number** 208626053088**Result** ✓ Passed

Notice Centre front exhaust section mountain bracket corroded deteriorated but section is still adequately supported

Notice Slight exhaust leak centre section to nearside rear section joint area

Notice Nearside rear exhaust section outer skin deteriorated corroded but section has no exhaust leak

Notice Slight exhaust leak front section to centre section joint area

**MOT #3** 2013-02-25 13:26**MOT test number** 989906453014**Result** ✗ Failed**Notice** Nearside rear exhaust section outer skin deteriorated corroded but section has no exhaust leak**Advice** Nearside Rear Upper Shock absorber has a slightly worn bush (2.7.4)**Notice** Slight exhaust leak front section to centre section joint area**Fail** Offside Rear Upper Shock absorber has an excessively worn bush (2.7.4)**Notice** Centre front exhaust section mountain bracket corroded deteriorated but section is still adequately supported**Notice** Slight exhaust leak centre section to nearside rear section joint area**MOT #2** 2012-02-23 11:37**MOT test number** 159744952093**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Notice** Front section exhaust mountain deteriorated but section is still adequately supported**Advice** Offside Rear Upper Shock absorber has a slightly worn bush (2.7.4)**Advice** Exhaust has a minor leak of exhaust gases (7.1.2)**Notice** N/s rear exhaust section slightly deteriorated outer skin**MOT #1** 2011-02-24 10:50**MOT test number** 339145951060**Result** ✓ Passed**Notice** ADVISE front brake pads low



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
10 April 2025

Tax status	Valid until 1 April
Days left	338
MOT expiry date	10 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	E
Single payment (12 months)	£ 180,00,-
Single six month payment	£ 99,00,-
Total payable by 12 monthly instalments	£ 189,00,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	22
First mileage registration	2008-03-01
Last registration	2024-04-11
Complete history	See info



Registration #1	2008-03-01	23 mi
Registration #2	2011-02-24	22.018 mi
Registration #3	2012-02-23	25.496 mi
Registration #4	2013-02-25	30.826 mi
Registration #5	2013-02-25	30.826 mi
Registration #6	2014-02-13	41.110 mi
Registration #7	2015-03-02	46.907 mi
Registration #8	2016-04-25	53.878 mi
Registration #9	2016-04-25	53.878 mi
Registration #10	2017-04-06	59.649 mi
Registration #11	2018-11-06	60.517 mi
Registration #12	2019-05-29	61.377 mi
Registration #13	2019-05-29	61.377 mi
Registration #14	2019-05-29	61.377 mi
Registration #15	2019-05-29	61.377 mi
Registration #16	2019-05-29	61.377 mi
Registration #17	2019-05-29	61.377 mi
Registration #18	2019-05-29	61.377 mi
Registration #19	2019-05-29	61.377 mi
Registration #20	2019-05-29	61.377 mi
Registration #21	2019-05-29	61.377 mi
Registration #22	2019-05-29	61.377 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating

Video [see crash video](#)



Dimensions & weight

Width	1578 mm
Height	1540 mm
Length	3538 mm
Wheel base	2299 mm
Kerb weight	840 kg
Max. allowed weight	1255 kg

Additional information

Fuel tank capacity	35 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	4

Number of axles	2
Engine number	4119468