



HONDA



LA08CTF


report date: 2024-03-28

General information

Make	HONDA
Model	ACCORD I-VTEC ES GT
Colour	Blue
Year of manufacture	2008
Top speed	130 mph
0 - 60 mph	10.7 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	154 BHP
Max. torque	192 Nm at 4.100 rpm
Engine capacity	1.997 cc
Cylinders	4
Fuel type	Petrol
Consumption city	26.4 mpg
Consumption extra urban	47.1 mpg
Consumption combined	36.7 mpg
CO2 emission	187 g/km
CO2 label	J





MOT history

MOT expiry date	2022-04-01
MOT pass rate	71 %
MOT passed	10
Failed MOT tests	4
Total advice items	14
Total items failed	7

MOT #14	2021-04-02 15:40
MOT test number	684716331414
Result	✓ Passed
Next expiry date	2022-04-01
Advice	Offside Rear position lamp lens badly broken. Need URGENT change

MOT #13	2021-04-02 15:40
MOT test number	133999870766
Result	✗ Failed
Pass with rectification	Offside Rear Position lamp missing (4.2.1 (a) (ii))
Pass with rectification	Rear Registration plate insecure (0.1 (a))
Advice	Offside Rear position lamp lens badly broken. Need URGENT change
Pass with rectification	Front Registration plate insecure (0.1 (a))

MOT #12	2020-02-17 17:33
MOT test number	462626499851
Result	✓ Passed
Advice	Nearside rear handbrake efforts weak and overall just legal
Advice	Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))

**MOT #11** 2020-02-12 16:44**MOT test number** 424886776457**Result** ✗ Failed**MAJOR** Parking brake lever has excessive movement indicating incorrect adjustment (1.1.6 (c))**Advice** Offside Front Lower Suspension arm pin or bush worn but not resulting in excessive movement front bush (5.3.4 (a) (i))**DANGEROUS** Parking brake efficiency less than 50% of the required value (1.4.2 (a) (ii))**MAJOR** Nearside Front Position lamp not working (4.2.1 (a) (ii))**MOT #10** 2019-01-23 15:44**MOT test number** 881557483007**Result** ✓ Passed**MOT #9** 2018-01-29 16:47**MOT test number** 211307464097**Result** ✓ Passed**MOT #8** 2017-01-30 12:36**MOT test number** 963132930053**Result** ✓ Passed**MOT #7** 2017-01-25 14:46**MOT test number** 174162293764**Result** ✗ Failed**Fail** Parking brake: efficiency below requirements (3.7.B.7)**Fail** Parking brake lever has no reserve travel (3.1.6b)**Fail** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

**MOT #6** 2016-01-27 10:09**MOT test number** 680132775728**Result** ✓ Passed**Advice** Both rear tyre treads getting low**MOT #5** 2015-01-14 13:23**MOT test number** 668044015031**Result** ✓ Passed**Notice** Front and rear brake pads worn low**MOT #4** 2014-01-15 12:29**MOT test number** 536345414003**Result** ✓ Passed**MOT #3** 2013-01-09 11:12**MOT test number** 255079803058**Result** ✓ Passed**MOT #2** 2013-01-09 10:40**MOT test number** 815019703079**Result** ✗ Failed**Fail** Front Brake pad(s) less than 1.5 mm thick (3.5.1g)**Notice** Advise rear tyres 2mm**Notice** Advise front discs lipped



MOT #1	2012-01-18 17:15
MOT test number	267328912099
Result	✓ Passed
Notice	Front + rear pads low
Notice	Both front tyre treads low



Tax & MOT check

✕
Untaxed

Tax expired:
31 March 2022

✕
MOT

Expired:
1 April 2022

Tax status	Expired at 31 March 2022
Days left	761 days too late
MOT expiry date	1 April 2022
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	J
Single payment (12 months)	£ 365,00,-
Single six month payment	£ 200,75,-
Total payable by 12 monthly instalments	£ 383,25,-



Damage history

Check the damage history for this HONDA. See if, where and when this HONDA had damage and the car repair costs. We also check if this HONDA was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra HONDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this HONDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this HONDA? How many owners did this HONDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period
Owner	Period

More info >

Plate changes

See in this check if this HONDA had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-28
Current registration	
Plate since	2024-03-28

More info >



Finance check

Check if this HONDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this HONDA has been settled.

If not, and you buy this HONDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this HONDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	15
First mileage registration	2008-08-18
Last registration	2021-04-02
Complete history	See info



Registration #1	2008-08-18	17 mi
Registration #2	2012-01-18	18.753 mi
Registration #3	2013-01-09	29.545 mi
Registration #4	2013-01-09	29.545 mi
Registration #5	2014-01-15	41.860 mi
Registration #6	2015-01-14	53.320 mi
Registration #7	2016-01-27	64.163 mi
Registration #8	2017-01-25	74.886 mi
Registration #9	2018-01-25	85.609 mi
Registration #10	2019-01-25	96.332 mi
Registration #11	2020-01-25	107.055 mi
Registration #12	2021-01-25	117.778 mi
Registration #13	2022-01-25	128.501 mi
Registration #14	2023-01-25	139.224 mi
Registration #15	2024-01-25	149.947 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	see crash video



Dimensions & weight

Width	1840 mm
Height	1440 mm
Length	4740 mm
Wheel base	2705 mm
Kerb weight	1462 kg

Additional information

Fuel tank capacity	65 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5
Engine number	R20A31250401