





report date: 2024-03-29

General information

Make	VOLVO
Model	V40 T3 CROSS COUNTRY NAV PLUS
Colour	Black
Year of manufacture	2018
Top speed	130 mph
0 - 60 mph	8.0 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	150 BHP
Max. torque	250 Nm at 1.300 rpm
Engine capacity	1.969 сс
Cylinders	4
Fuel type	Petrol
Consumption city	39.8 mpg
Consumption extra urban	61.4 mpg
Consumption combined	51.4 mpg
CO2 emission	128 g/km
CO2 label	D



CarCheck.co.uk page 1/11



report date: 2024-03-29

Internet history

Entry 1

Date 2021-09-20

Pictures 11

Listing price <u>View report</u>









source: cargurus.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

N/I	α		uc:	t۸	r\/
101	•		115	w	ıv
	•	Γh			. ,

MOT expiry date	2025-01-03
MOT pass rate	80 %
MOT passed	4
Failed MOT tests	1
Total advice items	7
Total items failed	3

MOT #5		2023-12-18 15:12
MOT test	number	242462316291
Result		✓ Passed
Next expi	ry date	2025-01-03
Advice	Advice Nearside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))	
Advice	Advice Nearside Front Tyre worn close to legal limit/worn on edge inner edge worn (5.2.3 (e))	
Advice Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))		ds (5.2.3 (d) (i))
Advice	Nearside Front Tyre slightly damaged (5.2.3 (d) (ii))	
Advice	Offside Front Tyre worn close to legal limit/worn on edge inner edge wo	rn (5.2.3 (e))

MOT #4	2022-12-20 14:4
MOT test	number 17263141418
Result	✓ Passe
Advice Nearside Front Tyre slightly damaged cut on outer sidewall , some cuts in tread (5.2.3 (d) (ii)) Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt	
Auvice	Offside Real Critic Seat litted flot allowing full hispection of adult beit

MOT #3	2022-01-04 11:37
MOT test number	567781610744
Result	✓ Passed

CarCheck.co.uk page 3/11



Pass with rectification

NU18OZF

report date: 2024-03-29

MOT #2 2021-02-15 13:40 **MOT test number** 654376628614 Result ✓ Passed MOT #1 2021-02-15 13:40 **MOT** test number 155669663346 Result × Failed Pass with rectification Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii)) Pass with rectification Offside Front Headlamp aim too low (4.1.2 (a))

Nearside Front Headlamp aim too low (4.1.2 (a))

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 October
Days left	154
MOT expiry date	3 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	G
First licence fee (12 months)	£ 210,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this VOLVO. See if, where and when this VOLVO had damage and the car repair costs. We also check if this VOLVO was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra VOLVO salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this VOLVO in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

Owner history

For how long did the current and previous owner(s) have this VOLVO? How many owners have? Check it in the premium report and see all owner registrations. Download the full it	

	More info >
Plate changes	
See in this check if this VOLVO had different number plates.	
Number of plates	
Current registration	IK SIN
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this VOLVO is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLVO has been settled.

If not, and you buy this VOLVO then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLVO is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info

More info >

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2018-03-29
Last registration	2023-12-18
Complete history	See info



Registration #1	2018-03-29	28 mi
Registration #2	2021-02-15	20.760 mi
Registration #3	2021-02-15	20.760 mi
Registration #4		11.777 es
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		D.377 es

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

50225	Air conditioning
50295	
60482	
0501	
0566	
60567	
60569	

Safety ratings

NCAP rating	****
Adult	98%
Children	75%
Pedestrian	88%
Safety systems	100%
Overall rating	92%
Video	see crash video



Dimensions & weight

Width	1857 mm
Height	1470 mm
Length	4370 mm
Wheel base	2646 mm
Kerb weight	1428 kg
Max. allowed weight	1970 kg

Additional information

Fuel tank capacity	62 l	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of seats CarCheck.co.uk	5	page 11/11

Number of axles2Engine number2529196