





report date: 2024-03-29

General information

Make	PEUGEOT
Model	407 HDI EXECUTIVE
Colour	Black
Year of manufacture	-
Top speed	129 mph
0 - 60 mph	9.8 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	134 BHP
Max. torque	320 Nm at 2.000 rpm
Cylinders	4
Fuel type	Diesel
Consumption city	36.7 mpg
Consumption extra urban	57.7 mpg
Consumption combined	47.9 mpg



CarCheck.co.uk page 1/12



RN54WYD
report date: 2024-03-29

Internet history

Emter.	1
	ъ.

Life y 1	
Date	2021-08-02
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-29

MOT history

MOT #12 2020-10-19 09:28

MOT test number 215882979739

Result
✓ Passed

Next expiry date 2021-10-18

MOT #11 2019-10-04 15:43

MOT test number 954168365582

Advice

Suspension arm ball joint has slight play n/s and o/s front lower ball joints (5.3.4 (a) (i))

MOT #10 2019-10-04 15:43

MOT test number 761688890177

Result X Failed

Pass with rectification Offside Rear Shock absorbers has a serious fluid leak (5.3.2 (b))

Pass with rectification Offside Front Headlamp not working on dipped beam (4.1.1 (a) (ii))

Pass with rectification Nearside Rear Position lamp not working (4.2.1 (a) (ii))

Advice Suspension arm ball joint has slight play n/s and o/s front lower ball joints (5.3.4 (a) (i))

Pass with rectification Offside Rear Direction indicator incorrect colour (4.4.3 (a))

MOT #9 2015-04-28 12:57

MOT test number 608398215192

Result ✓ Passed

CarCheck.co.uk page 3/12



Fail

RN54WYD

report date: 2024-03-29

MOT #8 2015-04-13 11:49 **MOT** test number 686883205169 Result **X** Failed Fail Nearside Front brake disc in such a condition that it is seriously weakened (3.5.1i) Fail Offside Front Suspension arm has excessive play in a ball joint (2.4.G.2) Nearside Rear Shock absorber has a serious fluid leak (2.7.3) Fail Offside Front Brake pad(s) less than 1.5 mm thick (3.5.1g) Fail Offside Rear brake disc in such a condition that it is seriously weakened (3.5.1i) Fail Fail Electronic stability system warning lamp does not illuminate (3.4.1b) Fail Nearside Front constant velocity joint gaiter damaged to the extent that it no longer prevents the ingress of dirt etc (2.5.C.1a)

MOT test number

Result

Advice Offside Front Lower Suspension arm has slight play in a ball joint (2.4.G.2)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3)

Nearside Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

MOT #6		2013-02-09 10:42
MOT test	number	897620043074
Result		✓ Passed
Advice	Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a	a)
Notice	N/s number plate light dull	
Advice	Nearside Rear Shock absorber has a light misting of oil (2.7.3)	

CarCheck.co.uk page 4/12



report date: 2024-03-29

MOT #5

MOT test number

Result

Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3)

2012-01-28 11:52

939748522029

✓ Passed

MOT #4 2011-02-12 09:57 **MOT** test number 138123241023 Result ✓ Passed **Advice** Nearside Rear Tyre worn close to the legal limit (4.1.E.1) Notice Front washers weak water pressure Advice Nearside Rear Shock absorber has a light misting of oil (2.7.3) Advice Offside Inner Rear Road wheel slightly damaged (4.2.A.1a) **Advice** Offside Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

MOT test number

Result

Advice Front Brake pad(s) wearing thin (3.5.1g)

Advice Offside Front Front suspension has slight play in a lower suspension ball joint (2.5.B.1a)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

 MOT #2
 2009-01-29 12:25

 MOT test number
 501599129025

 Result
 ✓ Passed

CarCheck.co.uk page 5/12



report date: 2024-03-29

MOT #1

MOT test number

Result

Notice Body filler in n/s sill

CarCheck.co.uk page 6/12



report date: 2024-03-29

Damage history

Check the damage history for this PEUGEOT. See if, where and when this PEUGEOT had damage and the car repair costs. We also check if this PEUGEOT was scrapped. Download the premium report here for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Type	



Extra PEUGEOT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



RN54WYD
report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this PEUGEOT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-29

\cap	ner	hi	~+~	-
UΝ	mer.		รเบ	H V

For how long did the current and previous owner(s) have this PEUGEOT? How many own have? Check it in the premium report and see all owner registrations. Download the full	

	More info >
Plate changes	
See in this check if this PEUGEOT had different number plates.	
Number of plates	
Current registration	NK SIE
Plate since	
Current registration	UK UK
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-29

Finance check

Check if this PEUGEOT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this PEUGEOT has been settled.

If not, and you buy this PEUGEOT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this PEUGEOT is financed.

Finance company

Date of agreement

Agreement type

Agreement term

Agreement number

Contact info

More info >

CarCheck.co.uk page 10/12



report date: 2024-03-29

Mileage check

Registration #14

Odometer	In miles
Mileage registrations	14
First mileage registration	2005-01-19
Last registration	2020-10-19
Complete history	See info



Registration #1	2005-01-19	24 mi
Registration #2	2008-02-14	117.370 mi
Registration #3	2009-01-29	127.653 mi
Registration #4	2010-02-10	136.226 mi
Registration #5	2011-02-12	140.980 mi
Registration #6	2012-01-28	144.439 mi
Registration #7	2013-02-09	152.439 mi
Registration #8		71.777 es
Registration #9		71.777 esi
Registration #10		71.777 es
Registration #11		11.777 es
Registration #12		71.777 es
Registration #13		11.777 es

mn.n.n

More info >

77.777 86

CarCheck.co.uk page 11/12



report date: 2024-03-29

Car features

S0225	Air conditioning
S0295	
S0482	
50501	
50566	
S0567	
S0569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1811 mm
Height	1445 mm
Length	4676 mm
Wheel base	2725 mm
Kerb weight	1580 kg
Max. allowed weight	2080 kg

Additional information

Fuel tank capacity	66 I	
Fuel delivery	Direct Injection	
Number of doors	4	
Number of seats CarCheck.co.uk	5	page 12/12

Number of axles 2

Engine number DYTJ4104192