





report date: 2024-03-28

### General information

Make	VOLKSWAGEN
Model	E-GOLF
Colour	Black
Year of manufacture	2019
Top speed	93 mph
Gearbox	1 speed automatic

## Engine & fuel consumption

Power	134 BHP
Max. torque	290 Nm at 3.000 rpm
Fuel type	Electricity
Consumption combined	282.5 mpg



CarCheck.co.uk page 1/11



report date: 2024-03-28

## Internet history

#### Entry 2

Date	2021-12-04
Pictures	1
Listing price	View report



#### source: cargurus.co.uk

#### Entry 1

Date	2021-12-04
Pictures	0
Listing price	View report

source: heycar.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-28

## MOT history

MOT expiry date	2024-11-20
MOT pass rate	67 %
MOT passed	2
Failed MOT tests	1
Total advice items	10
Total items failed	0

MOT #3		2023-11-07 14:32
MOT test numb	per	205507892877
Result		✓ Passed
Next expiry da	te	2024-11-20
<b>Advice</b> Offs	ide Rear Shock absorbers has light misting of oil (5.3.2 (b))	
Advice Nearside Rear Shock absorbers has light misting of oil (5.3.2 (b))		
<b>Advice</b> Offs	ide Front Play in steering rack inner joint(s)	

MOT #2	2023-11-04 11:20
MOT test number	354313893887
Result	<b>X</b> Failed
Advice Offside Front Play in steeri	rack inner joint(s)
<b>DANGEROUS</b> Nearside Rear Inner	re has ply or cords exposed EDGE (5.2.3 (d) (ii))
Advice Nearside Rear Shock absor	ers has light misting of oil (5.3.2 (b))
<b>DANGEROUS</b> Offside Rear Inner T EDGE (5.2.3 (d) (ii))	e has a bulge, caused by separation or partial failure of its structure
Advice Offside Rear Shock absorb	s has light misting of oil (5.3.2 (b))

CarCheck.co.uk page 3/11



report date: 2024-03-28

MOT #1 2022-11-12 09:53

**MOT test number** 443438501011

**Result** ✓ Passed

**Advice** Offside Rear Shock absorbers has light misting of oil (5.3.2 (b))

Advice Offside Rear Child Seat fitted not allowing full inspection of adult belt

CarCheck.co.uk page 4/11



report date: 2024-03-28





Days left 216

MOT expiry date 20 November 2024

Full MOT history See MOT history

CarCheck.co.uk page 5/11



report date: 2024-03-28


#### Damage history

Check the damage history for this VOLKSWAGEN. See if, where and when this VOLKSWAGEN had damage and the car repair costs. We also check if this VOLKSWAGEN was scrapped. Download the premium report here for the results.

#### Damage 1

Date	
Category	
Туре	

Damage 2	
Date	
Category	



#### Extra VOLKSWAGEN salvage check



**Type** 

If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this VOLKSWAGEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

**Trade retail value** 

**Auction value** 

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-28

## Owner history

Owner history	
For how long did the current and previous owner(s) have this VOLKSWAGEN? How many VOLKSWAGEN have? Check it in the premium report and see all owner registrations. Dow here.	
*********	
***************************************	
***************************************	
***************************************	
***************************************	
***************************************	
	More info >
Plate changes	
See in this check if this VOLKSWAGEN had different number plates.	
Number of plates	,
Current registration	UK
Plate since	
Current registration	NK NE
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-28

#### Finance check

Check if this VOLKSWAGEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this VOLKSWAGEN has been settled.

If not, and you buy this VOLKSWAGEN then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this VOLKSWAGEN is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Combact info	

**Contact info** 

 $\quad \text{More info} \quad > \quad$ 

CarCheck.co.uk page 9/11



report date: 2024-03-28

## Mileage check

Odometer	In miles
Mileage registrations	6
First mileage registration	2019-11-21
Last registration	2023-11-07
Complete history	See info



Registration #1	2019-11-21	21 mi
Registration #2		71.777 66
Registration #3		11.777 es
Registration #4		71.777 es
Registration #5		11.777 es
Deviatuation #C		

Registration #6

More info >

CarCheck.co.uk page 10/11




report date: 2024-03-28

### Car features

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

## Safety ratings

NCAP rating	****
Adult	94%
Children	89%
Pedestrian	65%
Safety systems	71%
Overall rating	85%
Video	see crash video



## Dimensions & weight

Width	2027 mm
Height	1482 mm
Length	4349 mm
Wheel base	2629 mm
Kerb weight	1615 kg
Max. allowed weight	2020 kg

## Additional information

Fuel delivery	Not Applicable
Number of doors	5
Number of seats	5
CarChack coluk	nage 11/11

CarCheck.co.uk page 11/11

Number of axles	2
Engine number	EAZA011568