





report date: 2024-03-29

General information

Make	RENAULT
Model	KADJAR GT LINE TCE
Colour	Red
Year of manufacture	2019
Top speed	126 mph
0 - 100 km/h	10.4 seconds
Gearbox	6 speed Manual

Engine & fuel consumption

Power	103 kW / 140 HP / 138 BHP
Max. torque	240 Nm at 1.600 rpm
Engine capacity	1.332 cc
Cylinders	4
Fuel type	Petrol
Consumption city	31.4 mpg
Consumption extra urban	46.1 mpg
Consumption combined	2.8 mpg
CO2 emission	136 g/km
CO2 label	E



CarCheck.co.uk page 1/11



report date: 2024-03-29


Internet history

Entry 1

Date 2022-02-24

Pictures 15

Listing price <u>View report</u>









source: autotrader.co.uk

CarCheck.co.uk page 2/11



report date: 2024-03-29

MOT history

MOT expiry date	2025-04-25
MOT pass rate	60 %
MOT passed	3
Failed MOT tests	2
Total advice items	14
Total items failed	0

MOT #5	2024-04-22 14:43
MOT test number	517027596466
Result	✓ Passed
Next expiry date	2025-04-25
Advice Rear Brake pad(s) wearing the	nin (1.1.13 (a) (ii))
Advice Both rear tyres aged and sta	rting to crack on edges

MOT #4		2024-04-22 09:50
MOT test	number	164110591802
Result		X Failed
MAJOR inner edge	Offside Front Tyre has a cut in excess of the requirements deep enough to (5.2.3 (d) (i))	reach the ply or cords
Advice	Rear Brake pad(s) wearing thin (1.1.13 (a) (ii))	
Advice	Both rear tyres aged and starting to crack on edges	

CarCheck.co.uk page 3/11



report date: 2024-03-29

MOT test number

Result

Advice

Nearside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

Advice

Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Advice

Unable to fully check ns rear seat belt due to child seat fitted

Advice

Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i))

MOT #2 2023-04-26 08:45 **MOT** test number 940140674665 Result × Failed **Advice** Nearside Front Inner Road wheel slightly distorted (5.2.2 (c) (i)) Advice Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Advice Unable to fully check ns rear seat belt due to child seat fitted **MAJOR** Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (5.2.3 (d) (i)) Advice Nearside Rear Outer Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))

MOT #1	2022-02-08 16:54
MOT test number	169475874948
Result	✓ Passed

CarCheck.co.uk page 4/11



report date: 2024-03-29

Tax & MOT check



Tax status	Valid until 1 May
Days left	1
MOT expiry date	25 April 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	Н
First licence fee (12 months)	£ 255,00,-
Standard rate (12 months)	£ 180,00,-
Standard rate (6 months)	£ 99,00,-
Premium rate (12 months)	£ 570,00,-
Premium rate (6 months)	£ 313,50,-

CarCheck.co.uk page 5/11



report date: 2024-03-29

Damage history

Check the damage history for this RENAULT. See if, where and when this RENAULT had damage and the car repair costs. We also check if this RENAULT was scrapped. Download the premium report here for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra RENAULT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 6/11



report date: 2024-03-29

Vehicle valuation

What is this car worth? See the vehicle value of this RENAULT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 7/11



report date: 2024-03-29

$\overline{}$	ner	L : _	L
()\\\	ner	nıs	rorv

For how long did the current and previous owner(s) have this RENAULT? How many owner have? Check it in the premium report and see all owner registrations. Download the full report and see all owner registrations.	
THE STATE OF THE S	

	More info >
Plate changes	
See in this check if this RENAULT had different number plates.	
Number of plates	,
Current registration	OK SIE
Plate since	
Current registration	SK UK
Plate since	
	More info >

CarCheck.co.uk page 8/11



report date: 2024-03-29

Finance check

Check if this RENAULT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this RENAULT has been settled.

If not, and you buy this RENAULT then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this RENAULT is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	

Contact info

 $\quad \text{More info} \quad > \quad$

CarCheck.co.uk page 9/11



report date: 2024-03-29

Mileage check

Odometer	In miles
Mileage registrations	7
First mileage registration	2019-05-31
Last registration	2024-04-22
Complete history	See info



Registration #1	2019-05-31	29 mi
Registration #2	2022-02-08	14.680 mi
Registration #3		11.777 es
Registration #4	2023-04-26	21.200 mi
Registration #5		11.777 es
Registration #6		11.777 es
Registration #7		11.777 mi

More info >

CarCheck.co.uk page 10/11



report date: 2024-03-29

Car features

S0225	Air conditionin
S0295	
50482	
60501	
60566	
60567	
50569	

Safety ratings

NCAP rating	****
Adult	89%
Children	81%
Pedestrian	74%
Safety systems	71%
Overall rating	81%
Video	see crash video



Dimensions & weight

Width	1836 mm
Height	1611 mm
Length	4489 mm
Wheel base	2646 mm
Kerb weight	1308 kg

Additional information

Fuel tank capacity	55 I
Number of axles	2
Engine number	D136879

CarCheck.co.uk page 11/11