



report date: 2024-03-29

General information

Make	FIAT
Model	500 LOUNGE
Colour	White
Year of manufacture	2017
Top speed	99 mph
0 - 60 mph	12.9 seconds
Gearbox	5 speed Manual

Engine & fuel consumption

Power	69 BHP
Max. torque	102 Nm at 3.000 rpm
Engine capacity	1.242 cc
Cylinders	4
Fuel type	Petrol
Consumption city	51.4 mpg
Consumption extra urban	65.7 mpg
Consumption combined	60.1 mpg
CO2 emission	110 g/km
CO2 label	B






Internet history

Entry 1

Date	2021-01-29
Pictures	10
Listing price	<a href="#">View report</a>



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-10-30
MOT pass rate	57 %
MOT passed	4
Failed MOT tests	3
Total advice items	21
Total items failed	8

MOT #7	2023-10-26 12:54
MOT test number	392904194119
Result	✓ Passed
Next expiry date	2024-10-30
Advice	Offside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))
Advice	Items removed from driver's view prior to test

**MOT #6**

2023-10-20 12:21

**MOT test number**

966802689583

**Result****✗ Failed****Minor**

Headlamp cleaning device inoperative Both (4.1.6 (a) (i))

**Fail**

Offside Front Suspension arm pin or bush excessively worn (5.3.4 (a) (i))

**Advice**

Offside Front Tyre worn close to legal limit/worn on edge 2-0mm (5.2.3 (e))

**Advice**

Offside Front Shock absorbers has light misting of oil (5.3.2 (b))

**Advice**

Offside Rear Nail in tyre

**Advice**

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Fail**

Offside Headlamp insecure (4.1.1 (c))

**Advice**

Nearside Front Tyre worn close to legal limit/worn on edge 2-0mm (5.2.3 (e))

**Advice**

Nearside Front Shock absorbers has light misting of oil (5.3.2 (b))

**Advice**

Items removed from driver's view prior to test

**Advice**

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #5**

2022-10-31 14:47

**MOT test number**

927041838077

**Result****✓ Passed****Advice**

Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice**

Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**Advice**

Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))

**Advice**

Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

**MOT #4** 2022-10-21 13:50**MOT test number** 167839800213**Result** ✗ Failed**Advice** Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Offside Front Suspension arm pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**Advice** Nearside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))**Fail** Offside Headlamp insecure (4.1.1 (c))**Advice** Offside Front Upper Macpherson strut pin or bush worn but not resulting in excessive movement (5.3.4 (a) (i))**MOT #3** 2021-10-22 14:57**MOT test number** 831344090334**Result** ✓ Passed**MOT #2** 2021-10-20 14:58**MOT test number** 773038336550**Result** ✗ Failed**Fail** Windscreen washer provides insufficient washer liquid (3.5 (a))**Fail** Nearside Headlamp aim too high (4.1.2 (a))**Advice** Offside Front door strap bracket bolt loose**Fail** Offside Headlamp insecure (4.1.1 (c))**Fail** Offside Headlamp aim too high (4.1.2 (a))**MOT #1** 2020-10-02 14:50**MOT test number** 883079023239**Result** ✓ Passed



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 February 2025

✓  
**MOT**  
**Expires:**  
30 October 2024

<b>Tax status</b>	Valid until 1 February
<b>Days left</b>	277
<b>MOT expiry date</b>	30 October 2024
<b>Full MOT history</b>	<a href="#">See MOT history</a>

Tax calculation

<b>Vehicle class</b>	48
<b>Band</b>	F
<b>First licence fee (12 months)</b>	£ 185,00,-
<b>Standard rate (12 months)</b>	£ 180,00,-
<b>Standard rate (6 months)</b>	£ 99,00,-
<b>Premium rate (12 months)</b>	£ 570,00,-
<b>Premium rate (6 months)</b>	£ 313,50,-



Damage history

Check the damage history for this FIAT. See if, where and when this FIAT had damage and the car repair costs. We also check if this FIAT was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra FIAT salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FIAT in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >





Owner history

For how long did the current and previous owner(s) have this FIAT? How many owners did this FIAT have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FIAT had different number plates.

Number of plates	1
Current registration	*****
Plate since	2024-03-29
Current registration	*****
Plate since	2024-03-29

More info >



Finance check

Check if this FIAT is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FIAT has been settled.

If not, and you buy this FIAT then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FIAT is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	9
First mileage registration	2017-10-31
Last registration	2023-10-26
Complete history	<a href="#">See info</a>



Registration #1	2017-10-31	16 mi
Registration #2	2020-10-02	29.164 mi
Registration #3	2020-10-02	29.164 mi
Registration #4	2021-10-20	31.827 mi
Registration #5	2021-10-22	31.829 mi
Registration #6	2023-10-26	31.829 mi
Registration #7	2023-10-26	31.829 mi
Registration #8	2023-10-26	31.829 mi
Registration #9	2023-10-26	31.829 mi

More info >



Car features

The FIAT factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FIAT factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating	★★★★☆
Adult	66%
Children	49%
Pedestrian	53%
Safety systems	27%
Overall rating	52%
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	1627 mm
Height	1488 mm
Length	3571 mm
Wheel base	2300 mm
Kerb weight	865 kg
Max. allowed weight	1345 kg

Additional information

Fuel delivery	Multi-Point Injection
Number of doors	3
Number of seats	4
Number of axles	2

Engine number	2181262
---------------	---------