



report date: 2024-03-28

General information

Make	MAZDA
Model	5 TS2
Colour	Grey
Year of manufacture	-
Top speed	121 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	105 BHP
Max. torque	145 Nm at 4.000 rpm
Cylinders	4
Fuel type	Petrol
Consumption city	25.7 mpg
Consumption extra urban	42.8 mpg
Consumption combined	34.5 mpg




LABEL UNKNOWN



Internet history

Entry 1

Date	2021-02-01
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT #16	2021-01-06 12:32
MOT test number	463813300967
Result	✓ Passed
Next expiry date	2022-01-29

MOT #15	2020-01-30 16:43
MOT test number	504712005112
Result	✓ Passed

- Advice** Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Minor** Nearside Front Inner Drive shaft joint constant velocity boot severely deteriorated (6.1.7 (g) (i))
- Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))
- Advice** Nearside Rear Nail in tyre

MOT #14	2019-01-30 09:20
MOT test number	242100508442
Result	✓ Passed

- Advice** Offside Front Tyre slightly damaged (5.2.3 (d) (ii))

MOT #13	2019-01-29 10:54
MOT test number	689195966872
Result	✗ Failed

- Fail** Front Windscreen wiper does not clear the windscreen effectively (3.4 (b) (ii))
- Fail** Rear Brake disc in such a condition that it is seriously weakened (1.1.14 (a) (ii))
- Fail** Offside Front All position lamps not working (4.2.1 (a))
- Fail** Rear Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))
- Advice** Offside Front Tyre slightly damaged (5.2.3 (d) (ii))

**MOT #12**

2018-01-30 09:51

MOT test number

299409828470

Result

✓ Passed

- Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)
- Advice** Offside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Offside Front Brake hose slightly damaged (3.6.B.4d)
- Advice** Nearside Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

MOT #11

2017-01-11 13:40

MOT test number

747538798008

Result

✓ Passed

- Advice** Nearside Front Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)
- Advice** Nearside Front Anti-roll bar rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Rear Brake pad(s) wearing thin (3.5.1g)

MOT #10

2016-01-05 16:50

MOT test number

429897751374

Result

✓ Passed

- Advice** Nearside Front Anti-roll bar rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

**MOT #9**

2016-01-05 14:32

MOT test number

523760561892

Result

✗ Failed

Advice Nearside Front Anti-roll bar rubber mounting deteriorated but not resulting in excessive movement (2.4.G.2)

Fail Nearside Rear coil spring broken (2.4.C.1a)

Fail Supplementary Restraint System warning lamp indicates a fault (5.4.2)

Advice Nearside Rear Anti-roll bar linkage has slight play in a ball joint (2.4.G.2)

Fail Offside Rear coil spring broken (2.4.C.1a)

MOT #8

2015-01-03 12:56

MOT test number

208053205041

Result

✓ Passed

Notice Slight damage to nearside rear tyre sidewall

MOT #7

2013-12-21 12:52

MOT test number

416475253317

Result

✓ Passed

Advice Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

**MOT #6** 2013-12-20 11:26**MOT test number** 539844553396**Result** ✗ Failed

- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Nearside Front suspension has excessive play in a lower suspension ball joint (2.5.B.1a)
- Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)

MOT #5 2012-10-12 13:14**MOT test number** 776536282226**Result** ✓ Passed**MOT #4** 2012-10-04 10:52**MOT test number** 296218072267**Result** ✗ Failed

- Fail** Offside Rear Shock absorber has a serious fluid leak (2.7.3)
- Fail** Brake hydraulic reservoir leaking hydraulic fluid (3.6.A.1)
- Notice** Nail in nearside rear tyre
- Advice** Offside Front Tyre worn close to the legal limit (4.1.E.1)
- Fail** Offside Rear Shock absorber has negligible damping effect (2.7.5)
- Fail** Brake hydraulic reservoir fluid level below minimum level (3.6.G.1b)
- Advice** Nearside Front Tyre worn close to the legal limit (4.1.E.1)


**MOT #3** 2011-09-28 12:55**MOT test number** 918261071261**Result** ✓ Passed**Notice** O/s/r child seat fitted not allowing full inspection of adult belt**Notice** Nail in nearside rear tyre**MOT #2** 2011-01-10 16:01**MOT test number** 147910111032**Result** ✓ Passed**MOT #1** 2011-01-10 16:01**MOT test number** 149990111070**Result** ✗ Failed**Pass with rectification** Windscreen wiper does not clear the windscreen effectively (8.2.2)



Damage history

Check the damage history for this MAZDA. See if, where and when this MAZDA had damage and the car repair costs. We also check if this MAZDA was scrapped. Download the premium report [here](#) for the results.

Damage 1	
Date	
Category	
Type	
Damage 2	
Date	
Category	
Type	



Extra MAZDA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MAZDA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MAZDA? How many owners did this MAZDA have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MAZDA had different number plates.

Number of plates	1
Current registration	
Plate since	2019-03-28
Current registration	
Plate since	2019-03-28

More info >



Finance check

Check if this MAZDA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MAZDA has been settled.

If not, and you buy this MAZDA then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MAZDA is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	17
First mileage registration	2007-11-01
Last registration	2021-01-06
Complete history	See info



Registration #1	2007-11-01	7 mi
Registration #2	2011-01-10	17.219 mi
Registration #3	2011-09-28	27.933 mi
Registration #4	2012-10-04	38.969 mi
Registration #5	2012-10-12	38.969 mi
Registration #6	2013-12-20	54.856 mi
Registration #7	2013-12-21	54.891 mi
Registration #8	2015-01-03	69.557 mi
Registration #9	2016-01-05	79.962 mi
Registration #10	2016-01-05	79.962 mi
Registration #11	2016-01-05	79.962 mi
Registration #12	2016-01-05	79.962 mi
Registration #13	2016-01-05	79.962 mi
Registration #14	2016-01-05	79.962 mi
Registration #15	2016-01-05	79.962 mi
Registration #16	2016-01-05	79.962 mi
Registration #17	2016-01-05	79.962 mi

More info >



Safety ratings

NCAP rating	★★★★★
Video	see crash video



Dimensions & weight

Width	1755 mm
Height	1665 mm
Length	4420 mm
Wheel base	2750 mm
Kerb weight	1400 kg
Max. allowed weight	2100 kg

Additional information

Fuel tank capacity	60 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	7
Number of axles	2
Engine number	LF 10374822