



report date: 2024-03-29

General information

Make	MINI
Model	COOPER SD COOPER
Colour	Black
Year of manufacture	2012
Top speed	119 mph
0 - 60 mph	11.1 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	120 BHP
Max. torque	160 Nm at 4.250 rpm
Engine capacity	1.995 cc
Cylinders	4
Fuel type	Diesel
Consumption city	30.4 mpg
Consumption extra urban	54.3 mpg
Consumption combined	42.2 mpg
CO2 emission	114 g/km
CO2 label	C





Internet history

Entry 1

Date	2021-02-02
Pictures	10
Listing price	View report



source: [autoonline.co.uk](#)



MOT history

MOT expiry date	2024-06-30
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	8
Total items failed	2

MOT #11 2023-06-29 10:15

MOT test number 791389003040

Result ✓ Passed

Next expiry date 2024-06-30

Advice Rear Inner Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Offside Rear Tyre worn close to legal limit/worn on edge (5.2.3 (e))

Minor Offside Stop lamp(s) with a multiple light source up to 1/2 not functioning (4.3.1 (a) (i))

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))

Advice Offside Rear Tyre slightly damaged/cracking or perishing (5.2.3 (d) (ii))

MOT #10 2022-07-01 11:06

MOT test number 676650654085

Result ✓ Passed

MOT #9 2021-05-13 06:31

MOT test number 401325062924

Result ✓ Passed

**MOT #8** 2020-11-03 15:21**MOT test number** 850581713628**Result** ✓ Passed**Minor** Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))**Advice** Front Registration plate deteriorated but not likely to be misread (0.1 (b))**MOT #7** 2019-06-06 12:26**MOT test number** 324700258470**Result** ✓ Passed**MOT #6** 2019-06-06 08:42**MOT test number** 755692352824**Result** ✗ Failed**Fail** Offside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**MOT #5** 2018-06-08 10:49**MOT test number** 866603068380**Result** ✓ Passed**MOT #4** 2018-06-02 15:53**MOT test number** 316453732217**Result** ✗ Failed**Fail** Offside Front Tyre has a bulge, caused by separation or partial failure of its structure (5.2.3 (d) (i))**Advice** Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))**MOT #3** 2017-05-04 12:00**MOT test number** 810270797030**Result** ✓ Passed



MOT #2	2016-05-23 08:47
MOT test number	622817116705
Result	✓ Passed
MOT #1	2015-05-12 09:38
MOT test number	909332135128
Result	✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 May 2025

✓
MOT
Expires:
30 June 2024

Tax status	Valid until 1 May
Days left	366
MOT expiry date	30 June 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this MINI. See if, where and when this MINI had damage and the car repair costs. We also check if this MINI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra MINI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this MINI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this MINI? How many owners did this MINI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date
Owner	Start date

More info >

Plate changes

See in this check if this MINI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this MINI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this MINI has been settled.

If not, and you buy this MINI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this MINI is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-05-30
Last registration	2023-06-29
Complete history	See info



Registration #1	2012-05-30	7 mi
Registration #2	2015-05-12	30.013 mi
Registration #3	2016-05-23	41.198 mi
Registration #4	2017-05-04	48.574 mi
Registration #5	2018-06-02	55.981 mi
Registration #6	2018-06-08	56.111 mi
Registration #7	2019-06-06	64.563 mi
Registration #8	2019-06-06	64.563 mi
Registration #9	2019-06-06	64.563 mi
Registration #10	2019-06-06	64.563 mi
Registration #11	2019-06-06	64.563 mi
Registration #12	2019-06-06	64.563 mi
Registration #13	2019-06-06	64.563 mi

More info >



Car features

The MINI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete MINI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1683 mm
Height	1414 mm
Length	3699 mm
Wheel base	2467 mm
Kerb weight	1205 kg
Max. allowed weight	1635 kg

Additional information

Fuel tank capacity	40 l
Fuel delivery	Multi-Point Injection
Number of doors	2

Number of seats 4

Engine number	A430I532
---------------	----------