





report date: 2024-03-29

General information

Make	ТОУОТА
Model	RAV4 VVTI VX
Colour	Black
Year of manufacture	2002
Top speed	105 mph
0 - 60 mph	11.6 seconds
Gearbox	4 speed automatic

Engine & fuel consumption

Power	126 BHP
Max. torque	177 Nm at 4.400 rpm
Engine capacity	1.998 сс
Cylinders	4
Fuel type	Petrol
Consumption city	22.4 mpg
Consumption extra urban	34.9 mpg
Consumption combined	28.8 mpg
CO2 emission	224 g/km
CO2 label	K



CarCheck.co.uk page 1/14



MOT history

MOT expiry date	2021-01-05
MOT pass rate	74 %
MOT passed	17
Failed MOT tests	6
Total advice items	37
Total items failed	8

MOT #23		2020-01-06 10:05
MOT test	number	821975116950
Result		✓ Passed
Next exp	ry date	2021-01-05
Advice	Oil leak, but not excessive engine (8.4.1 (a) (i))	
Advice	Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))	
Advice	Steering rack mounting bushes slightly worn	
Minor	Nearside Headlamp lens slightly defective (4.1.1 (b) (i))	
Advice	Oil leak, but not excessive front diff (8.4.1 (a) (i))	
Advice	Headlight images have no kick up	
Advice	Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i))	
Advice	Rear tyres perished in tread	
Advice	Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii))	
Minor	Offside Headlamp lens slightly defective (4.1.1 (b) (i))	

CarCheck.co.uk page 2/14



MOT #22 2020-01-04 10:11

MOT test number 864024378141

Result **★** Failed **Advice** Rear tyres perished in tread Advice Oil leak, but not excessive engine (8.4.1 (a) (i)) Advice Nearside Rear Seat belt webbing slightly damaged or frayed (7.1.2 (b) (ii)) Minor Nearside Headlamp lens slightly defective (4.1.1 (b) (i)) Advice Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i)) Nearside Parking brake inoperative on one side (1.4.1 (a)) **MAJOR** Advice Steering rack mounting bushes slightly worn **Advice** Oil leak, but not excessive front diff (8.4.1 (a) (i)) Minor Offside Headlamp lens slightly defective (4.1.1 (b) (i)) Advice Rear Anti-roll bar corroded but not seriously weakened (5.3.3 (b) (i)) Advice Headlight images have no kick up

CarCheck.co.uk page 3/14



MOT #21 2018-12-10 11:52 **MOT** test number 584534394641 Result ✓ Passed **Advice** Offside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i)) Central Stop lamp(s) non-obligatory stop lamp not working (4.3.1 (a) (ii)) Advice Advice Unable to see rear brake pads Advice Nearside Rear Suspension arm corroded but not seriously weakened (5.3.3 (b) (i)) Advice Oil leak, but not excessive (8.4.1 (a) (i)) Advice Items removed from driver's view prior to test Advice Offside Rear tyre perished in tread Advice Nearside Rear Brake hose has slight corrosion to ferrule (1.1.12 (f) (i))

MOT #20	2018-01-03 18:20
MOT test number	410977871936
Result	✓ Passed
MOT #19	2018-01-02 11:19
MOT test number	814635136076
Result	× Failed
Negraida Dany Broke pine everesiyahy samadad (2.6.B.2a)	

Fail Nearside Rear Brake pipe excessively corroded (3.6.B.2c)	
MOT #18	2017-07-31 08:26
MOT test number	858638641405
Result	✓ Passed
MOT #17	2016-07-25 14:49
MOT test number	837954707091
Result	✓ Passed

CarCheck.co.uk page 4/14



MOT #16 2015-07-15 08:47 **MOT test number** 649926795180 Result ✓ Passed 2015-07-14 15:20 MOT #15 246585395193 **MOT** test number × Failed Result **Pass with rectification** Nearside Headlamp aim too far to the left (1.8) Pass with rectification Nearside Headlamp aim too high (1.8) Fail Offside Parking brake operation grabbing severely (3.7.C.3b)

MOT #14	2014-12-02 08:31
MOT test number	426296234376
Result	✓ Passed
MOT #13	2013-12-11 08:47
MOT test number	808515943364
Result	✓ Passed
MOT #12	2012-11-29 09:04
MOT test number	436084232404
Result	✓ Passed
MOT #11	2011-12-20 08:54
MOT test number	668144251357

Result Passed

CarCheck.co.uk page 5/14



MOT #10 2010-12-06 16:34

MOT test number 183430740329

Advice Offside Front Seat belt damaged but webbing not significantly weakened (5.2.2a)

MOT #9 2010-11-16 12:30

MOT test number 283320620336

Result \(\sqrt{Passed} \)

Advice Offside Front Seat belt stitching slightly frayed (5.2.2b)

MOT #8 2010-03-11 13:09

MOT test number 900970670084

Result Passed

Notice Ns/os front tyres perished

MOT #7 2010-03-11 12:52

MOT test number 743790670032

Result X Failed

Notice Ns/os front tyres perished

Fail Nearside Rear Registration plate lamp not working (1.1.C.1d)

Fail Nearside Rear Stop lamp not working (1.2.1b)

MOT #6 2008-09-26 09:34

MOT test number 122210578271

Result ✓ Passed

MOT #5 2007-09-26 12:15

MOT test number 340649367251

Result ✓ Passed

CarCheck.co.uk page 6/14



MOT #4 2006-09-20 09:28

MOT test number 354673766245

Result ✓ Passed

MOT #3 2006-09-11 16:13

MOT test number 944154656228

Result X Failed

Fail Offside Front Seat belt damaged sufficient to obstruct correct operation of the belt (5.2.2a)

MOT #2 2005-09-28 09:46

MOT test number 300901875463

Result
✓ Passed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

MOT #1 2005-09-28 09:46

MOT test number 282991975204

Result × Failed

Advice Offside Front Tyre worn close to the legal limit (4.1.E.1)

Pass with rectification Front Windscreen washer provides insufficient washer liquid (8.2.3)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

CarCheck.co.uk page 7/14





Tax & MOT check



Tax expired: 31 December 2020

X MOT

Expired: 5 January 2021

Tax status	Expired at 31 December 2020
Days left	1215 days too late
MOT expiry date	5 January 2021
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
venicle class	70
Band	K
Single payment (12 months)	£ 395,00,-
Single six month payment	£ 217,25,-
Total payable by 12 monthly instalments	£ 414,75,-

CarCheck.co.uk page 8/14



Damage history

Check the damage history for this TOYOTA. See if, where and when this TOYOTA had damage and the car repair costs. We also check if this TOYOTA was scrapped. Download the premium report <u>here</u> for the results.

Damage 1	
Date	
Category	
Туре	
Damage 2	
Date	
Category	
Туре	



Extra TOYOTA salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this TOYOTA in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner	history
OWITCH	IIIJCOI y

For how long did the current and previous owner(s) have this TOYOTA? How many owner have? Check it in the premium report and see all owner registrations. Download the full r		١
mave: Check it in the premium report and see an owner registrations. Download the full r	eport <u>nere</u> .	

	More info >	
Plate changes		
See in this check if this TOYOTA had different number plates.		
Number of plates		
Current registration	UK UK	
Plate since		
Current registration	NK NK	
Reference to the second	UK C	
	More info >	

CarCheck.co.uk page 11/14



Finance check

Check if this TOYOTA is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this TOYOTA has been settled.

If not, and you buy this TOYOTA then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this TOYOTA is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact into

More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	23
First mileage registration	2002-01-31
Last registration	2020-01-06
Complete history	See info



Registration #1	2002-01-31	14 mi
Registration #2	2005-09-28	38.004 mi
Registration #3	2006-09-11	47.872 mi
Registration #4	2006-09-20	25.903 mi
Registration #5	2007-09-26	56.711 mi
Registration #6	2008-09-26	65.399 mi
Registration #7	2010-03-11	79.948 mi
Registration #8	2010-03-11	79.948 mi
Registration #9	2010-11-16	87.180 mi
Registration #10	2010-12-06	87.184 mi
Registration #11	2011-12-20	90.951 mi
Registration #12	2012-11-29	93.133 mi
Registration #13		11.777 es
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		D.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es
Registration #23		

More info >

CarCheck.co.uk page 13/14



Car features

S0225	Air conditioning
S0295	
50482	
60501	
60566	
60567	
50569	

Safety ratings

NCAP rating	***
Video	see crash video



Dimensions & weight

Width	1760 mm
Height	1660 mm
Length	4115 mm
Kerb weight	1150 kg

Additional information

Fuel tank capacity	58 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of axles	2
Engine number	1AZ4326115

CarCheck.co.uk page 14/14