



report date: 2024-03-29

General information

Make	CITROEN
Model	RELAY 35 L3H2 120 LWB HR PV
Colour	White
Year of manufacture	2008
Gearbox	6 speed Manual

Engine & fuel consumption

Power	120 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	2.198 cc
Cylinders	4
Fuel type	Diesel



LABEL UNKNOWN



Internet history

Entry 1

Date	2022-05-08
Pictures	0
Listing price	<a href="#">View report</a>

source: cargurus.co.uk



## MOT history

MOT expiry date	2024-10-30
MOT pass rate	70 %
MOT passed	7
Failed MOT tests	3
Total advice items	15
Total items failed	4

MOT #10 2023-10-12 12:42

MOT test number 894894287948

Result ✓ Passed

Next expiry date 2024-10-30

**Advice** General underbody corrosion

**Advice** Headlamp has a product on the lens but not seriously reducing light output Both (4.1.4 (b))

**Advice** Exhaust system corroded

MOT #9 2022-10-31 15:27

MOT test number 781505176772

Result ✓ Passed

MOT #8 2016-03-07 17:31

MOT test number 386246402133

Result ✓ Passed

**Advice** Both front tyres slightly cracked no cord showing

**Advice** Offside Front Seat belt stitching slightly frayed (5.2.2b)

**Advice** Exhaust system badly corroded but no leaks

**Advice** Both rear lamps slight moisture inside units

**MOT #7** 2015-02-17 09:26**MOT test number** 847728645036**Result** ✓ Passed**Advice** Offside Front Seat belt damaged but webbing not significantly weakened (5.2.2a)**Advice** Offside Rear position lamp(s) slightly affected by the operation of another lamp (1.1.A.3f)**MOT #6** 2015-02-12 10:10**MOT test number** 175383045480**Result** ✗ Failed**Advice** Offside Rear position lamp(s) slightly affected by the operation of another lamp (1.1.A.3f)**Fail** Offside Registration plate lamp not working (1.1.C.1d)**Advice** Offside Front Seat belt damaged but webbing not significantly weakened (5.2.2a)**Fail** Nearside Registration plate lamp not working (1.1.C.1d)**MOT #5** 2013-11-05 09:38**MOT test number** 979319003339**Result** ✓ Passed**Advice** Nearside Rear position lamp(s) damaged, but still visible from a reasonable distance (1.1.A.3d)**Advice** Nearside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**Advice** Offside Front Seat belt stitching slightly frayed (5.2.2b)**Advice** Offside Front Lower Suspension arm rubber bush deteriorated but not resulting in excessive movement (2.4.G.2)**MOT #4** 2012-11-27 14:48**MOT test number** 499582932478**Result** ✓ Passed



MOT #3	2012-11-13 12:28
MOT test number	458728712406
Result	✗ Failed
Fail	Offside Rear Leaf spring has excessive wear in an anchor pin and/or bush (2.4.B.2)

MOT #2	2011-11-22 13:09
MOT test number	187516721396
Result	✓ Passed

MOT #1	2011-11-21 16:16
MOT test number	369555121337
Result	✗ Failed
Fail	Nearside Leaf spring has excessive wear in an anchor pin and/or bush (2.4.B.2)



Tax & MOT check

✓  
**Taxed**  
**Tax due:**  
1 April 2025

✓  
**MOT**  
**Expires:**  
30 October 2024

Tax status		Valid until 1 April
Days left		336
MOT expiry date		30 October 2024
Full MOT history		<a href="#">See MOT history</a>



Damage history

Check the damage history for this CITROEN. See if, where and when this CITROEN had damage and the car repair costs. We also check if this CITROEN was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra CITROEN salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this CITROEN in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 15,000
Auction value	£ 15,000
Average private trade value	£ 15,000

More info >





Owner history

For how long did the current and previous owner(s) have this CITROEN? How many owners did this CITROEN have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration
Owner	Registration

More info >

Plate changes

See in this check if this CITROEN had different number plates.

Number of plates	1
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29
Current registration	<b>XXXXXX</b>
Plate since	2024-03-29

More info >



Finance check

Check if this CITROEN is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this CITROEN has been settled.

If not, and you buy this CITROEN then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this CITROEN is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	12
First mileage registration	2008-12-11
Last registration	2023-10-12
Complete history	<a href="#">See info</a>



Registration #1	2008-12-11	28 mi
Registration #2	2011-11-21	31.391 mi
Registration #3	2011-11-22	31.391 mi
Registration #4	2012-11-13	39.765 mi
Registration #5	2012-11-27	39.998 mi
Registration #6	2013-11-05	46.106 mi
Registration #7	2014-11-05	52.217 mi
Registration #8	2015-11-05	58.328 mi
Registration #9	2016-11-05	64.439 mi
Registration #10	2017-11-05	70.550 mi
Registration #11	2018-11-05	76.661 mi
Registration #12	2019-11-05	82.772 mi

More info >



Safety ratings

NCAP rating	★★★★☆
Video	<a href="#">see crash video</a>



Dimensions & weight

Width	2508 mm
Height	1932 mm
Length	5413 mm
Kerb weight	1975 kg

Additional information

Fuel tank capacity	90 l
Fuel delivery	Direct Injection
Number of doors	4
Number of seats	3
Engine number	TRJ20232357