





report date: 2024-03-28

General information

Make	FORD
Model	S-MAX TITANIUM TDCI
Colour	Silver
Year of manufacture	2012
Top speed	124 mph
0 - 100 km/h	11.1 seconds
0 - 60 mph	10.4 seconds
Gearbox	6 speed automatic

Engine & fuel consumption

Power	103 kW / 140 HP / 161 BHP
Max. torque	320 Nm at 2.000 rpm
Engine capacity	1.997 сс
Cylinders	4
Fuel type	Diesel
Consumption city	38.2 mpg
Consumption extra urban	54.3 mpg
Consumption combined	47.1 mpg
CO2 emission	159 g/km
CO2 label	G



CarCheck.co.uk page 1/12



EO62LGY report date: 2024-03-28

Internet history

Entry 1

Date	2021-01-31
Pictures	1
Listing price	View report



source: autoonline.co.uk

CarCheck.co.uk page 2/12



report date: 2024-03-28

MOT history

MOT expiry date	2024-12-14
MOT pass rate	82 %
MOT passed	9
Failed MOT tests	2
Total advice items	17
Total items failed	3

MOT #11		2023-12-15 10:51
MOT test	number	604150869775
Result		✓ Passed
Next expi	ry date	2024-12-14
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))		ii))
Advice	Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))	

MOT #10	2023-12-12 16:11	
MOT test number	711765747117	
Result	X Failed	
Fail Offside Front Outer Drive shaft joint constant velocity boot split or insecure, no longer prevents the ingress of dirt (6.1.7 (g) (ii))		
Advice Front Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a)	(ii))	
Advice Nearside Rear Anti-roll bar ball joint has slight play (5.3.4 (a) (i))		

MOT #9		2022-12-12 10:26
MOT test	number	836383586561
Result		✓ Passed
Advice	Offside Rear Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice	Offside Rear Tyre has a cut but not deep enough to reach the ply or cords (5.2.3 (d) (i))
Advice	Rear exhaust heat shield loose	

CarCheck.co.uk page 3/12



report date: 2024-03-28

2021-12-14 10:27 **MOT #8** 346384763992 **MOT test number** Result ✓ Passed **Minor** Front Lower Windscreen damaged but not adversely affecting driver's view (3.2 (a) (i)) Offside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i)) Minor **Advice** Offside Front Inner Tyre worn close to legal limit/worn on edge (5.2.3 (e)) Minor Nearside Rear Position lamp with a multiple light source up to 1/2 not functioning (4.2.1 (a) (i)) Minor Nearside Rear Registration plate lamp inoperative in the case of multiple lamps or light sources (4.7.1 (b) (i))

MOT #7	2020-12-15 16:39
MOT test number	976792911038
Result	✓ Passed
MOT #6	2020-02-03 10:48
MOT test number	308022217076
Result	✓ Passed
MOT #5	2019-01-18 11:02
MOT test number	759138008517
Result	✓ Passed
Advice Nearside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	
Advice Offside Front Tyre worn close to legal limit/worn on edge (5.2.3 (e))	

MOT #4	2017-08-24 15:33
MOT test number	647015062142
Result	✓ Passed
Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)	

CarCheck.co.uk page 4/12



EO62LGY report date: 2024-03-28

MOT #3 2017-08-24 14:09

MOT test number 426157820555

Result × Failed

Fail Nearside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

Advice Nearside Front Tyre worn close to the legal limit (4.1.E.1)

Fail Offside Rear Tyre tread depth below requirements of 1.6mm (4.1.E.1)

MOT #2 2016-09-02 15:31

MOT test number 947730660583

Advice Child Seat fitted not allowing full inspection of adult belt

MOT #1 2015-09-04 12:09

MOT test number 678903500129

CarCheck.co.uk page 5/12



report date: 2024-03-28

Tax & MOT check



Tax status	Valid until 1 March
Days left	307
MOT expiry date	14 December 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	G
Single payment (12 months)	£ 240,00,-
Single six month payment	£ 132,00,-
Total payable by 12 monthly instalments	£ 252,00,-

CarCheck.co.uk page 6/12



report date: 2024-03-28

Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 7/12



report date: 2024-03-28

Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 8/12



report date: 2024-03-28

Owner history

e union matery	
For how long did the current and previous owner(s) have this FORD? How many owners of Check it in the premium report and see all owner registrations. Download the full report is	

	More info >
Plate changes	
See in this check if this FORD had different number plates.	
Number of plates	
Current registration	NK SIN
Plate since	
Current registration	NK SIX
Plate since	
	More info >

CarCheck.co.uk page 9/12



report date: 2024-03-28

Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this FORD is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

More info >


CarCheck.co.uk page 10/12



report date: 2024-03-28

Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2012-09-06
Last registration	2023-12-15
Complete history	See info



Registration #1	2012-09-06	10 mi
Registration #2	2015-09-04	26.885 mi
Registration #3	2016-09-02	33.888 mi
Registration #4	2017-08-24	49.880 mi
Registration #5	2017-08-24	49.896 mi
Registration #6	2019-01-18	68.231 mi
Registration #7	2020-02-03	85.357 mi
Registration #8		11.777 es
Registration #9		11.777 mi
Registration #10		0.00 44
Registration #11		11.777 mi
Registration #12		11.777 46
Registration #13		10.777 au

More info >

CarCheck.co.uk page 11/12



report date: 2024-03-28

Car features

50225	Air conditionin
50295	
60482	
60501	
0566	
60567	
60569	

Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	1884 mm
Height	1764 mm
Length	4820 mm
Wheel base	2850 mm
Kerb weight	1631 kg
Max. allowed weight	2505 kg

Additional information

Fuel tank capacity	70 I	
Fuel delivery	Direct Injection	
Number of doors	5	
Number of axles CarCheck.co.uk	2	page 12/12