





report date: 2024-03-29

General information

Make	JAGUAR
Model	X-TYPE V6 SE
Colour	Silver
Year of manufacture	-
Top speed	137 mph
0 - 60 mph	8.9 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	194 BHP
Max. torque	244 Nm at 3.000 rpm
Cylinders	6
Fuel type	Petrol
Consumption city	19.0 mpg
Consumption extra urban	37.2 mpg
Consumption combined	27.4 mpg



CarCheck.co.uk page 1/14



Internet history

Entry 2

Date 2021-12-24

Pictures 11

Listing price <u>View report</u>









source: cargurus.co.uk

Entry 1

Date	2021-12-23
Pictures	0
Listing price	View report

source: autotrader.co.uk

CarCheck.co.uk page 2/14



MOT history

MOT #22 2021-09-07 09:44

MOT test number 488746822911

Result ✓ Passed

Next expiry date 2022-09-06

Advice Offside Rear Brake pipe corroded, covered in grease or other material (1.1.11 (c))

Advice Brake disc worn, pitted or scored, but not seriously weakened all (1.1.14 (a) (ii))

Advice Slight corrosion on the sills, sills covers fitted

Minor Nearside Rear Brake hose slightly twisted (1.1.12 (b) (i))

MOT #21 2021-03-29 16:21

MOT test number 697355913495

Result \rightarrow Passed

Advice Front Brake pad(s) wearing thin (1.1.13 (a) (ii))

Advice Front brake discs deteriorated

MOT #20 2020-04-01 08:30

MOT test number 472685951869

Result \(\sqrt{Passed} \)

Advice Front Brake pad(s) wearing thin inner (1.1.13 (a) (ii))

Advice Front Registration plate deteriorated but not likely to be misread cracked (0.1 (b))

MOT #19 2020-03-31 15:04

MOT test number 578472459690

Result X Failed

Advice Front Registration plate deteriorated but not likely to be misread cracked (0.1 (b))

MAJOR Offside Headlamp aim too high (4.1.2 (a))

Advice Front Brake pad(s) wearing thin inner (1.1.13 (a) (ii))

CarCheck.co.uk page 3/14



GY54VVK

report date: 2024-03-29

MOT #18 2019-03-29 16:05

MOT test number 824087178832

Result ✓ Passed

MOT #17 2019-03-28 16:23

MOT test number 312307493954

Result X Failed

MAJOR Offside Headlamp aim too low (4.1.2 (a))

MAJOR Windscreen washer provides insufficient washer liquid (3.5 (a))

MAJOR Nearside Rear Direction indicator incorrect colour (4.4.3 (a))

MOT #16 2018-05-08 10:30

MOT test number 233444267935

Result ✓ Passed

MOT #15 2018-05-01 13:44

MOT test number 531977388498

Result X Failed

Fail Offside Front Brake hose twisted (found during steering lock to lock check) (2.2.D.2b)

Fail Offside Front Headlamp aim too low (1.8)

Fail Nearside Front Windscreen wiper does not clear the windscreen effectively (8.2.2)

MOT #14 2017-06-07 13:34

MOT test number 362921666904

Result ✓ Passed

CarCheck.co.uk page 4/14



MOT #13 2017-06-07 10:16

MOT test number 846579691786

Result X Failed

Fail Offside Front Front position lamp(s) not working (1.1.A.3b)

MOT #12 2016-06-21 08:49

MOT test number 723579675380

Result \(\sqrt{Passed} \)

Advice Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #11 2015-06-09 12:35

MOT test number 527360665170

Result

Passed

MOT #10 2014-06-19 10:59

MOT test number 488300774173

Result Passed

Advice Front Brake pad(s) wearing thin (3.5.1g)

Notice Wipers smearing screen

MOT #9 2013-06-18 16:10

MOT test number 265579663102

Result \(\sqrt{Passed} \)

Advice Front Windscreen has damage to an area less than a 10mm circle within zone 'A' (8.3.1a)

MOT #8 2012-06-21 10:09

MOT test number 577823572161

Result \(\sqrt{Passed} \)

CarCheck.co.uk page 5/14



Result

GY54VVK report date: 2024-03-29

✓ Passed

MOT test number

Result

Fail Offside Front Headlamp not working on dipped beam (1.7.5a)

Fail Nearside Front Front position lamp(s) not working (1.1.A.3b)

Notice Oil leak

MOT #6	2011-09-22 11:39
MOT test number	495295361226
Result	✓ Passed
MOT #5	2010-08-23 17:07
MOT test number	621745730249

CarCheck.co.uk page 6/14



GY54VVK

report date: 2024-03-29

MOT #4 2010-08-09 13:29

MOT test number 114041520228

Result X Failed

Advice Offside Rear Direction indicator slightly discoloured (1.4.A.2f)

Fail Nearside Stop lamp not working (1.2.1b)

Notice Offside rear lens broken

Fail Offside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Notice Offside rear tyre perished

Fail Front brake disc in such a condition that it is seriously weakened (3.5.1i)

Fail Offside Rear Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

Fail Windscreen has damage to an area in excess of a 10mm circle within zone 'A' (8.3.1a)

Advice Rear Brake pad(s) wearing thin (3.5.1g)

Fail Nearside Front Tyre has a cut in excess of the requirements deep enough to reach the ply or cords (4.1.D.1a)

Notice Nail in nearside rear tyre

Fail Front Brake pad(s) less than 1.5 mm thick (3.5.1g)

Fail Nearside Rear Lower Suspension arm rubber bush deteriorated resulting in excessive movement (2.4.G.2)

MOT #3 2009-05-20 09:33

MOT test number 421060649161

Result \(\sqrt{Passed} \)

Advice Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)

MOT #2 2008-10-17 10:39

MOT test number 334721698201

Result
✓ Passed

CarCheck.co.uk page 7/14



GY54VVK

report date: 2024-03-29

MOT #1

MOT test number

134876587274

Result

Notice All tyres nearing limit.

Notice Offside front tyre wearing on inner edge.

CarCheck.co.uk page 8/14



Damage history

Check the damage history for this JAGUAR. See if, where and when this JAGUAR had damage and the car repair costs. We also check if this JAGUAR was scrapped. Download the premium report <u>here</u> for the results.

Damage 1
Date
Category
Type
Damage 2
Date
Category
Type



Extra JAGUAR salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report <u>here</u> for more information.

More info >

CarCheck.co.uk page 9/14



Vehicle valuation

What is this car worth? See the vehicle value of this JAGUAR in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value

Auction value

Average private trade value

More info >

CarCheck.co.uk page 10/14



Owner history

For how long did the current and previous owner(s) have this JAGUAR? How many owners have? Check it in the premium report and see all owner registrations. Download the full respectively.		ΛR
manage of the same		

	More info	>
Plate changes		
See in this check if this JAGUAR had different number plates.		
Number of plates		9
Current registration	UK UK	
Plate since		
Current registration	UK THE	
Plate since		
	More info	>

CarCheck.co.uk page 11/14



Finance check

Check if this JAGUAR is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this JAGUAR has been settled.

If not, and you buy this JAGUAR then you could lose the money and the car you paid for.

Download the premium report <u>here</u> and check if this JAGUAR is financed.

Finance company	
Date of agreement	
Agreement type	
Agreement term	
Agreement number	
Contact info	

Contact info


More info >

CarCheck.co.uk page 12/14



Mileage check

Odometer	In miles
Mileage registrations	25
First mileage registration	2004-10-18
Last registration	2021-09-07
Complete history	See info



Registration #1	2004-10-18	8 mi
Registration #2	2007-10-13	15.254 mi
Registration #3	2008-10-17	20.281 mi
Registration #4	2009-05-20	23.955 mi
Registration #5	2010-08-09	41.320 mi
Registration #6	2010-08-23	41.320 mi
Registration #7	2011-09-22	53.270 mi
Registration #8	2012-06-08	60.935 mi
Registration #9	2012-06-21	60.695 mi
Registration #10	2013-06-18	68.584 mi
Registration #11	2014-06-19	76.488 mi
Registration #12	2015-06-09	83.614 mi
Registration #13	2016-06-21	91.079 mi
Registration #14		11.777 es
Registration #15		11.777 es
Registration #16		11.777 es
Registration #17		11.777 es
Registration #18		11.777 es
Registration #19		11.777 es
Registration #20		11.777 es
Registration #21		11.777 es
Registration #22		11.777 es
Registration #23		11.777 es
Registration #24		11.777 es
Registration #25		11.777 es



Safety ratings

NCAP rating	****
Video	see crash video



Dimensions & weight

Width	2003 mm
Height	1392 mm
Length	4672 mm
Wheel base	2710 mm
Kerb weight	1595 kg
Max. allowed weight	2100 kg

Additional information

Fuel tank capacity	61
Fuel delivery	Multi-Point Injection
Number of doors	4
Number of seats	5
Number of axles	2
Engine number	406900412XB

CarCheck.co.uk page 14/14