



report date: 2024-03-29

General information

Make	FORD
Model	FUSION ZETEC CLIMATE
Colour	Orange
Year of manufacture	2008
Top speed	109 mph
0 - 60 mph	12.7 seconds
Gearbox	5 speed automatic

Engine & fuel consumption

Power	100 BHP
Max. torque	145 Nm at 4.000 rpm
Engine capacity	1.596 cc
Cylinders	4
Fuel type	Petrol
Consumption city	27.4 mpg
Consumption extra urban	46.3 mpg
Consumption combined	37.2 mpg
CO2 emission	181 g/km
CO2 label	I





Internet history

Entry 2

Date	2022-10-28
Pictures	28
Listing price	View report



source: cargurus.co.uk

Entry 1

Date	2022-07-08
Pictures	12
Listing price	View report



source: cargurus.co.uk



MOT history

MOT expiry date	2025-01-09
MOT pass rate	85 %
MOT passed	11
Failed MOT tests	2
Total advice items	10
Total items failed	4

MOT #13

2024-01-10 14:33

MOT test number

224442605191

Result

✓ Passed

Next expiry date

2025-01-09

Advice

Rear tyres cracking

MOT #12

2022-12-28 15:14

MOT test number

455966022502

Result

✓ Passed

MOT #11

2022-06-20 12:58

MOT test number

511763457391

Result

✓ Passed

MOT #10

2018-08-22 09:54

MOT test number

841887369134

Result

✓ Passed

Advice

Central Rear stop light not working

Advice

Nearside Front mirror housing cover damaged

**MOT #9** 2017-08-14 15:43**MOT test number** 108787425969**Result** ✓ Passed**MOT #8** 2016-08-23 15:13**MOT test number** 929618545476**Result** ✓ Passed**MOT #7** 2015-04-10 11:09**MOT test number** 717950005125**Result** ✓ Passed**Notice** N/s/f tyre 2mm**Notice** High level brake light not working**Notice** O/s/f tyre cracking**MOT #6** 2014-04-14 12:07**MOT test number** 105804404127**Result** ✓ Passed**Notice** O/s/f tyre cracking**MOT #5** 2014-04-14 12:07**MOT test number** 268894604427**Result** ✗ Failed**Notice** O/s/f tyre cracking**Pass with rectification** Offside Rear position lamp(s) not working (1.1.A.3b)**Pass with rectification** Offside Stop lamp not working (1.2.1b)



MOT #4 2013-04-04 10:57

MOT test number 546644893007

Result ✓ Passed

MOT #3 2012-03-27 15:45

MOT test number 196547082013

Result ✓ Passed

Notice Nearside rear tyre worn close to wear indicators

MOT #2 2012-03-27 15:45

MOT test number 536957282047

Result ✗ Failed

Pass with rectification Offside Rear position lamp(s) adversely affected by the operation of another lamp (1.1.A.3f)

Notice Nearside rear tyre worn close to wear indicators

Pass with rectification Nearside Rear Stop lamp not working (1.2.1b)

MOT #1 2011-04-04 11:37

MOT test number 956274691003

Result ✓ Passed



Tax & MOT check

✓
Taxed
Tax due:
1 April 2025

✓
MOT
Expires:
9 January 2025

Tax status	Valid until 1 April
Days left	337
MOT expiry date	9 January 2025
Full MOT history	See MOT history

Tax calculation

Vehicle class	48
Band	I
Single payment (12 months)	£ 320,00,-
Single six month payment	£ 176,00,-
Total payable by 12 monthly instalments	£ 336,00,-



Damage history

Check the damage history for this FORD. See if, where and when this FORD had damage and the car repair costs. We also check if this FORD was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra FORD salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this FORD in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this FORD? How many owners did this FORD have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****
*****	*****

More info >

Plate changes

See in this check if this FORD had different number plates.

Number of plates	1
Current registration	*****
Plate since	2019-09-29
Current registration	*****
Plate since	2019-09-29

More info >



Finance check

Check if this FORD is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this FORD has been settled.

If not, and you buy this FORD then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this FORD is financed.

Finance company	XXXXXXXXXX	XXXX
Date of agreement	XXXXXXXXXX	XXXX
Agreement type	XXXXXXXXXX	XXXX
Agreement term	XXXXXXXXXX	XXXX
Agreement number	XXXXXXXXXX	XXXX
Contact info	XXXXXXXXXX	XXXX

More info >



Mileage check

Odometer	In miles
Mileage registrations	13
First mileage registration	2008-03-25
Last registration	2024-01-10
Complete history	See info



Registration #1	2008-03-25	25 mi
Registration #2	2011-04-04	9.113 mi
Registration #3	2012-03-27	10.903 mi
Registration #4	2013-04-04	12.555 mi
Registration #5	2014-04-14	14.491 mi
Registration #6	2015-04-10	15.583 mi
Registration #7	2016-08-23	16.662 mi
Registration #8	2017-05-20	18.277 mi
Registration #9	2018-05-20	19.277 mi
Registration #10	2019-05-20	20.277 mi
Registration #11	2020-05-20	21.277 mi
Registration #12	2021-05-20	22.277 mi
Registration #13	2022-05-20	23.277 mi

More info >



Car features

The FORD factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete FORD factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★☆

Video [see crash video](#)



Dimensions & weight

Width	1963 mm
Height	1543 mm
Length	4013 mm
Wheel base	2485 mm
Kerb weight	1110 kg
Max. allowed weight	1630 kg

Additional information

Fuel tank capacity	45 l
Fuel delivery	Multi-Point Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	8L44829