



report date: 2024-03-29

General information

Make	AUDI
Model	A3 TDI E SPORT
Colour	Black
Year of manufacture	2009
Top speed	120 mph
Gearbox	5 speed Manual

Engine & fuel consumption

Power	104 BHP
Max. torque	250 Nm at 1.900 rpm
Engine capacity	1.896 cc
Cylinders	4
Fuel type	Diesel
Consumption city	48.7 mpg
Consumption extra urban	74.3 mpg
Consumption combined	62.8 mpg
CO2 emission	119 g/km
CO2 label	C





MOT history

MOT expiry date	2024-09-04
MOT pass rate	67 %
MOT passed	12
Failed MOT tests	6
Total advice items	25
Total items failed	11

MOT #18 2023-09-05 19:16

MOT test number 709382225509

Result ✓ Passed

Next expiry date 2024-09-04

Advice Rear Brake disc worn, pitted or scored, but not seriously weakened (1.1.14 (a) (ii))**Minor** Offside Rear Position lamp has a product on the lens or light source which changes the emitted colour indicator (4.2.3 (b) (i))

MOT #17 2022-06-29 09:31

MOT test number 293565113177

Result ✓ Passed**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))

MOT #16 2022-06-29 09:31

MOT test number 569264470645

Result ✗ Failed**Advice** Nearside Front Anti-roll bar linkage ball joint has slight play (5.3.4 (a) (i))**Pass with rectification** Nearside Headlamp aim too low (4.1.2 (a))**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Pass with rectification** Offside Headlamp aim too high (4.1.2 (a))

**MOT #15** 2021-07-05 11:23**MOT test number** 782463900548**Result** ✓ Passed**Advice** Central Front Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #14** 2021-07-03 08:40**MOT test number** 104913010845**Result** ✗ Failed**Fail** Nearside Front Shock absorbers has a serious fluid leak (5.3.2 (b))**Advice** Central Front Oil leak, but not excessive (8.4.1 (a) (i))**Advice** Offside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Fail** Supplementary restraint system warning lamp indicates a fault (7.1.6 (a))**MOT #13** 2020-07-06 13:08**MOT test number** 321466520160**Result** ✓ Passed**MOT #12** 2019-07-31 11:28**MOT test number** 415859601294**Result** ✓ Passed**Advice** Nearside Front Brake disc worn, but not excessively (1.1.14 (a) (i))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**Advice** Offside Front Brake disc worn, but not excessively (1.1.14 (a) (i))

**MOT #11** 2019-07-31 09:25**MOT test number** 905806007137**Result** ✗ Failed**Fail** Offside Front Brake pad(s) less than 1.5 mm thick (1.1.13 (a) (ii))**Advice** Nearside Front Shock absorbers light misting of oil or has limited damping effect (5.3.2 (b))**MOT #10** 2018-07-29 09:12**MOT test number** 198583039844**Result** ✓ Passed**Advice** Offside Rear Direction indicator slightly discoloured (4.4.3 (a))**Advice** Nearside Rear Tyre worn close to legal limit/worn on edge Inner Shoulder (5.2.3 (e))**MOT #9** 2017-08-14 11:55**MOT test number** 865159693899**Result** ✓ Passed**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)**MOT #8** 2017-08-14 10:29**MOT test number** 684714345655**Result** ✗ Failed**Fail** Offside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Nearside Rear Brake pad(s) less than 1.5 mm thick (3.5.1g)**Fail** Offside Headlamp aim beam image obviously incorrect (1.8.A.1b)**Advice** Offside Front Shock absorber has a light misting of oil (2.7.3)

**MOT #7** 2016-08-29 10:56**MOT test number** 969962886867**Result** ✓ Passed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Rear Brake pad(s) wearing thin both side (3.5.1g)**MOT #6** 2016-08-29 10:07**MOT test number** 207617443495**Result** ✗ Failed**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Fail** Front Tyre tread depth below requirements of 1.6mm both side (4.1.E.1)**Advice** Rear Brake pad(s) wearing thin both side (3.5.1g)**Fail** Nearside Rear Registration plate lamp not working (1.1.C.1d)**MOT #5** 2015-08-19 08:04**MOT test number** 281683411813**Result** ✓ Passed**MOT #4** 2014-08-24 11:29**MOT test number** 366836134268**Result** ✓ Passed**MOT #3** 2013-08-19 12:06**MOT test number** 898201333274**Result** ✓ Passed**Notice** Child seat fitted not allowing full inspection of adult belt**Advice** Nearside Front Shock absorber has a light misting of oil (2.7.3)**Advice** Rear Brake pad(s) wearing thin (3.5.1g)



MOT #2	2012-08-16 13:46
MOT test number	539639622252
Result	✓ Passed

MOT #1	2012-08-06 12:35
MOT test number	939939912246
Result	✗ Failed

Fail Offside Side repeater not working (1.4.A.2c)



Tax & MOT check

✓
Taxed
Tax due:
1 January 2025

✓
MOT
Expires:
4 September 2024

Tax status	Valid until 1 January
Days left	247
MOT expiry date	4 September 2024
Full MOT history	See MOT history

Tax calculation

Vehicle class	49
Band	C
Single payment (12 months)	£ 35,00,-
Single six month payment	Not applicable
Total payable by 12 monthly instalments	£ 36,75,-



Damage history

Check the damage history for this AUDI. See if, where and when this AUDI had damage and the car repair costs. We also check if this AUDI was scrapped. Download the premium report [here](#) for the results.

Damage 1

Date	
Category	
Type	

Damage 2

Date	
Category	
Type	



Extra AUDI salvage check



If this vehicle was seen at a salvage auction we offer: vehicle pictures, salvage location, retail value. Download the premium report [here](#) for more information.

More info >



Vehicle valuation

What is this car worth? See the vehicle value of this AUDI in the premium report. We check: purchase value, age, mileage, MOT history, damages and online sale prices.

Trade retail value	£ 19,999
Auction value	£ 19,999
Average private trade value	£ 19,999

More info >



Owner history

For how long did the current and previous owner(s) have this AUDI? How many owners did this AUDI have? Check it in the premium report and see all owner registrations. Download the full report [here](#).

Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since
Owner	Since

More info >

Plate changes

See in this check if this AUDI had different number plates.

Number of plates	1
Current registration	
Plate since	2024-03-29
Current registration	
Plate since	2024-03-29

More info >



Finance check

Check if this AUDI is financed, has an outstanding loan or finance agreement. If you are purchasing a vehicle it is smart to ensure that any finance that may have been taken out on this AUDI has been settled.

If not, and you buy this AUDI then you could lose the money and the car you paid for.

Download the premium report [here](#) and check if this AUDI is financed.

Finance company	REDACTED	REDACTED
Date of agreement	REDACTED	REDACTED
Agreement type	REDACTED	REDACTED
Agreement term	REDACTED	REDACTED
Agreement number	REDACTED	REDACTED
Contact info	REDACTED	REDACTED

More info >



Mileage check

Odometer	In miles
Mileage registrations	19
First mileage registration	2009-09-28
Last registration	2023-09-05
Complete history	See info



Registration #1	2009-09-28	27 mi
Registration #2	2012-08-06	42.161 mi
Registration #3	2012-08-16	42.845 mi
Registration #4	2013-08-19	59.710 mi
Registration #5	2014-08-24	70.767 mi
Registration #6	2015-08-19	78.459 mi
Registration #7	2016-08-29	86.749 mi
Registration #8	2016-08-29	86.749 mi
Registration #9	2017-08-14	93.766 mi
Registration #10	2017-08-14	93.766 mi
Registration #11	2018-08-29	100.783 mi
Registration #12	2019-08-29	107.800 mi
Registration #13	2020-08-29	114.817 mi
Registration #14	2021-08-29	121.834 mi
Registration #15	2022-08-29	128.851 mi
Registration #16	2023-08-29	135.868 mi
Registration #17	2023-08-29	135.868 mi
Registration #18	2023-08-29	135.868 mi
Registration #19	2023-08-29	135.868 mi

More info >



Car features

The AUDI factory car options list is only available in the premium report.

S0225	Air conditioning
S0295	
S0482	
S0501	
S0566	
S0567	
S0569	

View the complete AUDI factory list for this vehicle [here](#).

More info >

Safety ratings

NCAP rating ★★★★★

Video [see crash video](#)



Dimensions & weight

Width	1765 mm
Height	1423 mm
Length	4292 mm
Wheel base	2578 mm
Kerb weight	1320 kg
Max. allowed weight	1880 kg

Additional information

Fuel tank capacity	55 l
Fuel delivery	Direct Injection
Number of doors	5
Number of seats	5

Number of axles	2
Engine number	BLS B01113